



05-Oct-2019

PCN #:P-19-018039

Subject:MTA-100 Friction Lock Header Assembly

Description of Change: The following part numbers are currently single source manufactured at TE Qingdao, China. These parts will be dual source manufactured at TE Qingdao, China and TE Lickdale, USA in the future

Reason: Dear Customer, as a result of our continuous strive for improving our processes, we hereby inform you about an additional manufacturing location for the following parts.

Key Dates:

Contact By Date:16-Mar-2020

Implementation Date:16-Mar-2020

Product Affected

4-641215-3

2-640456-5

640456-5

3-641216-7

4-641215-5

3-641215-8

4-641215-6

3-641126-7

1744214-8

2-640456-2

3-641126-2

2-641215-0

1-641215-2

3-641216-8

3-641215-2

Product Affected

640457-5

640457-2

3-641127-3

640457-6

4-641215-8

5-641216-0

3-641216-5

2-640457-0

1-640456-6

3-641216-9

641126-9

641215-4

3-641215-4

4-641126-5

3-641215-7

640457-8

640456-2

(Alias Part Numbers:

"403612641"

"2-42934-0583")

640456-8

(Alias Part Numbers:

"403592280"

"2-42934-0585")

1-640457-5

1-640456-2

(Alias Part Numbers:

"2-42934-0581")

640457-7

1-640457-6

3-641216-4

4-641215-2

1-640457-4

640456-9

(Alias Part Numbers:

"405029927")

1-640457-3

3-641216-3

3-641126-4

4-641215-1

Product Affected

1-641215-6

(Alias Part Numbers:

"407225713")

1-640456-7

640456-4

(Alias Part Numbers:

"1220249")

1-640456-3

3-641126-8

1744214-6

2-640456-0

1-640456-4

3-641126-5

641126-4

4-641215-0

1-640457-2

1-640457-1

3-641126-6

4-641215-4

3-641126-9

4-641126-0

641126-5

641126-2

(Alias Part Numbers:

"651-1247-01")

641216-4

1-641215-0

641215-3

(Alias Part Numbers:

"406005140"

"651-1078-01")

3-641126-3

640457-4

(Alias Part Numbers:

"210-00157")

640456-3

(Alias Part Numbers:

"403726995")

1-640456-1

640456-6

Product Affected

(Alias Part Numbers:

"28-91108-06"

"2-42934-0582")

2-640456-4

1-640456-0

(Alias Part Numbers:

"2-42934-0587")

640457-9

3-641216-6

3-641215-9

2-640456-7

1-640456-9

4-641126-3

1-640456-8

(Alias Part Numbers:

"403709777")

1-641126-2

1-641215-8

641215-8

2-640457-3

1-640457-0

(Alias Part Numbers:

"403637424")

3-641216-2

1744265-1

640457-3

640456-7

3-641215-5

3-641127-4

3-641127-5

1-640456-5

(Alias Part Numbers:

"403592306")

4-641126-2

1744214-2

641126-3

(Alias Part Numbers:

"1166372")

641215-6

(Alias Part Numbers:

Product Affected

"651-1079-01")

641215-2

(Alias Part Numbers:

"405384330")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the

TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.