



TE Connectivity

Product Change Notification: P-17-014688 PCN Date: 28-JUL-17

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s)

General Product Description: AFFECTS CUSTOMERS IN NORTH AMERICA ONLY!! Dual sourcing of product

Description of Changes

TE Brazil added as second import source. This notification is only valid for customers in North America

Reason for Changes: Product improvement. As a result of our cont nuos strive for improving our delivery and meet our US cutomers capacity needs, we hereby inform you that TE US will introduce a second source for TE part numbers in this listing. Tke address of the second source is TE Connectivity Braganca, Ampere street 304 Braganca Paulista, \$ 0 Paulo 12929-570

Brazil, DUNS 908754679. ?Product meets all dimensions defined on the respective TE Customer drawings, performance criteria specified in TE Product and Application specifications. There is no change to fit, form or fuction of the product. There is no change to customer fixturing or application tooling. PPAP package will be sent for your review and approval prior to delivery of any product. Contact your local TE sales representative for support.

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):					
	15-SEP-2017					
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):					
	No Mixed Shipments					

Part Number(s) being Modified:

Don't November	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias Part	Description Of
Part Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Number(s)	Difference
282189-1	NO			'CF0543-000", "AMP-0- 0282189-1"			
<u>284703-1</u>	NO						
928999-1	NO			'0-0928999-1", "0-928999-1"			
964274-2	NO						
964324-1	NO						
964326-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alica Part Number(a)	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Number(s)	Difference
284703-1	NO						
928999-1	NO			'0-0928999-1", "0-928999-1"			
964274-2	NO						
964324-1	NO						

Part Number(s) being Modified:

 art mber	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference

Part	Part Discontinued	Customer	Customer Part	Alias Part Number(s)	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Alias Fait Nulliber(5)	Number	Number(s)	Difference
284703-1	NO						
928999-1	NO			'0-0928999-1", "0-928999-1"			
964274-2	NO						
964324-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282189-1	NO			"CF0543-000", "AMP-0- 0282189-1"			
928999-1	NO			"0-0928999-1", "0-928999-1"			
964326-1	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alica Dart Number(s)	Substitute Part	Substitute Alias Part	Description Of
Number	per PCN	Drawing	Number	Alias Part Number(s)	Number	Number(s)	Difference
282189-1	NO			"CF0543-000", "AMP-0- 0282189-1"			
928999-1	NO			"0-0928999-1", "0-928999-1"			
964326-1	NO						