



Product Change Notification

Current Date: 12-Dec-2019

TE Connectivity

Product Change Notification: P-19-018306

PCN Date: 09-DEC-19

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
AMP MCP2.8 CONTACT

Description of Changes
Dear customer, we hereby inform you about a new duplication production tool (11-1935189) in TE Suzhou plant for production , TE part number 1-968849-1 & 1-968851-1 & 1-968880-1,This die capability only cover Asia-Pacific market currently. EMEA customer do not need to change to China part only keep EMEA part
Other attachments:
Explanation for new duplication production tool for AMP MCP2.8 CONTACT

Reason for Changes:
Customer Request.Customer Request.customer request ,as a result of our continuous strive for capacity increase of our production, we hereby inform you upfront about a new tool 11-1935189, which are under construction in order to meet all specification requirements to cover increasing market demand and which will run in addition to current one.
Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-MAR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO						
1-968851-1	NO						
1-968880-1	NO			"1-0968880-1"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO		TYC1-968849-1				
1-968851-1	NO		TYC1-968851-1				
1-968880-1	NO		TYC1-968880-1	"1-0968880-1"			

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968851-1	NO						

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO						
1-968851-1	NO						

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO						
1-968851-1	NO						

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-1	NO		TYC1-968849-1				
1-968851-1	NO		TYC1-968851-1				
1-968880-1	NO		TYC1-968880-1	"1-0968880-1"			

Customer: TTI (3075935)

Location: Eden Prairie

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968851-1	NO						

Customer: TTI Inc (3165283)

Location: Cleveland

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968851-1	NO						
1-968880-1	NO			"1-0968880-1"			

Customer: TTI (556264)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968851-1	NO						

Explanation for a new duplication production tool 11-1935189 for AMP MCP2.8 CONTACT

(P/N: 1-968849-1 & 1-968851-1 & 1-968880-1)

1. For China local customer requirement on AMP MCP2.8 CONTACT, the new duplication production tool (11-1935189) in TE Suzhou plant for production to support only Asia-Pacific market. For this new duplication production tool , it will shorten the L/T of delivery time and offer good service for Asia-Pacific market .
2. The identification of Suzhou production part is that there are “T275” manufacturing location code marked & die - identification marked on the part as below:

