

14-Jan-2020 **PCN** #:E-20-000066

Subject:6612148 6123672 1827233 and 1827253 05FH 5H PLUG CONNECTOR 1123667 5H plug contact

Description of Change: change solder tail plating from Tin to gold flash

Reason: Product Improvement. product quality improvement

Key Dates:

Contact By Date: 10-Jul-2020

Implementation Date:10-Jul-2020

Product Affected

4-1827253-8

9-1827253-8

3-1827253-6

9-1827253-6

4-1827253-6

9-1827253-9

9-1827253-7

3-1827233-6

(Alias Part Numbers:

"1377801")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.
For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.