



29-Jan-2020

PCN #:E-20-001115

Subject:Relays SR2M/SR4/SR6 Force Guided

Description of Change: The following part numbers will receive a new CCC certificate number until the 31st of October 2020, as the current CCC certificates will be canceled by 1st of November 2020. The relays will keep their CCC approval mark; Only the process and responsibility of CCC conformance declarations will change, given by the Chinese Government.

Reason: Manufacturing / Process Requirements. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts will receive new CCC certificate numbers and will keep their CCC approval marking. This change in the CCC approval procedure are based on the Rule change given by the Chinese Government, so TE will take over the responsibility of ensuring the conformance to CCC of these parts. Therefore, the creation of the "Self Declarations of Conformance" / SDOCs, will replace the currently used "compulsory certificates", issued by CCC, latest by October 31st 2020.

Key Dates:

Contact By Date:01-Mar-2020

Implementation Date:01-Mar-2020

Product Affected

3-1415055-1

(Alias Part Numbers:

"SR4D4024")

5-1415053-1

(Alias Part Numbers:

"SR4M4005")

6-1415537-1

(Alias Part Numbers:

Product Affected

"SR6A6K12")

1415017-1

(Alias Part Numbers:

"V23050-A1024-A551"

"V23050A1024A551")

1-1415539-1

(Alias Part Numbers:

"SR960010")

7-1415054-1

(Alias Part Numbers:

"SR4D4005")

3-1415054-1

(Alias Part Numbers:

"SR4M4048")

1393260-6

(Alias Part Numbers:

"V23050-A1021-A542"

"V23050A1021A542")

3-1415006-1

(Alias Part Numbers:

"V23047-A1048-A501"

"V23047A1048A501")

1415015-1

(Alias Part Numbers:

"V23050-A1024-A533"

"V23050A1024A533")

1-1393258-1

(Alias Part Numbers:

"V23047-A1021-A501"

"V23047A1021A501")

5-1415537-8

(Alias Part Numbers:

"SR6A6K05")

1393258-2

(Alias Part Numbers:

"V23047-A1005-A501"

"V23047A1005A501")

7-1415011-1

(Alias Part Numbers:

"V23047-A1009-A511"

Product Affected

"V23047A1009A511")

1-1393258-5

(Alias Part Numbers:

"V23047-A1024-A501"

"V23047A1024A501")

6-1415537-3

(Alias Part Numbers:

"SR6A6K18")

1393258-4

(Alias Part Numbers:

"V23047-A1012-A501"

"V23047A1012A501")

6-1415055-1

(Alias Part Numbers:

"SR4D4048")

6-1415537-5

(Alias Part Numbers:

"SR6A6K24")

6-1415018-1

(Alias Part Numbers:

"V23050-A1048-A533"

"V23050A1048A533")

8-1415537-0

(Alias Part Numbers:

"SR6B6K24")

6-1415538-3

(Alias Part Numbers:

"SR960008")

1-1393260-1

(Alias Part Numbers:

"V23050-A1060-A542"

"V23050A1060A542")

4-1415053-1

(Alias Part Numbers:

"SR4M4024")

8-1415017-1

(Alias Part Numbers:

"V23050-A1005-A533"

"V23050A1005A533")

9-1415028-1

Product Affected

(Alias Part Numbers:

"V23047A1024A511X1")

4-1415516-1

(Alias Part Numbers:

"V23047A1018A511X005")

7-1415018-1

(Alias Part Numbers:

"V23050-A1060-A533"

"V23050A1060A533")

1393258-5

(Alias Part Numbers:

"V23047-A1012-A511"

"V23047A1012A511")

3-1415532-1

(Alias Part Numbers:

"V23050A1018A542X07")

1-1415017-1

(Alias Part Numbers:

"V23050-A1012-A551"

"V23050A1012A551")

7-1415537-8

(Alias Part Numbers:

"SR6B6K18")

1-1415012-1

(Alias Part Numbers:

"V23047-A1110-A501"

"V23047A1110A501")

1415062-1

(Alias Part Numbers:

"SR6D4110")

9-1415053-1

(Alias Part Numbers:

"SR4M4018")

3-1415018-1

(Alias Part Numbers:

"V23050-A1021-A533"

"V23050A1021A533")

1-1393260-0

(Alias Part Numbers:

"V23050-A1048-A542"

Product Affected

"V23050A1048A542")

1-1393260-3

(Alias Part Numbers:

"V23050-A1110-A542"

"V23050A1110A542")

7-1415006-1

(Alias Part Numbers:

"V23047-A1005-A511"

"V23047A1005A511")

8-1415535-1

(Alias Part Numbers:

"SR9400003")

1393260-5

(Alias Part Numbers:

"V23050-A1018-A542"

"V23050A1018A542")

1393260-4

(Alias Part Numbers:

"V23050-A1012-A542"

"V23050A1012A542")

1-1393258-7

(Alias Part Numbers:

"V23047-A1024-A511"

"V23047A1024A511"

"F97243-000"

"AMPS-1-1393258-7")

7-1415537-9

(Alias Part Numbers:

"SR6B6K21")

1393260-7

(Alias Part Numbers:

"V23050-A1024-A542"

"V23050A1024A542")

1-1393260-2

(Alias Part Numbers:

"V23050-A1085-A542"

"V23050A1085A542")

1415055-1

(Alias Part Numbers:

"SR4D4012")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.