



19-May-2020

PCN #:E-20-005776

Subject:OUAZ/T81 series

Description of Change: updated the switching time of Ink printing changed to laser marking, and contents of the marking is not changed

Reason: Product Improvement. Due to the increase of OUAZ/T81 order, the PCN(E-19-004715) of changing Ink printing to laser marking for OUAZ/T81 series is delayed, now updated the switching time

Key Dates:

Contact By Date:01-Oct-2020

Implementation Date:01-Oct-2020

Product Affected

1461070-2

(Alias Part Numbers:

"OUAZ-SH-105D

405")

1419131-5

(Alias Part Numbers:

"OUAZ-SS-112L

900")

5-1419130-9

(Alias Part Numbers:

"OUAZ-SH-112DZ

800")

7-1440009-1

(Alias Part Numbers:

"OUAZ-SS-103L

900")

Product Affected

7-1393779-2

(Alias Part Numbers:

"T81N5D312-24")

1461015-6

(Alias Part Numbers:

"OUAZ-SH-118L

900")

4-1419145-3

(Alias Part Numbers:

"OUAZ-SH-106L

900")

4-1419145-8

(Alias Part Numbers:

"OUAZ-SH-124L

900")

1721684-9

5-1393779-5

(Alias Part Numbers:

"T81H5D312-05")

1-1461070-1

(Alias Part Numbers:

"OUAZ-SH-112L

405")

3-1419145-9

(Alias Part Numbers:

"OUAZ-SH-105D

900")

9-1440001-6

(Alias Part Numbers:

"OUAZ-SH-112LZ

800")

1-1461070-8

(Alias Part Numbers:

"OUAZ-SH-124DZ

405")

9-1419130-8

(Alias Part Numbers:

"OUAZ-SS-109L

900")

9-1440001-2

Product Affected

(Alias Part Numbers:

"OUAZ-SH-105LZ
04000")

4-1419130-0

(Alias Part Numbers:

"OUAZ-SH-103L
900")

7-1419130-3

(Alias Part Numbers:

"OUAZ-SH-124DZ
800")

"OUAZ-SH-124DZ.800")

8-1419130-6

(Alias Part Numbers:

"OUAZ-SS-105L
900")

6-1393779-9

(Alias Part Numbers:

"T81N5D312-05")

6-1419130-5

(Alias Part Numbers:

"OUAZ-SH-112L
900")

5-1393779-8

(Alias Part Numbers:

"T81H5D312-12")

1-1461070-2

(Alias Part Numbers:

"OUAZ-SH-124L
405")

1461070-5

(Alias Part Numbers:

"OUAZ-SH-112D
405")

1461070-8

(Alias Part Numbers:

"OUAZ-SH-105L
405")

5-1419130-6

(Alias Part Numbers:

Product Affected

"OUAZ-SH-112D
900")

1-1419131-1

(Alias Part Numbers:

"OUAZ-SS-124L
900")

7-1419130-1

(Alias Part Numbers:

"OUAZ-SH-124D
903")

9-1419130-3

(Alias Part Numbers:

"OUAZ-SS-109D
900")

9-1419130-0

(Alias Part Numbers:

"OUAZ-SS-106LM
100")

8-1419130-3

(Alias Part Numbers:

"OUAZ-SS-105D
900")

1-1461071-0

(Alias Part Numbers:

"OUAZ-SS-109L
405")

5-1393779-9

(Alias Part Numbers:

"T81H5D312-24")

4-1419145-0

(Alias Part Numbers:

"OUAZ-SH-105L
900")

1461015-4

(Alias Part Numbers:

"OUAZ-SH-124D
900")

1-1461071-1

(Alias Part Numbers:

"OUAZ-SS-112L

Product Affected

405")

1-1721684-1

(Alias Part Numbers:

"OUAZ-SH-124LF

900")

5-1419145-4

(Alias Part Numbers:

"OUAZ-SS-106L

900")

1-1461071-2

(Alias Part Numbers:

"OUAZ-SS-124L

405")

5-1419145-7

(Alias Part Numbers:

"OUAZ-SS-112D

900")

7-1393779-1

(Alias Part Numbers:

"T81-N5D312 12"

"T81N5D312-12")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.