



19-Jun-2020

PCN #:E-20-007708

Subject:Force Guided Relay SR4 & SR6 second source for contact rivets

Description of Change: The following part numbers contain contact rivets, for which TE has approved an additional supplier (second source). The contacts from the additional supplier are identical in form and dimensions, in their material, as well as their manufacturing process.

Reason: Manufacturing / Process Requirements. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. Within our continued efforts to deliver our products on time, we've made the decision to approve an additional contact rivet supplier as a second source. This allows us to maintain production in case of a drop-out of our primary supplier. The contact rivets of both suppliers are identical in form, dimensions, material and manufacturing processes.

Key Dates:

Contact By Date:19-Aug-2020

Implementation Date:19-Aug-2020

Product Affected

2-1415019-1

(Alias Part Numbers:

"V23050-A1048-A551"

"V23050A1048A551")

7-1415545-4

1-1415544-5

1-1393260-2

(Alias Part Numbers:

"V23050-A1085-A542"

"V23050A1085A542"

Product Affected

"SR6B4085")

1415055-1

(Alias Part Numbers:

"SR4D4012")

1-1393260-3

(Alias Part Numbers:

"V23050-A1110-A542"

"V23050A1110A542")

7-1415053-1

(Alias Part Numbers:

"SR4M4009")

7-1415018-1

(Alias Part Numbers:

"V23050-A1060-A533"

"V23050A1060A533")

5-1415019-1

(Alias Part Numbers:

"V23050-A1110-A551"

"V23050A1110A551")

7-1415359-1

(Alias Part Numbers:

"V23050A1110A533X01")

1-1393260-1

(Alias Part Numbers:

"V23050-A1060-A542"

"V23050A1060A542")

5-1415054-1

(Alias Part Numbers:

"SR4M4085")

1393260-5

(Alias Part Numbers:

"V23050-A1018-A542"

"V23050A1018A542")

9-1415018-1

(Alias Part Numbers:

"V23050-A1110-A533"

"V23050A1110A533")

1393260-9

(Alias Part Numbers:

"V23050-A1040-A542"

Product Affected

"V23050A1040A542")

7-1415545-2

1-1415055-1

(Alias Part Numbers:

"SR4D4018")

6-1415055-1

(Alias Part Numbers:

"SR4D4048")

4-1415055-1

(Alias Part Numbers:

"SR4D4036")

3-1415532-1

(Alias Part Numbers:

"V23050A1018A542X07")

7-1415055-1

(Alias Part Numbers:

"SR4D4060")

6-1415353-1

(Alias Part Numbers:

"SR6M4021")

1415354-1

(Alias Part Numbers:

"SR6M4018")

4-1415054-1

(Alias Part Numbers:

"SR4M4060")

7-1415545-0

7-1415541-3

(Alias Part Numbers:

"SR940004")

6-1415054-1

(Alias Part Numbers:

"SR4M4110")

1-1415054-1

(Alias Part Numbers:

"SR4M4036")

9-1415366-1

(Alias Part Numbers:

"SR6D4040")

4-1415053-1

Product Affected

(Alias Part Numbers:

"SR4M4024")

2-1415054-1

(Alias Part Numbers:

"SR4M4040")

3-1415367-1

(Alias Part Numbers:

"SR4D4015")

7-1415545-7

4-1415367-1

(Alias Part Numbers:

"SR4M4015")

6-1415017-1

(Alias Part Numbers:

"V23050-A1018-A551"

"V23050A1018A551")

1415078-1

(Alias Part Numbers:

"SR6D4012")

8-1415359-1

(Alias Part Numbers:

"V23050A1110A551X01")

1393260-4

(Alias Part Numbers:

"V23050-A1012-A542"

"V23050A1012A542")

3-1415018-1

(Alias Part Numbers:

"V23050-A1021-A533"

"V23050A1021A533")

7-1415354-1

(Alias Part Numbers:

"SR6D4018")

9-1415053-1

(Alias Part Numbers:

"SR4M4018")

5-1415367-1

(Alias Part Numbers:

"SR4D4080")

3-1415019-1

Product Affected

(Alias Part Numbers:
"V23050-A1060-A551"
"V23050A1060A551")

3-1415055-1

(Alias Part Numbers:
"SR4D4024")

2-1415055-1

(Alias Part Numbers:
"SR4D4021")

8-1415055-1

(Alias Part Numbers:
"SR4D4085")

8-1415053-1

(Alias Part Numbers:
"SR4M4012")

7-1415545-1

6-1415018-1

(Alias Part Numbers:
"V23050-A1048-A533"
"V23050A1048A533")

1393260-6

(Alias Part Numbers:
"V23050-A1021-A542"
"V23050A1021A542")

1393260-1

(Alias Part Numbers:
"V23050-A1005-A542"
"V23050A1005A542")

7-1415545-3

5-1415055-1

(Alias Part Numbers:
"SR4D4040")

7-1415054-1

(Alias Part Numbers:
"SR4D4005")

8-1415017-1

(Alias Part Numbers:
"V23050-A1005-A533"
"V23050A1005A533")

1415018-1

Product Affected

(Alias Part Numbers:
"V23050-A1009-A533"
"V23050A1009A533")

6-1415367-1

(Alias Part Numbers:
"SR4M4080")

1-1415354-1

(Alias Part Numbers:
"SR6M4110")

8-1415054-1

(Alias Part Numbers:
"SR4D4006")

1-1415015-1

(Alias Part Numbers:
"V23050-A1012-A533"
"V23050A1012A533")

1393260-2

(Alias Part Numbers:
"V23050-A1006-A542"
"V23050A1006A542")

7-1415545-8

8-1415018-1

(Alias Part Numbers:
"V23050-A1085-A533"
"V23050A1085A533")

6-1415027-1

(Alias Part Numbers:
"SR6D4024")

6-1415053-1

(Alias Part Numbers:
"SR4M4006")

9-1415055-1

(Alias Part Numbers:
"SR4D4110")

8-1415353-1

(Alias Part Numbers:
"SR6D4021")

5-1415053-1

(Alias Part Numbers:
"SR4M4005")

Product Affected

2-1415017-1

(Alias Part Numbers:

"V23050-A1005-A551"

"V23050A1005A551")

3-1415054-1

(Alias Part Numbers:

"SR4M4048")

7-1415545-9

7-1415545-5

3-1415353-1

(Alias Part Numbers:

"SR6M4024")

8-1415535-1

(Alias Part Numbers:

"SR9400003")

1-1415544-3

7-1415545-6

7-1415353-1

(Alias Part Numbers:

"SR6M4012")

9-1415054-1

(Alias Part Numbers:

"SR4D4009")

1415062-1

(Alias Part Numbers:

"SR6D4110")

1-1415017-1

(Alias Part Numbers:

"V23050-A1012-A551"

"V23050A1012A551")

1-1393260-0

(Alias Part Numbers:

"V23050-A1048-A542"

"V23050A1048A542")

1415054-1

(Alias Part Numbers:

"SR4M4021")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.