



Product Change Notification

Current Date: 15-Jul-2020

TE Connectivity

Product Change Notification: P-20-019313

PCN Date: 14-JUL-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Improvement of Date Code for Power F Relays

Description of Changes

Dear customer, within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we have made the decision to improve the readability of the datecodes and the traceability of the produced parts, we are going to introduce a standardization of the marking of all Power F (V23134) relays. We are going to implement a laser marking for the datecode for all power F relays. The new datecode will show the following format after implementation: ++JJWWDL with JJ=Year, WW=week, D=day (Saturday:1) and, S=Shift and L=Line. TE Connectivity Sales Team will answer your questions on any additional information or clarification that may be needed in that respect.

Reason for Changes:

Product improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

20-JUL-2020

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

19-JUL-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
1-1414315-0	NO						
1393303-9	NO			"V23134-B0053-C642", "V23134B53C642"			
1393304-9	NO			"V23134J1052D642"			
3-1393303-7	NO			"V23134B1053C642"			
5-1393304-2	NO			"V23134K 59X312", "V23134K0059X312"			
5-1393304-7	NO			"V23134M 52G242", "V23134M0052G242", "V23134M52G242"			
6-1393303-7	NO			"V23134E 59X285"			
6-1393304-7	NO			"V23134M 53C642", "V23134M0053C642"			

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO		TYC1-1393304-1	"V23134J1053D642"			
1-1414315-0	NO		TYC1-1414315-0				
1393303-9	NO			"V23134-B0053-C642", "V23134B53C642"			
1393304-9	NO		TYC1393304-9	"V23134J1052D642"			
3-1393303-7	NO		TYC3-1393303-7	"V23134B1053C642"			
5-1393304-2	NO		TYC5-1393304-2	"V23134K 59X312", "V23134K0059X312"			
5-1393304-7	NO		TYC5-1393304-7				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"V23134M 52G242", "V23134M0052G242", "V23134M52G242"			
6-1393303-7	NO		TYC6-1393303-7	"V23134E 59X285"			
6-1393304-7	NO			"V23134M 53C642", "V23134M0053C642"			

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
3-1393303-7	NO			"V23134B1053C642"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number (s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393304-1	NO			"V23134J1053D642"			
3-1393303-7	NO			"V23134B1053C642"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414315-0	NO		TYC1-1414315-0				
1393303-9	NO			"V23134-B0053-C642", "V23134B 53C642"			
1393304-9	NO		TYC1393304-9	"V23134J1052D642"			
3-1393303-7	NO		TYC3-1393303-7	"V23134B1053C642"			
6-1393303-7	NO		TYC6-1393303-7	"V23134E 59X285"			
6-1393304-7	NO			"V23134M 53C642", "V23134M0053C642"			