



Product Change Notification

Current Date: 23-Jul-2020

TE Connectivity

Product Change Notification: P-20-019379

PCN Date: 22-JUL-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Recall of PCN P-20-019314 of 14. July 2020

Description of Changes

Dear customer, the PCN P-20-019314 was done by mistake providing the wrong information. Herewith we recall this PCN. A new PCN with the correct information will follow in the near future. Sorry for the inconvenience.

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	22-JUL-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			
1-1393302-4	NO			"VF7-11H11"			
1-1393302-6	NO			"VF7-41F11-S01"			
1-1414147-0	NO			"V23134J0052X429"			
1-1414167-0	NO						
1-1414286-0	NO						
1-1414312-0	NO			"V23134-M0052-X440"			
1-1414610-0	NO						
1393304-5	NO			"V23134J 56X408"			
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-7	NO			"V23134B1053C642"			
3-1414937-3	NO						
4-1393306-6	NO			"VF7-11F11-S01"			
5-1393302-2	NO			"V23134-A0053-G243", "V23134A 53G243"			
5-1393302-8	NO			"V23134A1052C643"			
6-1393302-3	NO			"V23134A1053C643"			
7-1393303-3	NO			"V23134J 52D642", "V23134J0052D642"			
8-1393305-4	NO			"VF4-45H11-S05"			
9-1393303-7	NO			"V23134J 53D642"			
9-1904049-3	NO						

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414147-0	NO		TYC1-1414147-0	"V23134J0052X429"			
	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414167-0							
1-1414286-0	NO		TYC1-1414286-0				
1-1414312-0	NO			"V23134-M0052-X440"			
1-1414610-0	NO						
1393304-5	NO		TYC1393304-5	"V23134J 56X408"			
2-1393302-2	NO		TYC2-1393302-2	"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-7	NO		TYC3-1393303-7	"V23134B1053C642"			
3-1414937-3	NO		TYC3-1414937-3				
5-1393302-2	NO		TYC5-1393302-2	"V23134-A0053-G243", "V23134A 53G243"			
5-1393302-8	NO		TYC5-1393302-8	"V23134A1052C643"			
6-1393302-3	NO		TYC6-1393302-3	"V23134A1053C643"			
7-1393303-3	NO		TYC7-1393303-3	"V23134J 52D642", "V23134J0052D642"			
9-1393303-7	NO		TYC9-1393303-7	"V23134J 53D642"			
9-1904049-3	NO		TYC9-1904049-3				

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			
1-1393302-4	NO			"VF7-11H11"			
1-1393302-6	NO			"VF7-41F11-S01"			
1-1414147-0	NO			"V23134J0052X429"			
1-1414167-0	NO						
3-1393303-7	NO			"V23134B1053C642"			
3-1414937-3	NO						
4-1393306-6	NO			"VF7-11F11-S01"			
8-1393305-4	NO			"VF4-45H11-S05"			

Customer: TTI Electronics Asia Pte Ltd (1407161)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			
1-1393302-4	NO			"VF7-11H11"			
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1414937-3	NO						
4-1393306-6	NO			"VF7-11F11-S01"			

Customer: TTI Electronics Asia Pte Ltd (3063486)

Location: Taipei

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393302-3	NO			"VF7-11F12"			
1-1393302-4	NO			"VF7-11H11"			
1-1393302-6	NO			"VF7-41F11-S01"			
1-1414147-0	NO			"V23134J0052X429"			
1-1414167-0	NO						
2-1393302-2	NO			"V23134A 52C643", "V23134A0052C643", "D33228-000", "AMPS-2-1393302-2"			
3-1393303-7	NO			"V23134B1053C642"			
3-1414937-3	NO						
4-1393306-6	NO			"VF7-11F11-S01"			
8-1393305-4	NO			"VF4-45H11-S05"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414147-0	NO		TYC1-1414147-0	"V23134J0052X429"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1414167-0	NO						
1-1414286-0	NO		TYC1-1414286-0				
1-1414610-0	NO						
1393304-5	NO		TYC1393304-5	"V23134J 56X408"			
3-1393303-7	NO		TYC3-1393303-7	"V23134B1053C642"			
3-1414937-3	NO		TYC3-1414937-3				
5-1393302-2	NO		TYC5-1393302-2	"V23134-A0053-G243", "V23134A 53G243"			
5-1393302-8	NO		TYC5-1393302-8	"V23134A1052C643"			
6-1393302-3	NO		TYC6-1393302-3	"V23134A1053C643"			
9-1393303-7	NO		TYC9-1393303-7	"V23134J 53D642"			
9-1904049-3	NO		TYC9-1904049-3				