



## Product Change Notification

Current Date: 21-Apr-2020

## TE Connectivity

Product Change Notification: E-20-005716

PCN Date: 21-APR-20

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

## General Product Description:

TPA LED ASSY

## Description of Changes

Packaging note has been updated

## Other attachments:

[PCN E-20-005716](#)

## Reason for Changes:

Document Clarification. Engineering request

## Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

**Note: This PCN contains only document changes, these changes do not affect the form, fit or function of the parts referenced.**

## Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
<a href="#">2286014</a>	2286014-1		E	



## PCN Description of Eng. Changes

PCN No.  
OEM / CAM informed  
Estimated First Date for samples

E-20-005716					
Not necessary					
30-Aug-20					

Picture:

**NOTES**  
Bemerkungen

- 1 TE COMPONENT PART NO.  
TE Bauteile Nr.
- 2 DATE CLOCK OF THE SINGLE PART  
Datumsuhr der Einzelteile
- 3 LETTER-INSERT FOR THE REVISION STATUS OF THE COMPONENT MOULD  
Schriftsatz fuer Aenderungszustand des Bauteil Werkzeuges
- 4 MATERIAL MARKING  
Werkstoffkennzeichnung
- 5 SUITABLE COUNTERPART DT06-2S (LED). SEE DRAWING: 2286003  
passendes Gegenstueck DT06-2S (LED). siehe Zeichnung: 2286003
- 6 MALFUNCTION CAUSED BY LAQUER IS NOT COVERD BY TE WARRANTY  
Funktionsbeeintraechtigung durch Lackieren. liegt nicht im Einfluss und Gewährleistungsumfang von TE
- 7 PLASTIC TRAY (ESD PROTECTED) PACKAGING IN CORRUGATED BOX  
Produkttraeger (ESD sicher) im Versandkarton

OLD

**NOTES**  
Bemerkungen

- 1 TE COMPONENT PART NO.  
TE Bauteile Nr.
- 2 DATE CLOCK OF THE SINGLE PART  
Datumsuhr der Einzelteile
- 3 LETTER-INSERT FOR THE REVISION STATUS OF THE COMPONENT MOULD  
Schriftsatz fuer Aenderungszustand des Bauteil Werkzeuges
- 4 MATERIAL MARKING  
Werkstoffkennzeichnung
- 5 SUITABLE COUNTERPART DT06-2S (LED). SEE DRAWING: 2286003  
passendes Gegenstueck DT06-2S (LED). siehe Zeichnung: 2286003
- 6 MALFUNCTION CAUSED BY LAQUER IS NOT COVERD BY TE WARRANTY  
Funktionsbeeintraechtigung durch Lackieren. liegt nicht im Einfluss und Gewährleistungsumfang von TE
- 7 PACKAGING IN TUBES ACCORDING TO PACKAGING SPEC V2286014  
Verpackung in Tuben gemäß Verpackungsspez V228601

NEW

x	Potential Impact for Customer	x	Product Type	x	Change Type	x	Kind of Change	x	Change Feature	Remark / Free text
x	Revision adapted	x	CONNECTOR LOCKS AND POSITION ASSURANCE	x	No Form, Fit, Function	x	Drawing	x	Drawing Change	