

TE Connectivity

Product Change Notification: P-20-019478 PCN Date: 25-AUG-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change

Description of Changes

TE Connectivity (TE) is dual sourcing the manufacturing location of the products listed below. Currently the listed products are being produced in the TE Hermosillo, MX. Facility. In the future, parts will be sourced from TE Hermosillo, MX and/or TE Norwood, Mass. USA. Lead times for orders on these part numbers will not be negatively impacted due to this change. Please contact your TE Account Manager with questions.

| Reason for Changes: | | | | | | |
|---|---|--|--|--|--|--|
| In order to support business continuity, TE is temporaril facilities. | y dual sourcing select kits and RF connector assemblies from both the TE Hermosillo, MX and TE Norwood, Mass. USA | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): First Date To Ship (Changed Parts Only): | | | | | | |
| | 01-SEP-2020 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | 31-DEC-2021 | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number (s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------|---------------------------|---------------------|-------------------------|------------------------------|---------------------------|------------------------------------|------------------------------|
| 1052523-1 | NO | | | | | | |
| 1052544-1 | NO | | | "2052-1350-02" | | | |
| 1052552-1 | NO | | | "2052-1352-02" | | | |
| 1052901-1 | NO | | | | | | |
| 1053489-1 | NO | | | | | | |
| 1054869-1 | NO | | | | | | |
| 1057780-1 | NO | | | "3152-1201-10" | | | |
| 5205980-1 | NO | | | "2-30351-0010", "1185341" | | | |
| 5207719-1 | NO | | | "2-42935-9042" | | | |
| 5207719-3 | NO | | | | | | |
| 5207908-1 | NO | | | "4-27202-1747" | | | |
| 5748676-2 | NO | | | | | | |
| <u>5748677-1</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|------------------------------|---------------------------|------------------------------------|------------------------------|
| 1052523-1 | NO | | | | | | |
| 1052544-1 | NO | | | "2052-1350-02" | | | |
| 1052552-1 | NO | | | "2052-1352-02" | | | |
| 1052901-1 | NO | | | | | | |
| 1053489-1 | NO | | | | | | |
| 1054869-1 | NO | | | | | | |
| 1057780-1 | NO | | | "3152-1201-10" | | | |
| 5205980-1 | NO | | | "2-30351-0010", "1185341" | | | |
| | | | | 1105541 | | | |

| Part | Part Discontinued | Customer | Customer Part | Alias Part Number(s) | Substitute Part | Substitute Alias Part | Description Of |
|------------------|-------------------|----------|---------------|----------------------|-----------------|-----------------------|----------------|
| Number | per PCN | Drawing | Number | (0) | Number | Number(s) | Difference |
| <u>5207719-1</u> | NO | | | "2-42935-9042" | | | |
| <u>5207719-3</u> | NO | | | | | | |
| <u>5207908-1</u> | NO | | | "4-27202-1747" | | | |
| 5748676-2 | NO | | | | | | |
| 5748677-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|------------------|---------------------------|---------------------|-------------------------|------------------------------|---------------------------|------------------------------------|------------------------------|
| 1052544-1 | NO | | | "2052-1350-02" | | | |
| <u>1052552-1</u> | NO | | | "2052-1352-02" | | | |
| 1052901-1 | NO | | | | | | |
| 1053489-1 | NO | | | | | | |
| 1054869-1 | NO | | | | | | |
| <u>1057780-1</u> | NO | | | "3152-1201-10" | | | |
| 5205980-1 | NO | | | "2-30351-0010", "1185341" | | | |
| 5207719-1 | NO | | | "2-42935-9042" | | | |
| <u>5207719-3</u> | NO | | | | | | |
| <u>5207908-1</u> | NO | | | "4-27202-1747" | | | |
| <u>5748676-2</u> | NO | | | | | | • |
| <u>5748677-1</u> | NO | | | | | | |