



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019875

PCN Date: 20-OCT-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
043639-000	NO			"3-1190335-0", "TXR40AB90-1607AI"			
044674-000	NO			"2-1190343-1", "209M412-19B"			
068659-000	NO			"2-1190517-8", "TXR76AB00-1406AI"			
074975-000	NO			"9-1190560-1", "TXR41AB00-1806AI"			
093385-000	NO			"1-1190685-0", "TXR40AB00-1612BI"			
099503-000	NO			"2-1190729-9", "TXR54AC00-0804AI"			
105217-000	NO			"2-1190769-2", "TXR54AB00-0804BI"			
112873-000	NO			"4-1190823-8", "TXR41AB00-2410AI"			
113745-000	NO			"6-1190829-3", "TXR40AB00-2407AI"			
130209-000	NO			"6-1190945-5", "TXR40BW00-1810AI"			
131975-000	NO			"3-1190959-9", "TXR40SJ00-1006AI"			
145697-000	NO			"6-1191052-2", "TXR41AB00-1006AI"			
146995-000	NO			"3-1191062-0", "TXR40AB00-1410AI"			
165763-000	NO			"7-1191196-0", "TXR40AB45-2218AI"			
168289-000	NO			"4-1191225-3", "TXR41AB00-2414AI"			
169269-000	NO			"3-1191232-0", "TXR40AB00-1407AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
177931-000	NO			"6-1191293-2", "TXR15AB00-2412AI"			
179233-000	NO			"9-1191302-2", "TXR40BW00-1610AI"			
218886-000	NO			"5-1198311-8", "TXR40AB45-1007BI"			
253087-000	NO			"1191852-1", "TXR40AC00-2216BI"			
254995-000	NO			"8-1191866-9", "TXR76AB00-0804AI"			
283879-000	NO			"1192144-1", "TXR40AB90-0804AI"			
306973-000	NO			"3-1192325-4", "TXR40AC00-1010AI"			
308763-000	NO			"5-1192338-7", "TXR40AC00-2410AI"			
320635-000	NO			"8-1192430-7", "TXR41AB00-1406AI"			
337735-000	NO			"6-1192549-4", "TXR40BW00-1608AI"			
359189-000	NO			"9-1192694-9", "TXR54AB00-1816AI"			
367328-000	NO			"7-1199196-3", "TXR40AC90-2016AI"			
373299-000	NO			"1-1192796-9", "TXR41AB90-1812BI"			
377253-000	NO			"1-1192825-4", "TXR40BW00-2416AI"			
402983-000	NO			"1193042-9", "TXR40AC45-0804BI"			
407824-000	NO			"4-1193076-1", "TXR40AB90-1404AI"			
407979-000	NO			"218M632B19B", "5-1193077-1"			
412819-000	NO			"1193113-7", "TXR40AB00-1806BI"			
415359-000	NO			"3-1193130-6", "TXR40BW00-1005AI"			
415943-000	NO			"1-1193135-2", "TXR41AB00-1405AI"			
417669-000	NO			"9-1193146-8", "TXR15AB00-2414AI"			
432825-000	NO			"204M014-19B06-40", "4-1193255-9"			
433093-000	NO			"6-1193257-1", "TXR54AB90-1608AI"			
449341-000	NO			"6-1193375-2", "TXR40BW00-1814AI"			
455940-000	NO			"1-1193422-7", "203M908-19B"			
457380-000	NO			"209M408-19C", "2-1193432-1"			
463243-000	NO			"1193474-6", "203M012-19B07-12"			
480961-000	NO			"3-1193600-4", "TXR40AB90-2014AI"			
504881-000	NO			"4-1193813-0", "TXR54AC00-1006AI"			
508624-000	NO			"203M208-19B04", "6-1193998-7"			
511647S001	NO			"5-1194021-2", "TXR41AB00-2210BI-CS2315"			
570655-000	NO			"2-1194523-7", "TXR32AB00-2012AI"			
584487-000	NO			"5-1194628-6", "TXR40AB90-2412AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
603573-000	NO			"7-1194776-3", "TXR40AB90-2216AI"			
606076-000	NO			"5-1198838-3", "TXR40AB45-1810AI"			
609961-000	NO			"1194823-7", "TXR40AB90-1008AI"			
616803-000	NO			"204M112-19B04-40", "6-1194874-4"			
620737-000	NO			"8-1194904-6", "218M628-19B"			
633907-000	NO			"1-1195014-7", "TXR40AB90-2214AI"			
638339-000	NO			"8-1195045-7", "TXR40AB00-1414AI"			
638701-000	NO			"6-1195048-4", "TXR40BW00-1007AI"			
687452-000	NO			"7-1195398-1", "202M124-19B"			
703855S001	NO			"8-1195521-9", "TXR41AB90-1206BI-CS2259"			
726907-000	NO			"4-1195681-8", "TXR76AB00-1207AI"			
734059-000	NO			"2-1195733-2", "TXR40AB00-1810AI"			
743425-000	NO			"3-1195800-9", "TXR54AB00-2808AI"			
749301-000	NO			"2-1195844-5", "TXR40AB90-1208AI"			
754567-000	NO			"2-1195882-0", "TXR76AB00-1006AI"			
757847-000	NO			"2-1195905-2", "TXR18AB00-2205AI"			
763691-000	NO			"9-1195945-5", "TX21AB00-0804"			
792623-000	NO			"8-1196137-1", "TXR40AB45-2416AI"			
799612-000	NO			"1-1196182-0", "TXR54AB00-2216AI"			
807915S002	NO			"203M018-19C08-CS5567", "1196265-5"			
816217-000	NO			"9-1196360-8", "TXR40AC90-1007AI"			
822313-000	NO			"9-1196412-6", "TXR40AB00-1005BI"			
837783-000	NO			"8-1196538-1", "TXR18AB00-1606AI"			
865172-000	NO			"8-1200027-3", "TXR54AB00-2010AI2J"			
865757-000	NO			"9-1196741-0", "TXR41AB90-1207AI"			
883337-000	NO			"1-1196875-2", "TXR40AC00-1204AI"			
883741-000	NO			"1196878-4", "TXR40AB90-2016BI"			
885031-000	NO			"1-1196887-6", "TXR21AB00-2216CI"			
886603-000	NO			"1196898-8", "TXR41AB90-1407AI"			
896227-000	NO			"5-1196968-0", "TXR41SJ00-1206AI"			
928279-000	NO			"1197198-1", "TXR41AB90-1006AI"			
929031-000	NO			"1197203-9", "TXR40AB00-1814AI"			
950825-000	NO			"1-1197353-6", "TXR40AB90-2210AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
953753-000	NO			"9-1197384-8", "TXR40BW00-1206AI"			
966135-000	NO			"2-1197471-8", "TXR40AB90-2008AI"			
973765-000	NO			"8-1197525-3", "TXR41AB90-1812AI"			
975981-000	NO			"7-1197541-7", "TXR54AB90-1408AI"			
980525-000	NO			"9-1197576-6", "TXR40AB45-1208BI"			
AAE9406-00	NO			"STXR41SJ00-1210AI"			
CF0574-000	NO			"STXR40BW00-1614AI"			
CH0814-000	NO			"TXR40SJ45-1408BI", "3-1899517-4"			
CH1171-000	NO			"208M908-19B06", "1-1899527-5"			
CH3923-000	NO			"3-1899625-2", "TXR40AB00-1610AIJ"			
CJ0281-000	NO			"BND40AB00-1209A"			
CP1245-000	NO			"TXR15AB00-2820AI"			
CP3502-000	NO			"TXR88AB00-0906AI"			
CS0253-000	NO			"TXR54AC00-2414AI-CS2928"			
CU6829-000	NO			"208M714-01W12"			
CV0758-000	NO			"5-1899730-4", "TXR40AZ00-1007AI"			
CV1543-000	NO			"STXR40AZ00-1010BI"			
CW0599-000	NO			"TX40AZ00-2408"			
CW0954-000	NO			"TXR21AZ00-0804AI"			
CW0961-000	NO			"TXR41AZ90-1007AI"			
CW3887-000	NO			"STXR40AZ00-0807BI"			
CW3889-000	NO			"STXR40AZ00-1210BI", "STXR40AZ00-1210BI"			
CW3892-000	NO			"STXR40AZ90-2424BI"			
CW3906-000	NO			"TX54AZ00-0804"			
CY0506-000	NO			"208M724-62J10"			
CZ6612-000	NO			"TX40AZ00-1004"			
EB9483-000	NO			"TXR40AZ90-1612BI"			
EG0498-000	NO			"TXR54AC00-1814BI"			
EG1539-000	NO			"BND40AB00-1208W"			
EG4120-000	NO			"TX18AZ00C1204"			
EH8414-000	NO			"STXR40SJ00-0807AI"			

Customer: TTI, Inc. (1305175)

Location: Maisach-germlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
044674-000	NO			"2-1190343-1", "209M412-19B"			
068659-000	NO		RAY068659-000	"2-1190517-8", "TXR76AB00-1406AI"			
093385-000	NO		RAY093385-000	"1-1190685-0", "TXR40AB00-1612BI"			
099503-000	NO		RAY099503-000	"2-1190729-9", "TXR54AC00-0804AI"			
112873-000	NO			"4-1190823-8", "TXR41AB00-2410AI"			
130209-000	NO		RAY130209-000	"6-1190945-5", "TXR40BW00-1810AI"			
131975-000	NO		RAY131975-000	"3-1190959-9", "TXR40SJ00-1006AI"			
145697-000	NO		RAY145697-000	"6-1191052-2", "TXR41AB00-1006AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
146995-000	NO		RAY146995-000	"3-1191062-0", "TXR40AB00-1410AI"			
168289-000	NO			"4-1191225-3", "TXR41AB00-2414AI"			
169269-000	NO		RAY169269-000	"3-1191232-0", "TXR40AB00-1407AI"			
179233-000	NO			"9-1191302-2", "TXR40BW00-1610AI"			
254995-000	NO			"8-1191866-9", "TXR76AB00-0804AI"			
308763-000	NO			"5-1192338-7", "TXR40AC00-2410AI"			
320635-000	NO		RAY320635-000	"8-1192430-7", "TXR41AB00-1406AI"			
337735-000	NO			"6-1192549-4", "TXR40BW00-1608AI"			
377253-000	NO			"1-1192825-4", "TXR40BW00-2416AI"			
415359-000	NO			"3-1193130-6", "TXR40BW00-1005AI"			
432825-000	NO			"204M014-19B06-40", "4-1193255-9"			
449341-000	NO		RAY449341-000	"6-1193375-2", "TXR40BW00-1814AI"			
455940-000	NO			"1-1193422-7", "203M908-19B"			
584487-000	NO			"5-1194628-6", "TXR40AB90-2412AI"			
616803-000	NO			"204M112-19B04-40", "6-1194874-4"			
638339-000	NO			"8-1195045-7", "TXR40AB00-1414AI"			
638701-000	NO			"6-1195048-4", "TXR40BW00-1007AI"			
734059-000	NO		RAY734059-000	"2-1195733-2", "TXR40AB00-1810AI"			
743425-000	NO			"3-1195800-9", "TXR54AB00-2808AI"			
749301-000	NO		RAY749301-000	"2-1195844-5", "TXR40AB90-1208AI"			
754567-000	NO			"2-1195882-0", "TXR76AB00-1006AI"			
799612-000	NO			"1-1196182-0", "TXR54AB00-2216AI"			
837783-000	NO			"8-1196538-1", "TXR18AB00-1606AI"			
883337-000	NO			"1-1196875-2", "TXR40AC00-1204AI"			
883741-000	NO			"1196878-4", "TXR40AB90-2016BI"			
928279-000	NO			"1197198-1", "TXR41AB90-1006AI"			
929031-000	NO		RAY929031-000	"1197203-9", "TXR40AB00-1814AI"			
953753-000	NO			"9-1197384-8", "TXR40BW00-1206AI"			
AAE9406-00	NO			"STXR41SJ00-1210AI"			
CF0574-000	NO		RAYCF0574-000	"STXR40BW00-1614AI"			
CH3923-000	NO			"3-1899625-2", "TXR40AB00-1610AIJ"			
CW0599-000	NO			"TX40AZ00-2408"			
EG0498-000	NO			"TXR54AC00-1814BI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EG1539-000	NO			"BND40AB00-1208W"			
EH8414-000	NO		RAYEH8414-000	"STXR40SJ00-0807AI"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
043639-000	NO			"3-1190335-0", "TXR40AB90-1607AI"			
044674-000	NO			"2-1190343-1", "209M412-19B"			
074975-000	NO			"9-1190560-1", "TXR41AB00-1806AI"			
113745-000	NO			"6-1190829-3", "TXR40AB00-2407AI"			
145697-000	NO			"6-1191052-2", "TXR41AB00-1006AI"			
146995-000	NO			"3-1191062-0", "TXR40AB00-1410AI"			
165763-000	NO			"7-1191196-0", "TXR40AB45-2218AI"			
169269-000	NO			"3-1191232-0", "TXR40AB00-1407AI"			
177931-000	NO			"6-1191293-2", "TXR15AB00-2412AI"			
253087-000	NO			"1191852-1", "TXR40AC00-2216BI"			
283879-000	NO			"1192144-1", "TXR40AB90-0804AI"			
320635-000	NO			"8-1192430-7", "TXR41AB00-1406AI"			
359189-000	NO			"9-1192694-9", "TXR54AB00-1816AI"			
367328-000	NO			"7-1199196-3", "TXR40AC90-2016AI"			
373299-000	NO			"1-1192796-9", "TXR41AB90-1812BI"			
407824-000	NO			"4-1193076-1", "TXR40AB90-1404AI"			
407979-000	NO			"218M632B19B", "5-1193077-1"			
412819-000	NO			"1193113-7", "TXR40AB00-1806BI"			
415943-000	NO			"1-1193135-2", "TXR41AB00-1405AI"			
417669-000	NO			"9-1193146-8", "TXR15AB00-2414AI"			
433093-000	NO			"6-1193257-1", "TXR54AB90-1608AI"			
455940-000	NO			"1-1193422-7", "203M908-19B"			
457380-000	NO			"209M408-19C", "2-1193432-1"			
480961-000	NO			"3-1193600-4", "TXR40AB90-2014AI"			
508624-000	NO			"203M208-19B04", "6-1193998-7"			
570655-000	NO			"2-1194523-7", "TXR32AB00-2012AI"			
584487-000	NO			"5-1194628-6", "TXR40AB90-2412AI"			
603573-000	NO			"7-1194776-3", "TXR40AB90-2216AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
606076-000	NO			"5-1198838-3", "TXR40AB45-1810AI"			
609961-000	NO			"1194823-7", "TXR40AB90-1008AI"			
620737-000	NO			"8-1194904-6", "218M628-19B"			
633907-000	NO			"1-1195014-7", "TXR40AB90-2214AI"			
687452-000	NO			"7-1195398-1", "202M124-19B"			
703855S001	NO			"8-1195521-9", "TXR41AB90-1206BI-CS2259"			
726907-000	NO			"4-1195681-8", "TXR76AB00-1207AI"			
734059-000	NO			"2-1195733-2", "TXR40AB00-1810AI"			
749301-000	NO			"2-1195844-5", "TXR40AB90-1208AI"			
757847-000	NO			"2-1195905-2", "TXR18AB00-2205AI"			
763691-000	NO			"9-1195945-5", "TX21AB00-0804"			
792623-000	NO			"8-1196137-1", "TXR40AB45-2416AI"			
799612-000	NO			"1-1196182-0", "TXR54AB00-2216AI"			
816217-000	NO			"9-1196360-8", "TXR40AC90-1007AI"			
822313-000	NO			"9-1196412-6", "TXR40AB00-1005BI"			
865172-000	NO			"8-1200027-3", "TXR54AB00-2010AI2J"			
865757-000	NO			"9-1196741-0", "TXR41AB90-1207AI"			
885031-000	NO			"1-1196887-6", "TXR21AB00-2216CI"			
886603-000	NO			"1196898-8", "TXR41AB90-1407AI"			
928279-000	NO			"1197198-1", "TXR41AB90-1006AI"			
929031-000	NO			"1197203-9", "TXR40AB00-1814AI"			
950825-000	NO			"1-1197353-6", "TXR40AB90-2210AI"			
966135-000	NO			"2-1197471-8", "TXR40AB90-2008AI"			
973765-000	NO			"8-1197525-3", "TXR41AB90-1812AI"			
975981-000	NO			"7-1197541-7", "TXR54AB90-1408AI"			
980525-000	NO			"9-1197576-6", "TXR40AB45-1208BI"			
CH0814-000	NO			"TXR40SJ45-1408BI", "3-1899517-4"			
CH1171-000	NO			"208M908-19B06", "1-1899527-5"			
CP1245-000	NO			"TXR15AB00-2820AI"			
CP3502-000	NO			"TXR88AB00-0906AI"			
CW0599-000	NO			"TX40AZ00-2408"			
CW0961-000	NO			"TXR41AZ90-1007AI"			
CW3887-000	NO			"STXR40AZ00-0807BI"			
CW3889-000	NO			"STXR40AZ00-1210BI", "STXR40AZ00-1210BI"			
CW3892-000	NO			"STXR40AZ90-2424BI"			
CY0506-000	NO			"208M724-62J10"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CZ6612-000	NO			"TX40AZ00-1004"			
EB9483-000	NO			"TXR40AZ90-1612BI"			
EG4120-000	NO			"TX18AZ00C1204"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
105217-000	NO			"2-1190769-2", "TXR54AB00-0804BI"			
145697-000	NO			"6-1191052-2", "TXR41AB00-1006AI"			
146995-000	NO			"3-1191062-0", "TXR40AB00-1410AI"			
169269-000	NO			"3-1191232-0", "TXR40AB00-1407AI"			
306973-000	NO			"3-1192325-4", "TXR40AC00-1010AI"			
367328-000	NO			"7-1199196-3", "TXR40AC90-2016AI"			
402983-000	NO			"1193042-9", "TXR40AC45-0804BI"			
412819-000	NO			"1193113-7", "TXR40AB00-1806BI"			
433093-000	NO			"6-1193257-1", "TXR54AB90-1608AI"			
455940-000	NO			"1-1193422-7", "203M908-19B"			
457380-000	NO			"209M408-19C", "2-1193432-1"			
463243-000	NO			"1193474-6", "203M012-19B07-12"			
504881-000	NO			"4-1193813-0", "TXR54AC00-1006AI"			
511647S001	NO			"5-1194021-2", "TXR41AB00-2210BI-CS2315"			
570655-000	NO			"2-1194523-7", "TXR32AB00-2012AI"			
584487-000	NO			"5-1194628-6", "TXR40AB90-2412AI"			
609961-000	NO			"1194823-7", "TXR40AB90-1008AI"			
633907-000	NO			"1-1195014-7", "TXR40AB90-2214AI"			
734059-000	NO			"2-1195733-2", "TXR40AB00-1810AI"			
749301-000	NO			"2-1195844-5", "TXR40AB90-1208AI"			
792623-000	NO			"8-1196137-1", "TXR40AB45-2416AI"			
807915S002	NO			"203M018-19C08-CS5567", "1196265-5"			
896227-000	NO			"5-1196968-0", "TXR41SJ00-1206AI"			
966135-000	NO			"2-1197471-8", "TXR40AB90-2008AI"			
980525-000	NO			"9-1197576-6", "TXR40AB45-1208BI"			
CH1171-000	NO			"208M908-19B06", "1-1899527-5"			
CS0253-000	NO			"TXR54AC00-2414AI-CS2928"			
CU6829-000	NO			"208M714-01W12"			
CV0758-000	NO			"5-1899730-4", "TXR40AZ00-1007AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CV1543-000	NO			"STXR40AZ00-1010BI"			
CW0599-000	NO			"TX40AZ00-2408"			
CW0954-000	NO			"TXR21AZ00-0804AI"			
CW0961-000	NO			"TXR41AZ90-1007AI"			
CW3887-000	NO			"STXR40AZ00-0807BI"			
CW3889-000	NO			"STXR40AZ00-1210BI", "STXR40AZ00-1210BI"			
CW3892-000	NO			"STXR40AZ90-2424BI"			
CW3906-000	NO			"TX54AZ00-0804"			
CZ6612-000	NO			"TX40AZ00-1004"			
EB9483-000	NO			"TXR40AZ90-1612BI"			
EG4120-000	NO			"TX18AZ00C1204"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gerlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
044674-000	NO			"2-1190343-1", "209M412-19B"			
068659-000	NO		RAY068659-000	"2-1190517-8", "TXR76AB00-1406AI"			
093385-000	NO		RAY093385-000	"1-1190685-0", "TXR40AB00-1612BI"			
099503-000	NO		RAY099503-000	"2-1190729-9", "TXR54AC00-0804AI"			
112873-000	NO			"4-1190823-8", "TXR41AB00-2410AI"			
130209-000	NO		RAY130209-000	"6-1190945-5", "TXR40BW00-1810AI"			
131975-000	NO		RAY131975-000	"3-1190959-9", "TXR40SJ00-1006AI"			
145697-000	NO		RAY145697-000	"6-1191052-2", "TXR41AB00-1006AI"			
146995-000	NO		RAY146995-000	"3-1191062-0", "TXR40AB00-1410AI"			
168289-000	NO			"4-1191225-3", "TXR41AB00-2414AI"			
169269-000	NO		RAY169269-000	"3-1191232-0", "TXR40AB00-1407AI"			
179233-000	NO			"9-1191302-2", "TXR40BW00-1610AI"			
254995-000	NO			"8-1191866-9", "TXR76AB00-0804AI"			
308763-000	NO			"5-1192338-7", "TXR40AC00-2410AI"			
320635-000	NO		RAY320635-000	"8-1192430-7", "TXR41AB00-1406AI"			
337735-000	NO			"6-1192549-4", "TXR40BW00-1608AI"			
377253-000	NO			"1-1192825-4", "TXR40BW00-2416AI"			
415359-000	NO			"3-1193130-6", "TXR40BW00-1005AI"			
432825-000	NO			"204M014-19B06-40", "4-1193255-9"			
449341-000	NO		RAY449341-000	"6-1193375-2", "TXR40BW00-1814AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
455940-000	NO			"1-1193422-7", "203M908-19B"			
584487-000	NO			"5-1194628-6", "TXR40AB90-2412AI"			
616803-000	NO			"204M112-19B04-40", "6-1194874-4"			
638339-000	NO			"8-1195045-7", "TXR40AB00-1414AI"			
638701-000	NO			"6-1195048-4", "TXR40BW00-1007AI"			
734059-000	NO		RAY734059-000	"2-1195733-2", "TXR40AB00-1810AI"			
743425-000	NO			"3-1195800-9", "TXR54AB00-2808AI"			
749301-000	NO		RAY749301-000	"2-1195844-5", "TXR40AB90-1208AI"			
754567-000	NO			"2-1195882-0", "TXR76AB00-1006AI"			
799612-000	NO			"1-1196182-0", "TXR54AB00-2216AI"			
837783-000	NO			"8-1196538-1", "TXR18AB00-1606AI"			
883337-000	NO			"1-1196875-2", "TXR40AC00-1204AI"			
883741-000	NO			"1196878-4", "TXR40AB90-2016BI"			
928279-000	NO			"1197198-1", "TXR41AB90-1006AI"			
929031-000	NO		RAY929031-000	"1197203-9", "TXR40AB00-1814AI"			
953753-000	NO			"9-1197384-8", "TXR40BW00-1206AI"			
AAE9406-00	NO			"STXR41SJ00-1210AI"			
CF0574-000	NO		RAYCF0574-000	"STXR40BW00-1614AI"			
CH3923-000	NO			"3-1899625-2", "TXR40AB00-1610AIJ"			
CW0599-000	NO			"TX40AZ00-2408"			
EG0498-000	NO			"TXR54AC00-1814BI"			
EG1539-000	NO			"BND40AB00-1208W"			
EH8414-000	NO		RAYEH8414-000	"STXR40SJ00-0807AI"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
218886-000	NO			"5-1198311-8", "TXR40AB45-1007BI"			
CJ0281-000	NO			"BND40AB00-1209A"			

Customer: TTI Electronics Asia Pte Ltd. (1407161)

Location: Hong Kong

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
218886-000	NO			"5-1198311-8", "TXR40AB45-1007B1"			
CJ0281-000	NO			"BND40AB00-1209A"			