



Product Change Notification

Current Date: 21-Oct-2020

TE Connectivity

Product Change Notification: P-20-019874

PCN Date: 20-OCT-20

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing location change product change notification

Description of Changes

The following Part Numbers will be transferred from the Bath facility, UK, to Hastings UK location.

Reason for Changes:

Relocating the products will support a fully integrated, vertical model including machining, plating and assembly with a view to improving lead times and operational flexibility. Our plan includes mitigating actions to ensure this is a smooth transfer, and both facilities operating under AS9100. The transfer will be in phases, starting at the end of 2020, and target competition date end of 2021.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	31-DEC-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
045865-000	NO			"5-1190352-5", "TX40AC90-1006"			
069359-000	NO			"9-1190521-6", "201M128-19C"			
140070-000	NO			"6-1191015-3", "203M016-19B10"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206AI"			
152201-000	NO			"1191100-9", "TXR54AB00-1812BI"			
167451-000	NO			"1-1191219-9", "STXR40AB00-1210AI"			
174289-000	NO			"6-1191267-4", "TXR40AB00-2408AI"			
224077-000	NO			"8-1191650-5", "TXR40AB90-1005AI"			
252406-000	NO			"3-1199929-9", "TXS104AB00-1005AI"			
256493-000	NO			"1191877-3", "STXR41AB00-1210AI"			
262233-000	NO			"9-1191930-3", "TXR40AC90-1808AI"			
278451-000	NO			"6-1192061-5", "TXR54AB00-2214AI"			
294311-000	NO			"9-1192229-8", "TXR40AC90-1607AI"			
301227-000	NO			"1-1192282-2", "TXR40BW00-0804AI"			
334781-000	NO			"9-1192528-0", "202M216-19B"			
347583-000	NO			"7-1192615-6", "TXR40BW00-2014AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
355597-000	NO			"5-1192669-9", "TXR40BW00-1812AI"			
385453-000	NO			"1-1192892-8", "TXR15AB00-2424AI"			
396055-000	NO			"8-1192970-9", "TXR41AB90-1612AI"			
411147-000	NO			"8-1193100-0", "TXR41AB00-1408AI"			
421397-000	NO			"3-1193174-3", "TXR40AB00-2014AI"			
440177-000	NO			"1193309-6", "TXR41AB00-2212AI"			
443143-000	NO			"204M116-19B04-40", "1193331-4"			
444671-000	NO			"2-1193342-2", "TXR41AB90-2412AI"			
447297-000	NO			"3-1193361-8", "TXR76AB00-1605AI"			
451483-000	NO			"5-1193390-2", "TXR54AB00-2410BI"			
481087-000	NO			"1-1193601-8", "TXR76AB00-1204AI"			
495693-000	NO			"4-1193707-2", "TXR41AB00-1410BI"			
520935-000	NO			"8-1194094-0", "TXR40AB00-1604AI"			
535325-000	NO			"2-1194203-3", "TXR41AB00-1608AI"			
540553-000	NO			"2-1194240-1", "TXR40AC00-2414AI"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406AI"			
572809-000	NO			"8-1194547-6", "TXR40AB00-2216AI"			
576287-000	NO			"3-1194572-2", "TXR40AB90-2010BI"			
600577-000	NO			"3-1194752-2", "TXR40AC00-1610BI"			
608335-000	NO			"7-1194811-5", "TXR40BW00-1810BI"			
621387-000	NO			"9-1194910-8", "TXR76AB00-1405AI"			
638627-000	NO			"1195048-6", "TX40AB90-0804"			
641131-000	NO			"6-1195067-1", "TXR40AB00-1204BI"			
645057-000	NO			"9-1195094-6", "TXR41AC00-1208AI"			
667053-000	NO			"2-1195254-5", "TXR21AB00-1205AI"			
671613-000	NO			"9-1195284-0", "TXR40AC00-1210AI"			
675991-000	NO			"8-1195315-7", "TXR54AB90-1204BI"			
697581-000	NO			"1195475-3", "TXR41AB00-1607AI"			
699062-000	NO			"7-1201153-0", "TXR40SJ00-1408BI"			
739884-000	NO			"1195775-3", "201M918-62J"			
757063-000	NO			"4-1195899-5", "TXR40AB00-0807AI"			
762621-000	NO			"4-1195938-9", "TXR40AB90-1408AI"			
778005-000	NO			"9-1196055-5", "TXR40AB00-1205AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
808656-000	NO			"3-1196279-2", "201M122-19C"			
812043-000	NO			"9-1196316-4", "TXR40AB00-1810BI"			
814229-000	NO			"9-1196336-0", "TXR54AC00-1004AI"			
826827-000	NO			"3-1196458-7", "TXR40SJ00-1007AI"			
832211-000	NO			"8-1196497-8", "TXR40AB45-1814AI"			
864163-000	NO			"3-1196730-8", "TXR40BW00-1408AI"			
880831-000	NO			"3-1196857-1", "TXR41AB00-1410AI"			
886625-000	NO			"2-1196898-0", "TXR41AB00-2220AI"			
887445-000	NO			"5-1196904-3", "TXR54AB90-1004AI"			
902654-000	NO			"9-1197014-7", "TXR54AB00-1004AI"			
913885-000	NO			"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
952393-000	NO			"2-1197375-1", "TXR40AB90-1410BI"			
955847-000	NO			"5-1197400-6", "TXR40AB90-1608AI"			
970531-000	NO			"6-1197502-2", "TXR18AB00B3620AI"			
982603-000	NO			"204M010-19B04-40", "1-1197592-5"			
AAF2661-00	NO			"TXR40AB00-1408AIJ"			
C73862-000	NO			"6-1200810-6", "TXR40AU00-1006AI"			
C76413-000	NO			"1-1200503-0", "TXR40SJ90-1410BI"			
CA7140-000	NO			"TXR40BW00-2216AI", "5-1899129-3"			
CB3822-000	NO			"TXR40AB45-2006AI"			
CB4935-000	NO			"TXR40AZ00-1004AI"			
CF0470-000	NO			"5-1899165-3", "STXR40BW00-0805AI"			
CF0573-000	NO			"STXR40BW00-1210AI", "1-1899174-4"			
CF4657-000	NO			"TXR41SJ00-1610AI"			
CF4658-000	NO			"TXR66SJ00-2820BI"			
CF7703-000	NO			"TXR40AB00-1208AIJ"			
CF8796-000	NO			"TXR40AB00-1604BI", "2-1899238-0"			
CP1490-000	NO			"TXR88AB00-1006AI"			
CV5404-000	NO			"TXR40AZ00-1810AI"			
CV5408-000	NO			"TXR40AZ00-1814BI"			
CV5416-000	NO			"TXR40AZ00-2218BI"			
CW0950-000	NO			"TXR15AZ00-2014AI"			
CW1055-000	NO			"TXR40AZ00-1404BI"			
CW1080-000	NO			"TXR40AZ00-2216BI"			
CW3905-000	NO			"TXR40AZ90-1004AI"			
CW4641-000	NO			"TXR40AZ00-1008BI"			
CZ3865-000	NO			"TXR40AZ90-1007AI"			
CZ4491-000	NO			"TXR40AZ00-1208BI"			
CZ4501-000	NO			"TX40AZ00-0804"			
CZ9647-000	NO			"TXS201AX00-2418"			
E24641-000	NO			"4-1200810-2", "TXR76AU00-1208AI"			
E57334-000	NO			"8-1201206-4", "TXR40AB45-1814BI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
EB9476-000	NO			"TXR40AZ90-1406AI"			
EB9526-000	NO			"TXR54AZ90-0804AI"			
EG0237-000	NO			"TXR40AZ00-2006AI"			
EG1672-000	NO			"TXR40AZ00-1806BI"			
EG2466-000	NO			"BND18AB00-2216W"			
EJ0471-000	NO			"TXR40SJ00-2424AI"			
EK2357-000	NO			"228M714-19U"			
F87005-000	NO			"3-1201366-9", "TXR40SJ90-2008AI"			

Customer: TTI, Inc. (1305175)

Location: Maisach-germlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
069359-000	NO			"9-1190521-6", "201M128-19C"			
140070-000	NO		RAY140070-000	"6-1191015-3", "203M016-19B10"			
152201-000	NO			"1191100-9", "TXR54AB00-1812BI"			
167451-000	NO		RAY167451-000	"1-1191219-9", "STXR40AB00-1210AI"			
224077-000	NO			"8-1191650-5", "TXR40AB90-1005AI"			
252406-000	NO			"3-1199929-9", "TXS104AB00-1005AI"			
256493-000	NO			"1191877-3", "STXR41AB00-1210AI"			
278451-000	NO			"6-1192061-5", "TXR54AB00-2214AI"			
301227-000	NO			"1-1192282-2", "TXR40BW00-0804AI"			
334781-000	NO			"9-1192528-0", "202M216-19B"			
347583-000	NO			"7-1192615-6", "TXR40BW00-2014AI"			
355597-000	NO		RAY355597-000	"5-1192669-9", "TXR40BW00-1812AI"			
421397-000	NO		RAY421397-000	"3-1193174-3", "TXR40AB00-2014AI"			
440177-000	NO			"1193309-6", "TXR41AB00-2212AI"			
443143-000	NO			"204M116-19B04-40", "1193331-4"			
447297-000	NO			"3-1193361-8", "TXR76AB00-1605AI"			
481087-000	NO			"1-1193601-8", "TXR76AB00-1204AI"			
495693-000	NO			"4-1193707-2", "TXR41AB00-1410BI"			
535325-000	NO		RAY535325-000	"2-1194203-3", "TXR41AB00-1608AI"			
540553-000	NO			"2-1194240-1", "TXR40AC00-2414AI"			
554173-000	NO		RAY554173-000	"5-1194375-5", "TXR40AB00-1406AI"			
572809-000	NO			"8-1194547-6", "TXR40AB00-2216AI"			
621387-000	NO			"9-1194910-8", "TXR76AB00-1405AI"			
671613-000	NO			"9-1195284-0", "TXR40AC00-1210AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
697581-000	NO		RAY697581-000	"1195475-3", "TXR41AB00-1607AI"			
778005-000	NO		RAY778005-000	"9-1196055-5", "TXR40AB00-1205AI"			
808656-000	NO			"3-1196279-2", "201M122-19C"			
812043-000	NO		RAY812043-000, RAYTXR40AB00-1810BI	"9-1196316-4", "TXR40AB00-1810BI"			
826827-000	NO			"3-1196458-7", "TXR40SJ00-1007AI"			
864163-000	NO			"3-1196730-8", "TXR40BW00-1408AI"			
913885-000	NO		RAY913885-000	"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
982603-000	NO			"204M010-19B04-40", "1-1197592-5"			
AAF2661-00	NO			"TXR40AB00-1408AIJ"			
C73862-000	NO		RAYC73862-000	"6-1200810-6", "TXR40AU00-1006AI"			
CA7140-000	NO			"TXR40BW00-2216AI", "5-1899129-3"			
CF0470-000	NO			"5-1899165-3", "STXR40BW00-0805AI"			
CF0573-000	NO		RAYCF0573-000	"STXR40BW00-1210AI", "1-1899174-4"			
CF7703-000	NO			"TXR40AB00-1208AIJ"			
CV5408-000	NO			"TXR40AZ00-1814BI"			
CV5416-000	NO			"TXR40AZ00-2218BI"			
E24641-000	NO			"4-1200810-2", "TXR76AU00-1208AI"			
EG2466-000	NO			"BND18AB00-2216W"			
EJ0471-000	NO			"TXR40SJ00-2424AI"			
EK2357-000	NO			"228M714-19U"			

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
045865-000	NO			"5-1190352-5", "TX40AC90-1006"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206AI"			
174289-000	NO			"6-1191267-4", "TXR40AB00-2408AI"			
411147-000	NO			"8-1193100-0", "TXR41AB00-1408AI"			
451483-000	NO			"5-1193390-2", "TXR54AB00-2410BI"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406AI"			
576287-000	NO			"3-1194572-2", "TXR40AB90-2010BI"			
608335-000	NO			"7-1194811-5", "TXR40BW00-1810BI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
638627-000	NO			"1195048-6", "TX40AB90-0804"			
645057-000	NO			"9-1195094-6", "TXR41AC00-1208AI"			
675991-000	NO			"8-1195315-7", "TXR54AB90-1204BI"			
739884-000	NO			"1195775-3", "201M918-62J"			
762621-000	NO			"4-1195938-9", "TXR40AB90-1408AI"			
887445-000	NO			"5-1196904-3", "TXR54AB90-1004AI"			
902654-000	NO			"9-1197014-7", "TXR54AB00-1004AI"			
913885-000	NO			"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
952393-000	NO			"2-1197375-1", "TXR40AB90-1410BI"			
955847-000	NO			"5-1197400-6", "TXR40AB90-1608AI"			
970531-000	NO			"6-1197502-2", "TXR18AB00B3620AI"			
CB4935-000	NO			"TXR40AZ00-1004AI"			
CF4657-000	NO			"TXR41SJ00-1610AI"			
CF4658-000	NO			"TXR66SJ00-2820BI"			
CF8796-000	NO			"TXR40AB00-1604BI", "2-1899238-0"			
CP1490-000	NO			"TXR88AB00-1006AI"			
CV5404-000	NO			"TXR40AZ00-1810AI"			
CW0950-000	NO			"TXR15AZ00-2014AI"			
CW1055-000	NO			"TXR40AZ00-1404BI"			
CW1080-000	NO			"TXR40AZ00-2216BI"			
CW3905-000	NO			"TXR40AZ90-1004AI"			
CW4641-000	NO			"TXR40AZ00-1008BI"			
CZ3865-000	NO			"TXR40AZ90-1007AI"			
CZ4491-000	NO			"TXR40AZ00-1208BI"			
CZ4501-000	NO			"TX40AZ00-0804"			
EB9476-000	NO			"TXR40AZ90-1406AI"			
EG0237-000	NO			"TXR40AZ00-2006AI"			
EG1672-000	NO			"TXR40AZ00-1806BI"			
EJ0471-000	NO			"TXR40SJ00-2424AI"			
F87005-000	NO			"3-1201366-9", "TXR40SJ90-2008AI"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
045865-000	NO			"5-1190352-5", "TX40AC90-1006"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206AI"			
174289-000	NO			"6-1191267-4", "TXR40AB00-2408AI"			
262233-000	NO			"9-1191930-3", "TXR40AC90-1808AI"			
294311-000	NO			"9-1192229-8", "TXR40AC90-1607AI"			
334781-000	NO			"9-1192528-0", "202M216-19B"			
385453-000	NO			"1-1192892-8", "TXR15AB00-2424AI"			
396055-000	NO			"8-1192970-9", "TXR41AB90-1612AI"			
411147-000	NO			"8-1193100-0", "TXR41AB00-1408AI"			
421397-000	NO			"3-1193174-3", "TXR40AB00-2014AI"			
444671-000	NO			"2-1193342-2", "TXR41AB90-2412AI"			
451483-000	NO			"5-1193390-2", "TXR54AB00-2410BI"			
520935-000	NO			"8-1194094-0", "TXR40AB00-1604AI"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406AI"			
572809-000	NO			"8-1194547-6", "TXR40AB00-2216AI"			
576287-000	NO			"3-1194572-2", "TXR40AB90-2010BI"			
600577-000	NO			"3-1194752-2", "TXR40AC00-1610BI"			
638627-000	NO			"1195048-6", "TX40AB90-0804"			
641131-000	NO			"6-1195067-1", "TXR40AB00-1204BI"			
667053-000	NO			"2-1195254-5", "TXR21AB00-1205AI"			
699062-000	NO			"7-1201153-0", "TXR40SJ00-1408BI"			
757063-000	NO			"4-1195899-5", "TXR40AB00-0807AI"			
762621-000	NO			"4-1195938-9", "TXR40AB90-1408AI"			
778005-000	NO			"9-1196055-5", "TXR40AB00-1205AI"			
814229-000	NO			"9-1196336-0", "TXR54AC00-1004AI"			
832211-000	NO			"8-1196497-8", "TXR40AB45-1814AI"			
880831-000	NO			"3-1196857-1", "TXR41AB00-1410AI"			
886625-000	NO			"2-1196898-0", "TXR41AB00-2220AI"			
902654-000	NO			"9-1197014-7", "TXR54AB00-1004AI"			
913885-000	NO			"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
952393-000	NO			"2-1197375-1", "TXR40AB90-1410BI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
955847-000	NO			"5-1197400-6", "TXR40AB90-1608AI"			
970531-000	NO			"6-1197502-2", "TXR18AB00B3620AI"			
C76413-000	NO			"1-1200503-0", "TXR40SJ90-1410BI"			
CB3822-000	NO			"TXR40AB45-2006AI"			
CB4935-000	NO			"TXR40AZ00-1004AI"			
CF8796-000	NO			"TXR40AB00-1604BI", "2-1899238-0"			
CV5404-000	NO			"TXR40AZ00-1810AI"			
CW0950-000	NO			"TXR15AZ00-2014AI"			
CW3905-000	NO			"TXR40AZ90-1004AI"			
CW4641-000	NO			"TXR40AZ00-1008BI"			
CZ3865-000	NO			"TXR40AZ90-1007AI"			
CZ4491-000	NO			"TXR40AZ00-1208BI"			
CZ4501-000	NO			"TX40AZ00-0804"			
E57334-000	NO			"8-1201206-4", "TXR40AB45-1814BI"			
EG0237-000	NO			"TXR40AZ00-2006AI"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
045865-000	NO			"5-1190352-5", "TX40AC90-1006"			
150211-000	NO			"2-1191086-1", "TXR54AB00-1206AI"			
174289-000	NO			"6-1191267-4", "TXR40AB00-2408AI"			
411147-000	NO			"8-1193100-0", "TXR41AB00-1408AI"			
451483-000	NO			"5-1193390-2", "TXR54AB00-2410BI"			
554173-000	NO			"5-1194375-5", "TXR40AB00-1406AI"			
572809-000	NO			"8-1194547-6", "TXR40AB00-2216AI"			
576287-000	NO			"3-1194572-2", "TXR40AB90-2010BI"			
608335-000	NO			"7-1194811-5", "TXR40BW00-1810BI"			
638627-000	NO			"1195048-6", "TX40AB90-0804"			
645057-000	NO			"9-1195094-6", "TXR41AC00-1208AI"			
675991-000	NO			"8-1195315-7", "TXR54AB90-1204BI"			
739884-000	NO			"1195775-3", "201M918-62J"			
762621-000	NO			"4-1195938-9", "TXR40AB90-1408AI"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
832211-000	NO			"8-1196497-8", "TXR40AB45-1814AI"			
902654-000	NO			"9-1197014-7", "TXR54AB00-1004AI"			
913885-000	NO			"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
952393-000	NO			"2-1197375-1", "TXR40AB90-1410BI"			
955847-000	NO			"5-1197400-6", "TXR40AB90-1608AI"			
970531-000	NO			"6-1197502-2", "TXR18AB00B3620AI"			
CB4935-000	NO			"TXR40AZ00-1004AI"			
CF4657-000	NO			"TXR41SJ00-1610AI"			
CF4658-000	NO			"TXR66SJ00-2820BI"			
CF8796-000	NO			"TXR40AB00-1604BI", "2-1899238-0"			
CP1490-000	NO			"TXR88AB00-1006AI"			
CV5404-000	NO			"TXR40AZ00-1810AI"			
CW0950-000	NO			"TXR15AZ00-2014AI"			
CW1055-000	NO			"TXR40AZ00-1404BI"			
CW1080-000	NO			"TXR40AZ00-2216BI"			
CW3905-000	NO			"TXR40AZ90-1004AI"			
CW4641-000	NO			"TXR40AZ00-1008BI"			
CZ3865-000	NO			"TXR40AZ90-1007AI"			
CZ4491-000	NO			"TXR40AZ00-1208BI"			
CZ4501-000	NO			"TX40AZ00-0804"			
CZ9647-000	NO			"TXS201AX00-2418"			
EB9476-000	NO			"TXR40AZ90-1406AI"			
EB9526-000	NO			"TXR54AZ90-0804AI"			
EG0237-000	NO			"TXR40AZ00-2006AI"			
EG1672-000	NO			"TXR40AZ00-1806BI"			
EJ0471-000	NO			"TXR40SJ00-2424AI"			
F87005-000	NO			"3-1201366-9", "TXR40SJ90-2008AI"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
069359-000	NO			"9-1190521-6", "201M128-19C"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
140070-000	NO		RAY140070-000	"6-1191015-3", "203M016-19B10"			
152201-000	NO			"1191100-9", "TXR54AB00-1812BI"			
167451-000	NO		RAY167451-000	"1-1191219-9", "STXR40AB00-1210AI"			
224077-000	NO			"8-1191650-5", "TXR40AB90-1005AI"			
252406-000	NO			"3-1199929-9", "TXS104AB00-1005AI"			
256493-000	NO			"1191877-3", "STXR41AB00-1210AI"			
278451-000	NO			"6-1192061-5", "TXR54AB00-2214AI"			
301227-000	NO			"1-1192282-2", "TXR40BW00-0804AI"			
334781-000	NO			"9-1192528-0", "202M216-19B"			
347583-000	NO			"7-1192615-6", "TXR40BW00-2014AI"			
355597-000	NO		RAY355597-000	"5-1192669-9", "TXR40BW00-1812AI"			
421397-000	NO		RAY421397-000	"3-1193174-3", "TXR40AB00-2014AI"			
440177-000	NO			"1193309-6", "TXR41AB00-2212AI"			
443143-000	NO			"204M116-19B04-40", "1193331-4"			
447297-000	NO			"3-1193361-8", "TXR76AB00-1605AI"			
481087-000	NO			"1-1193601-8", "TXR76AB00-1204AI"			
495693-000	NO			"4-1193707-2", "TXR41AB00-1410BI"			
535325-000	NO		RAY535325-000	"2-1194203-3", "TXR41AB00-1608AI"			
540553-000	NO			"2-1194240-1", "TXR40AC00-2414AI"			
554173-000	NO		RAY554173-000	"5-1194375-5", "TXR40AB00-1406AI"			
572809-000	NO			"8-1194547-6", "TXR40AB00-2216AI"			
621387-000	NO			"9-1194910-8", "TXR76AB00-1405AI"			
671613-000	NO			"9-1195284-0", "TXR40AC00-1210AI"			
697581-000	NO		RAY697581-000	"1195475-3", "TXR41AB00-1607AI"			
778005-000	NO		RAY778005-000	"9-1196055-5", "TXR40AB00-1205AI"			
808656-000	NO			"3-1196279-2", "201M122-19C"			
812043-000	NO		RAY812043-000, RAYTXR40AB00-1810BI	"9-1196316-4", "TXR40AB00-1810BI"			
826827-000	NO			"3-1196458-7", "TXR40SJ00-1007AI"			
864163-000	NO			"3-1196730-8", "TXR40BW00-1408AI"			
913885-000	NO		RAY913885-000	"8-1197095-4", "TXR40AB00-1812AI"			
931957-000	NO			"5-1197223-3", "TXR40AB00-2414AI"			
982603-000	NO			"204M010-19B04-40", "1-1197592-5"			
AAF2661-00	NO			"TXR40AB00-1408AIJ"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
C73862-000	NO		RAYC73862-000	"6-1200810-6", "TXR40AU00-1006AI"			
CA7140-000	NO			"TXR40BW00-2216AI", "5-1899129-3"			
CF0470-000	NO			"5-1899165-3", "STXR40BW00-0805AI"			
CF0573-000	NO		RAYCF0573-000	"STXR40BW00-1210AI", "1-1899174-4"			
CF7703-000	NO			"TXR40AB00-1208AIJ"			
CV5408-000	NO			"TXR40AZ00-1814BI"			
CV5416-000	NO			"TXR40AZ00-2218BI"			
E24641-000	NO			"4-1200810-2", "TXR76AU00-1208AI"			
EG2466-000	NO			"BND18AB00-2216W"			
EJ0471-000	NO			"TXR40SJ00-2424AI"			
EK2357-000	NO			"228M714-19U"			