



# Product Change Notification

Current Date: 16-Nov-2020

## TE Connectivity

**Product Change Notification:** P-20-020034

**PCN Date:** 16-NOV-20

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Power F-A Relay - Cover mold replacement

**Description of Changes**

Dear Customer, Please note that PCN P-20-019921 was done by mistake. Please ignore it. Please find following the correct information. sorry for the confusion Within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we hereby inform you upfront about a tool replacement for Power F-A Shrouded Cover to continuously meet all specification requirements. This PCN is for information purposes only, with no need to release this change

**Reason for Changes:**

Product improvement.

**Estimated Dates:**

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-JAN-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414121-0</a>	NO						
<a href="#">1-1414122-0</a>	NO						
<a href="#">1-1414552-0</a>	NO						



# Product Change Notification

Current Date: 16-Nov-2020

## TE Connectivity

Product Change Notification: P-20-020034

PCN Date: 16-NOV-20

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Power F-A Relay - Cover mold replacement

### Description of Changes

Dear Customer, Please note that PCN P-20-019921 was done by mistake. Please ignore it. Please find following the correct information. sorry for the confusion Within our ongoing efforts to optimize our product portfolio throughout the lifecycle, we hereby inform you upfront about a tool replacement for Power F-A Shrouded Cover to continuously meet all specification requirements. This PCN is for information purposes only, with no need to release this change

### Reason for Changes:

Product improvement.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	01-JAN-2021
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	No Mixed Shipments

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1414121-0</a>	NO		TYC1-1414121-0				
<a href="#">1-1414122-0</a>	NO		TYC1-1414122-0				
<a href="#">1-1414552-0</a>	NO		TYC1-1414552-0				