



25-Feb-2021

PCN #:P-21-020510

Subject:Stamping reel label Layout and QR Code& Barcode information change

Description of Change: TE Suzhou label Layout optimize and QR Code & Barcode optimize Barcode change to LT(3S) CODE QR code change to Part Number+ Package QTY+ PO Number+ Ver +date code+ Serial Number (0001~9999) This label change Not accept re-submit PPAP/PSW request

Reason: New [specification.TE](#) Suzhou Process Label scan system update

Key Dates:

Contact By Date:25-Feb-2021

Implementation Date:25-Feb-2021

Product Affected Alias Part Number

175180-1
1-1924727-4
1564852-1
929025-1
7-1452653-1
5-963715-1
1241380-1
1241396-1
2050986-1
2-1813018-2
1-1456968-1
1241390-1
927824-2
927774-1
5-968220-1

Product Affected	Alias Part Number
2-2208928-1	
1670146-1	
1418884-1	
2050862-1	
927831-1	
2-964302-1	
1241608-1	
1827012-1	
1-1456841-4	
964280-2	
1376039-1	
7-1452668-1	
964274-2	
2035334-8	
1-1924727-3	
929939-1	"CF0548-000", "AMP-0-0929939-1", "60.349.00"
967542-2	
7-1452671-1	
2236700-1	
927766-3	"AMP-0-0927766-3", "E17312-000"
1241730-2	
927771-1	
927829-1	
1-968855-1	"8202612100"
1717172-1	
1813018-3	
968903-1	
770520-1	
1376039-5	
5-1241608-1	
1-2098753-3	
1123653-1	
5-963716-1	
1241402-1	
1418758-1	
927829-2	
2035334-4	
144969-1	
2293362-1	
964284-2	

Product Affected	Alias Part Number
316838-1	
2-964294-1	
1862006-1	
927831-4	
316836-1	"0-0316836-1"
2035334-7	
929025-2	
282439-1	
2035334-2	
1-1456968-8	
1670144-3	
927829-5	
962874-1	
1418406-1	
1241858-2	
967541-1	
2035334-6	
927768-1	
964267-2	
964348-2	
5-1418758-1	
969005-2	
7-1452665-1	
968903-3	
2825197-1	
7-1452665-3	
2294463-2	
1564980-1	
2050986-3	
2050862-3	
927831-2	
1-963863-0	
282110-1	
965999-2	
927823-1	
2294463-3	
967543-2	
7-1452656-3	
1418844-1	
1-1456841-2	

Product Affected	Alias Part Number
1-1456841-5	
1241388-1	
1670144-1	
927824-1	
964273-1	
1241378-1	
968221-1	
1241404-1	
964269-2	
929027-3	
1-1456841-7	
927831-5	
2050862-2	
2-1813018-1	
C00123-001	"2-1201541-3", "927771-3"
964273-2	
282438-1	
2341174-1	
144969-4	
1670146-3	
927827-2	
1-1924727-1	
1379419-1	
1123343-1	"EM3607-000", "AMP-0-1123343-1"
1813018-6	
2035334-3	
927827-1	
1564324-1	
1813018-4	
5-928999-1	
1-2098753-1	
1418408-1	
929024-1	
963715-1	
927771-6	
2141824-1	
1241394-1	
2035334-5	
2-963863-0	
6-928918-1	

Product Affected**Alias Part Number**

967543-1

928998-1

2035334-1

1-1456841-8

2-1813018-3

1703414-1

5-928999-5

2-964300-1

7-1452671-3

2-927768-1

967543-3

929027-2

2141882-2

929939-6

1813018-1

1534334-1

967542-1

962876-3

1-2208928-1

1534594-1

1-1456841-1

1241372-1

928999-1

"0-0928999-1", "0-928999-1"

968220-1

1-927771-1

1813018-5

927768-3

"0-0927768-3"

776001-1

5-968221-1

929027-1

2141826-1

2-964296-1

927774-3

964261-2

1717366-2

1-2098753-4

965929-1

1-1456968-4

1813018-2

1241406-1

Product Affected	Alias Part Number
964263-2	
1-968857-1	
7-1452653-3	
929939-3	
1-968000-1	
7-1452656-1	
927771-3	"0-0927771-3"
965998-1	
2297494-1	
962876-5	
929024-2	
964286-2	
1-1456968-3	
1-1456968-2	
1-1456841-6	
7-1452668-3	
173681-1	
964265-2	
927767-1	
2294463-1	
144969-2	
1-1456841-3	
1241374-1	
1717366-1	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.