



01-Apr-2021

PCN #:P-21-020704

Subject:Micro A relay. Additional production source of specified contact rivet.

Description of Change: Dear customer, due to the COVID-19 epidemic, our contact rivet supplier (Doduco Spain) has insufficient supply capacity, so we inform you in advance that we have approved an additional second source outside the EMEA area (Doduco China) to protect and assure TE capability to meet our customer demands. The supplier, the contact rivet and the contact rivet material itself remain unchanged and the additional source will be utilized as alternative in case of supply shortages locally.

Reason: Document clarification. Additional production source of the specified contact rivet.

Key Dates:

Contact By Date:05-Apr-2021

Implementation Date:05-Apr-2021

Product Affected	Alias Part Number
2359393-1	"V23074A2001A402"
6-1393292-3	"V23074A2002A403"
4-1904124-3	
5-1393292-8	"V23074A2001A402"
2359392-1	"V23074-A1002-A402"
6-1419137-4	"V23074A2001A403"
4-1904124-2	
3-1393292-8	"V23074A1002A403"

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.