



22-Apr-2021

PCN #:PCN-21-102441

Subject:776523-1 AMPSEAL 16 3P Plug New Manual Assembly Line

Description of Change: The Industrial and Commercial Transportation business unit of TE Connectivity is adding an additional hand assembly line at the current manufacturing location. This change is for the following part number(s). PPAP requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

Reason: Dear Customer, we hereby inform you of this change. This change is necessary due to capacity constraints. The change will not impact connector performance. This new assembly line is in the same location as the current line and follows all TE quality standards **IMPORTANT:** The parts from either line can be used interchangeably in the field. Shipments of both configurations may be mixed. These parts will be identified with the marking of L2 (LINE 2) below date code for traceability purpose.

Key Dates:

Contact By Date:04-May-2021

Implementation Date:04-May-2021

Product Affected	Alias Part Number
-------------------------	--------------------------

776523-1	
----------	--

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.