



Product Change Notification

Current Date: 26-Apr-2021

TE Connectivity

Product Change Notification: P-21-020805

PCN Date: 23-APR-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

HCR relay: Alternative contact rivet supplier

Description of Changes

Dear customer, due to the COVID-19 epidemic, our contact rivet supplier (Doduco Spain) has insufficient supply capacity, so we inform you in advance that we intend to use contact rivets from an alternative supplier (Tanaka Japan) to protect and assure TE capability to meet our customer demands. Tanaka contact rivets are approved to be used in HCR relays and are used in ~65% of all HCR relays produced. We intend to use Tanaka contact rivets during the shortage of Doduco rivets. This PCN is intended to only inform you with no need to release the change, we are at your disposal to clarify any doubt.

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

24-APR-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393315-1	NO			"V23132B2002B200"			
1393315-2	NO			"V23132A2001A200"			
1393315-9	NO			"V23132B2002A200"			
1416010-1	NO			"V23132-A2001-B200"			
9-1415001-5	NO			"CZ1474-000"			



Product Change Notification

Current Date: 26-Apr-2021

TE Connectivity

Product Change Notification: P-21-020805

PCN Date: 23-APR-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

HCR relay: Alternative contact rivet supplier

Description of Changes

Dear customer, due to the COVID-19 epidemic, our contact rivet supplier (Doduco Spain) has insufficient supply capacity, so we inform you in advance that with intend to use contact rivets from an alternative supplier (Tanaka Japan) to protect and assure TE capability to meet our customer demands. Tanaka contact rivets are approved to be used in HCR relays and are used in ~65% of all HCR relays produced. We intend to use Tanaka contact rivets during the shortage of Doduco rivets. This PCN is intended to only inform you with no need to release the change, we are at your disposal to clarify any doubt.

Reason for Changes:

Document clarification.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	24-APR-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393315-1	NO		TYC1-1393315-1	"V23132B2002B200"			
1393315-2	NO			"V23132A2001A200"			
1393315-9	NO		TYC1393315-9	"V23132B2002A200"			
1416010-1	NO		TYC1416010-1	"V23132-A2001-B200"			
9-1415001-5	NO		TYC9-1415001-5	"CZ1474-000"			