



Product Change Notification

Current Date: 26-Apr-2021

TE Connectivity

Product Change Notification: P-21-020808

PCN Date: 23-APR-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change - Hermosillo MX

Description of Changes

The Data and Devices business unit of TE Connectivity (TE) is moving its current manufacturing site in Hermosillo, MX to a new manufacturing site in the same city of Hermosillo, MX. The new site is only approximately 3.5 mi (equivalent to approximately 5 km) away from the current site. We plan to migrate all the existing manufacturing equipment relating to the products listed below from our current site to the new site. Please contact your TE Account Manager with questions.

Reason for Changes:

Hermosillo, MX is a key manufacturing site serving our customer s needs in the Americas and globally. To expand our footprint, increase manufacturing flexibility, and integrate core processes, TE will be moving the products outlined herein to a new manufacturing site.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

01-OCT-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

31-MAR-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-330311-1	NO						
2-5745174-7	NO						
2-747579-7	NO		TYC2-747579-7				
3-1393670-9	NO		TYC3-1393670-9	"V23600A1227G 1", "V23600A1227G1"			
3-747579-2	NO		TYC3-747579-2	"E98969-000", "AMP-3-0747579-2"			
4-745130-0	NO		TYC4-745130-0				
4-745130-1	NO		TYC4-745130-1				
414026-3	NO		TYC414026-3				
51421-2	NO						
5205817-1	NO		TYC5205817-1				
5205817-3	NO		TYC5205817-3, 5911857-1	"673-1082-01"			
5205980-1	NO		TYC5205980-1	"2-30351-0010", "1185341"			
5205980-5	NO		TYC5205980-5				
5206471-1	NO						
5206514-1	NO		4081026-0701, TYC5206514-1				
5206514-4	NO						
5207719-3	NO		5727584-7, TYC5207719-3				
5222092-1	NO		TYC5222092-1	"2-42936-9569"			
5227161-1	NO		TYC5227161-1				
5227161-3	NO		TYC1060989-1, TYC5227161-3	"1363579"			
5227161-6	NO		TYC5227161-6				
5227161-7	NO		TYC5227161-7				
5227161-9	NO		TYC5227161-9				
5227222-2	NO		TYC5227222-2				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5227426-1	NO		TYC5227426-1				
5227661-1	NO		TYC5227661-1				
5227673-1	NO		TYC5227673-1				
5227676-1	NO		TYC5227676-1, TC5227676-1				
5227677-1	NO		TYC5227677-1				
5227818-1	NO						
5227839-1	NO		TYC5227839-1				
5413194-1	NO		TYC5413194-1				
5413515-2	NO		TYC5413515-2				
5413558-1	NO		TYC5413558-1				
5413589-8	NO		TYC5413589-8				
5413631-1	NO		TYC5413631-1				
5413771-3	NO		TYC5413771-3				
5413879-1	NO		TYC5413879-1				
5413969-2	NO		TYC5413969-2				
5745007-1	NO		TYC5745007-1	"2-42934-2773"			
5745171-5	NO		TYC5745171-5				
5745172-1	NO		TYC5745172-1				
5745172-2	NO		TYC5745172-2				
5745173-4	NO		TYC5745173-4	"4-36001-0619"			
5745174-5	NO		TYC5745174-5				
5745175-5	NO						
5745652-2	NO		TYC5745652-2				
5745652-3	NO		TYC5745652-3				
5745781-6	NO		TYC5745781-6				
5745783-3	NO						
5745967-2	NO		TYC5745967-2				
5747150-2	NO		TYC5747150-2				
5747150-8	NO		TYC5747150-8				
5747301-8	NO		TYC5747301-8				
5747461-1	NO						
5747467-4	NO		TYC5747467-4, TYC574767-4				



Product Change Notification

Current Date: 26-Apr-2021

TE Connectivity

Product Change Notification: P-21-020808

PCN Date: 23-APR-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Manufacturing Location Change - Hermosillo MX

Description of Changes

The Data and Devices business unit of TE Connectivity (TE) is moving its current manufacturing site in Hermosillo, MX to a new manufacturing site in the same city of Hermosillo, MX. The new site is only approximately 3.5 mi (equivalent to approximately 5 km) away from the current site. We plan to migrate all the existing manufacturing equipment relating to the products listed below from our current site to the new site. Please contact your TE Account Manager with questions.

Reason for Changes:

Hermosillo, MX is a key manufacturing site serving our customer s needs in the Americas and globally. To expand our footprint, increase manufacturing flexibility, and integrate core processes, TE will be moving the products outlined herein to a new manufacturing site.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-OCT-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-MAR-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2-330311-1	NO						
2-5745174-7	NO						
2-747579-7	NO		TYC2-747579-7				
3-1393670-9	NO		TYC3-1393670-9	"V23600A1227G 1", "V23600A1227G1"			
3-747579-2	NO		TYC3-747579-2	"E98969-000", "AMP-3-0747579-2"			
4-745130-0	NO		TYC4-745130-0				
4-745130-1	NO		TYC4-745130-1				
414026-3	NO		TYC414026-3				
51421-2	NO						
5205817-1	NO		TYC5205817-1				
5205817-3	NO		TYC5205817-3, 5911857-1	"673-1082-01"			
5205980-1	NO		TYC5205980-1	"2-30351-0010", "1185341"			
5206471-1	NO						
5206514-1	NO		4081026-0701, TYC5206514-1				
5206514-4	NO						
5207719-3	NO		5727584-7, TYC5207719-3				
5222092-1	NO		TYC5222092-1	"2-42936-9569"			
5227161-1	NO		TYC5227161-1				
5227161-3	NO		TYC1060989-1, TYC5227161-3	"1363579"			
5227161-7	NO		TYC5227161-7				
5227161-9	NO		TYC5227161-9				
5227222-2	NO		TYC5227222-2				
5227426-1	NO		TYC5227426-1				
5227661-1	NO		TYC5227661-1				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5227673-1	NO		TYC5227673-1				
5227676-1	NO		TYC5227676-1, TC5227676-1				
5227677-1	NO		TYC5227677-1				
5227818-1	NO						
5227839-1	NO		TYC5227839-1				
5413194-1	NO		TYC5413194-1				
5413515-2	NO		TYC5413515-2				
5413558-1	NO		TYC5413558-1				
5413589-8	NO		TYC5413589-8				
5413631-1	NO		TYC5413631-1				
5413771-3	NO		TYC5413771-3				
5413879-1	NO		TYC5413879-1				
5413969-2	NO		TYC5413969-2				
5745007-1	NO		TYC5745007-1	"2-42934-2773"			
5745171-5	NO		TYC5745171-5				
5745172-1	NO		TYC5745172-1				
5745172-2	NO		TYC5745172-2				
5745173-4	NO		TYC5745173-4	"4-36001-0619"			
5745652-2	NO		TYC5745652-2				
5745652-3	NO		TYC5745652-3				
5745783-3	NO						
5745967-2	NO		TYC5745967-2				
5747150-2	NO		TYC5747150-2				
5747150-8	NO		TYC5747150-8				
5747301-8	NO		TYC5747301-8				
5747461-1	NO						
5747467-4	NO		TYC5747467-4, TYC574767-4				