



17-Jun-2021

PCN #:P-21-021084

Subject:PLUG ASSY, KEY A, TA, HVA280-2PHI XE

Description of Change: TE is building a second mold capacity for peripheral seal- HVA280 header p/n (1587719-1) used in the plug assembly HVA280 part numbers listed on the next tab. This peripheral seal mold will be located at an outside supplier. No change to finished good shipping location. No change to fit, form or function. Addendum of PCN P-21-020883

Reason: Product improvement.Increase capacity to meet customer demand.
Addendum of PCN P-21-020883

Key Dates:

Contact By Date:21-Aug-2021

Implementation Date:21-Aug-2021

Product Affected	Alias Part Number
-------------------------	--------------------------

2103744-1	
2103177-5	
2103628-1	
4-2103015-6	
2103628-2	
2103385-4	
1587819-1	
1587819-4	
4-2103350-2	
4-2840548-2	
5-2103177-1	
4-2103015-1	
2294430-5	
1587902-2	

Product Affected	Alias Part Number
1587715-2	
2103534-5	
2103628-5	
2103149-2	
2103744-6	
4-2840548-1	
2103149-7	
2103628-6	
1-2103177-1	
2103628-7	
4-2103350-1	
4-2103350-4	
1-2103744-1	
2103534-1	
2103534-4	
4-2103177-4	
2103149-1	
2103177-2	
2103628-4	
2294430-1	
2103744-5	
5-2103177-4	
4-2103177-2	
2177376-1	
4-2103350-5	
4-2103177-6	
4-2103015-4	
4-2103177-1	
2103534-2	
4-2103177-5	
1-2103177-4	
2103744-2	
4-2103015-5	
2103149-4	
1587715-1	
1587819-2	
4-2103015-2	
4-2103177-7	
2103177-1	
6-2103177-4	

Product Affected	Alias Part Number
2103177-4	
4-2103587-2	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.