



25-Jun-2021

PCN #:E-21-006539

Subject:CPC Connector Housings

Description of Change: Change the method of marking the part number, date code and country of manufacture on these housings from white ink stamping to laser marking. This change only impacts the following parts: 206036-5, 1-206036-4, 206061-2, 206061-8, 206153-2, 206430-3, 206430-4.

Reason: Manufacturing / Process Requirements. The tooling used to white ink stamp is damaged and unable to be repaired or replaced. For this reason the changes needs to be implemented immediately.

Key Dates:

Contact By Date:05-Jul-2021

Implementation Date:05-Jul-2021

| Product Affected | Alias Part Number |
|-------------------------|---|
| 206153-2 | |
| 206036-4 | |
| 206430-2 | "5011473", "CL0834-000", "JOR-06588" |
| 206036-8 | |
| 206061-1 | |
| 206036-2 | |
| 206036-1 | "C21176-000", "DUL-RECPT-SZ-17-16-CPC" |
| 206061-2 | |
| 206430-3 | |
| 206036-7 | |
| 206153-1 | "926370-000", "LTRW-AMP-206153-1", "0-0206153-1" |
| 206430-1 | |
| 206430-4 | |

| Product Affected | Alias Part Number |
|-------------------------|----------------------------------|
| 206061-3 | |
| 206036-3 | "A76356-000", "AMPS-0-0206036-3" |
| 206036-5 | |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE

Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.