



29-Jun-2021

**PCN #:**PCN-21-105391

**Subject:**DEUTSCH DT Series 2,3,4,6,12 Position Assembly Process and Packaging Change

**Description of Change:** The Industrial and Commercial Transportation business unit of TE Connectivity is upgrading the automated assembly machines for the part number(s) listed below. The new equipment's laser will improve the legibility on the cavity ID marking. The affected parts packaging will change to the standard automotive AIAG shape and size boxes with dimensions LxWxH 15.375x9.5x8.563 inches. Standard Package Quantity will not change. Product drawings are not affected. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via [ict-ppap-request@te.com](mailto:ict-ppap-request@te.com) or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved.

**Reason:** Dear Customer, we hereby inform you of this change. The change is necessary to improve the operating efficiency and to standardize packaging in the current manufacturing location. The change does not impact connector performance. **IMPORTANT:** The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

**Key Dates:**

**Contact By Date:**18-Sep-2021

**Implementation Date:**18-Sep-2021

**Product Affected**                      **Alias Part Number**

DT04-4P-E005

DT04-3P-EE01

DT06-12SC-C017

**Product Affected****Alias Part Number**

DT06-3S-PE01

DT06-12SA-CE06

DT04-12PC-CE08

DT06-4S-CP01

DT06-12SB

DT06-4S-C017

DT06-12SB-CE05

DT06-12SD-C017

DT04-4P-E008

DT06-12SB-C017

DT04-12PC

DT06-6S-E003

DT04-2P-CE01

DT04-2P-CE09

DT04-12PB-E003

DT06-3S-CE01

DT04-4P-E004

DT04-12PA-CE08

DT06-12SC-P012

DT06-4S

"2-1899779-3", "EH7682-000", "DE-DT06-4S",  
"8202606747"

DT04-3P-C015

DT04-6P-CE02

DT06-12SA-E003

DT04-12PA-E008

DT04-2P-CE03

DT04-12PA-CE07

DT04-12PB-CE08

DT06-12SD-P012

DT06-12SB-CE13

DT06-12SC-CE01

DT06-12SC-CE04

DT06-12SA-CE05

DT06-12SA-C015

DT06-4S-EP06

DT06-6S-CE01

DT06-12SD-EP04

DT04-6P-CE01

DT04-12PB-C015

DT04-12PB-CE01

<b>Product Affected</b>	<b>Alias Part Number</b>
DT06-6S-L019	
DT04-4P-CE09	
DT06-6S-C017	
DT04-2P-EE01	
DT04-12PD-CE07	
DT04-12PB-CE07	
DT06-12SC-CE05	
DT06-6S-P004	
DT06-12SB-EP04	
DT06-4S-CE15	
DT06-4S-C015	
DT04-6P-P004	
DT06-12SA-CE13	
DT06-3S-CE05	
DT04-12PC-BE03	
DT06-12SB-E003	
DT06-4S-CE13	
DT06-12SC-CE13	
DT04-12PA-P004	
DT06-2S-CE13	
DT04-12PD-P004	
DT06-4S-EP04	
DT04-12PD-EP04	
DT04-6P-E003	
DT06-4S-E004	
DT06-3S-EF01	
DT06-12SB-P012	
DT06-3S-E008	
DT06-4S-CE05	
DT04-6P-C015	
DT06-3S-CE04	
DT06-3S-EP04	
DT06-12SD-CE05	
DT06-12SA-EP04	
DT06-12SA-EP20	
DT06-3S-EP09	
DT04-12PD-B016	
DT04-12PA-CE09	
DT06-2S-CE05	
DT04-12PD-C017	

<b>Product Affected</b>	<b>Alias Part Number</b>
DT04-12PA-E004	"ZPF000000000141220"
DT06-6S-CE02	
DT06-3S-CE14	
DT06-2S-CE04	"8202614114"
DT04-3P-E004	
DT06-2S-EP04	
DT06-12SD	
DT06-6S-E004	
DT06-4S-EP11	
DT04-12PA-E005	
DT06-4S-P004	
DT06-12SB-B016	
DT06-6S-P012	"ZPF000000000141218"
DT06-3S-CP01	
DT06-12SB-CE01	
DT04-12PA-CE03	
DT06-12SC-B016	
DT06-2S-EE05	
DT04-6P-E008	
DT06-12SD-EP06	
DT06-12SD-C015	"ZPF000000000130712"
2323768-4	"DT04-12PD-CE04"
DT06-2S-EP06	
DT04-12PC-B016	
DT04-2P-E008	
DT04-12PA-B016	
DT06-4S-CE06	
DT04-4P-CE03	
DT06-2S-EP11	
DT04-3P-E005	"8202612556"
DT04-6P-E005	
DT04-6P-CE09	
DT06-6S	"6-1899776-2"
DT04-12PA-BE03	"9-1899838-2"
DT06-12SA	
DT06-12SC	
DT04-12PB-P004	
DT04-2P-E005	
DT06-2S-FP02	
DT06-3S-EP06	

<b>Product Affected</b>	<b>Alias Part Number</b>
DT06-12SA-CE11	
DT04-2P-EP04	
DT04-12PB-EP04	
DT06-6S-E008	
DT06-2S-E008	
DT04-3P-CE02	"73000933-F"
DT06-3S-EF02	
DT04-6P-CE03	
DT06-6S-LC01	
DT06-4S-P012	
DT04-12PA	
DT06-12SB-CE06	
DT04-12PD-C015	
DT06-6S-CE05	
DT06-12SB-E008	
DT04-4P-EE01	
DT06-4S-E008	
DT06-3S-EP11	
DT04-12PD-BE02	
DT06-2S-C017	
DT06-12SA-CE10	"ZPF000000000146119"
DT06-3S-EP05	
DT06-12SA-EP07	"ZPF000000000141219"
DT04-12PC-CE07	
DT04-12PC-C015	
DT04-12PC-BE02	
DT04-12PD-E003	
DT06-3S-E005	
2323768-2	"DT04-12PB-CE04"
DT06-2S-EF01	
DT04-2P-C017	
DT06-12SD-CE13	
DT06-12SC-CE06	
DT06-6S-E005	
DT04-4P	
DT06-3S-CE13	
DT06-3S-P032	
DT06-12SD-CE06	
DT04-12PA-CE02	"ZPF000000000146116"
DT04-4P-E003	

<b>Product Affected</b>	<b>Alias Part Number</b>
DT06-4S-CE02 2323768-3	"DT04-12PC-CE04"
DT06-12SB-CE04 DT04-3P	
DT04-12PA-BE02 DT04-4P-B033	
DT04-4P-CE02 DT06-3S-C017	
DT06-12SA-E008 DT06-2S-E005	
DT06-12SB-P004 DT04-4P-C017	
DT04-3P-CE04	"8202608246"
DT04-12PA-C017 DT04-12PA-CE01	
DT04-12PB-B016 DT06-3S-PP01	
DT04-12PC-P004 DT06-12SA-CE12	
DT04-12PC-CE01 DT06-12SC-E003	
DT04-12PC-EP04 DT06-12SA-CE04	
DT04-12PB-C017 DT06-4S-E005	
DT06-12SA-EP08 DT06-2S-LC01	
DT06-3S-EP10 DT06-4S-LC01	
DT06-12SA-P004 DT04-3P-EP04	
DT04-2P-E003 DT04-4P-EP13	"5-1899776-9"
DT06-3S-E003 DT04-12PD	
DT06-12SC-P004 DT06-2S-CE01	
DT06-2S-E003 DT06-12SA-B016	
DT04-6P-EP04	

<b>Product Affected</b>	<b>Alias Part Number</b>
DT06-2S-CE06	"ZPF000000000140939", "820P-37546"
DT06-12SC-EP06	
DT04-12PC-E003	
DT04-6P-E004	
DT04-4P-EP04	
DT04-4P-P021	
DT06-3S-P006	"6-1899776-0"
DT06-12SD-E003	
DT06-12SA-CE01	
DT06-6S-EP11	
DT04-12PA-CE04	
DT06-6S-EP06	
DT04-4P-CE04	"820E-37521", "4004200319"
DT04-4P-CE01	
DT04-12PA-E003	
DT04-12PA-C015	
DT06-12SA-CE02	
DT04-12PA-EP04	
DT04-12PC-C017	
DT06-6S-EP04	
DT06-12SA-EP06	
DT06-4S-CE04	
DT06-12SB-C015	"ZPF000000000130692"
DT06-12SA-C017	
DT04-6P	
DT06-12SC-EP04	
DT06-4S-E003	
DT06-12SB-EP06	
DT06-12SC-C015	
DT04-3P-CE09	
DT04-12PB	
DT04-3P-CE03	
DT04-12PB-BE02	
DT04-4P-C015	
DT04-3P-CE01	
DT06-12SD-B016	
DT06-6S-C015	
DT06-12SA-CE08	
DT04-12PA-BE04	
DT06-6S-CE06	

<b>Product Affected</b>	<b>Alias Part Number</b>
DT06-4S-CE01	
DT04-4P-P004	
DT04-3P-E008	"5000634"
DT06-12SA-E005	
DT04-6P-C017	
DT06-2S-CE03	
DT04-3P-E003	
DT04-2P-CE04	
DT06-12SA-P012	
DT06-12SD-CE04	"ZPF000000000130709"
DT06-12SD-P004	



The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.