



01-Jul-2021

PCN #:PCN-21-106312

Subject:DEUTSCH HDP, DRC and DT16 Retainer New Capacity Tooling

Description of Change: The Industrial and Commercial Transportation business unit of TE Connectivity is adding new capacity tooling for retainers for the part number(s) listed below. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawings are not affected.

Reason: Dear Customer, we hereby inform you of this change. The new tooling is necessary improve our production capacity. The added tooling does not impact connector performance. **IMPORTANT:** No fit, form, or function change. Parts off the new tool are identical to current production. Shipments from current and new tooling configurations may be mixed.

Key Dates:

Contact By Date:07-Jul-2021

Implementation Date:07-Jul-2021

Product Affected	Alias Part Number
HDP26-24-31SE-L015	"ZPF000000000131156", "HDP26-24-31SE-L015LS", "6-1899768-0", "HDP26-24-31SE-L015-L"
HD36-18-14SN-072	"ZPF000000000130788", "HD36-18-14SN-072-RU"
HD10-9-96PE-B009	
HD36-18-14PN-072	
DRC26-60S08	"ZPF000000000131386"
HD34-24-23PN-L005	
HDP24-24-31PE-L017	"ZPF000000000131139", "HDP24-24-31PE-L017LD", "HDP24-24-31PE-L017LS", "5-1899768-4", "HDP24-24-31PE-L017-L"

Product Affected	Alias Part Number
HD36-24-31ST-072 DT16-18SB-K004	"ZPF000000000131184"
HD36-24-23SN-072 HD36-18-14SN-C014 HD36-24-23SN-L006 DRC26-50S04-C031	"ZPF000000000131077", "7-1899816-3"
YHDP26-24-23SEL024	"HDP26-24-23SE-L024"
HD36-24-31ST-L006	"HD36-24-31ST-L006-RU"
HD10-9-1939P	"ZPF000000000130529", "HD10-9-1939P-AS", "HD10-9-1939P-MS"
DRC22-40PA	
HD34-24-23PE	"ZPF000000000131044", "\$\$HD34-24-23PE"
HD36-24-23SE-072	"ZPF000000000131074", "HD36-24-23SE-072-RU", "2-1899806-9"
DRC26-60S04	"ZPF000000000131382"
HDP26-24-31PT-L017	"ZPF000000000131154", "HDP26-24-31PT- L017LS", "4-1899772-1", "HDP26-24-31PT-L017-L"
DRC26-50S08-C031	
HDP26-24-23PT-L015	"ZPF000000000131033"
HDP26-18-14SE	"ZPF000000000130758", "HDP26-18-14SE-AS", "HDP26-18-14SE-LS", "HDP26-18-14SE-MS", "HDP26-18-14SE-SC", "HDP26-18-14SE-L", "HDP26-18-14SE-M", "HDP26-18-14SE-S"
YHDP26-24-23PEL024	"HDP26-24-23PE-L024"
DRC26-50S03	"ZPF000000000131365", "DRC26-50S03-LS", "DRC26-50S03-L"
DRC26-50S07-C026	
HD34-24-23SE-072	"ZPF000000000131055"
HD34-24-23PN-072	"ZPF000000000131049", "7-1899816-2"
HDP26-24-23ST-L015	"ZPF000000000131042"
HDB36-18-14SN-072	
HDP24-18-14PE-L017	"6-1899818-2"
DRC14-40PAE	"ZPF000000000131288"
HD34-18-14SE	"ZPF000000000130771", "HD34-18-14SE-RU"
DT16-18SA-K004	
HDP24-18-14SN-L017	
HDP26-24-31SE-L017	"ZPF000000000131157", "HDP26-24-31SE- L017AS", "HDP26-24-31SE-L017LS", "8-1899770-3"

Product Affected	Alias Part Number
HD34-24-23PT-059	"ZPF000000000131051", "5-1899816-5"
HDP24-18-14PN-L017	"HDP24-18-14PN-L017RU"
DRC26-60S05	"ZPF000000000131383", "DRC26-60S05-LD", "DRC26-60S05-LS", "5-1899776-6", "DRC26-60S05-L"
HD36-24-23SE-059	"ZPF000000000131073", "6-1899779-9"
HD36-18-20SN-072	"ZPF000000000130918"
HD34-18-14SE-059	"ZPF000000000130772", "HD34-18-14SE-059-RU"
DRC12-40PC	"ZPF000000000131276", "DRC12-40PC-MS", "DRC12-40PC-RU", "DRC12-40PC-M"
HD34-24-31ST-059	"ZPF000000000131171", "HD34-24-31ST-059-RU"
DRC26-40SD-L011	
HDP24-18-20SN	
DT16-18SD-K004	
DRC14-40PC	"ZPF000000000131291"
DRC26-50S01-C026	"ZPF000000000131363"
HD34-24-31ST-072	
HDP24-24-23PT	"ZPF000000000131014", "HDP24-24-23PT-LS", "HDP24-24-23PT-MS", "HDP24-24-23PT-M", "HDP24-24-23PT-L"
HDB36-18-14SN	"ZPF000000000130748", "17096", "ZPF000000000148239"
DRC26-40SC-P017	
HD10-9-1939PE-B022	"5-1899820-7"
DRC26-50S09-C031	
HD34-24-23SN-072	"ZPF000000000131058", "4-1899818-0"
HD34-18-14PN	"ZPF000000000130764", "HD34-18-14PN-LS", "11822", "ZPF000000000148238", "\$ \$HD34-18-14PN", "HD34-18-14PN-L"
HD17-9-1939SE	"ZPF000000000130549", "HD17-9-1939SE-RU"
HD34-24-31PE-072	"ZPF000000000131163"
HD16-9-1939SE-P080	
HDB36-18-14PE 2369194-1	"ZPF000000000130744", "HDB36-18-14PE-RU" "HD34-24-31PE-B019"
DRC26-50S10-C031	
HDP26-24-23PE-L015	"ZPF000000000131027"
YHDP26-24- 31PEL024	"HDP26-24-31PE-L024"

Product Affected	Alias Part Number
HDP24-18-14SE-L017	"ZPF000000000130753", "1899836-6"
HDP26-24-31PE	"ZPF000000000131149", "HDP26-24-31PE-LS", "\$HDP26-24-31PE", "HDP26-24-31PE-L"
HD34-24-23PT-072	"ZPF000000000131052"
HDB36-24-31PT	"ZPF000000000131131"
HD34-18-20PN	"ZPF000000000130907"
DT16-6SB-KP01	
HD36-24-23PT-059	"ZPF000000000131070", "HD36-24-23PT-059-RU"
DRC26-50S04-C026	
DRC12-40PDE	"DRC12-40PDE-RU"
HDP24-24-23ST-L017	"ZPF000000000131025"
DRC26-40SB-P019	
HD34-18-14PE-059	"ZPF000000000130762", "HD34-18-14PE-059-RU"
HD17-9-1939S	"ZPF000000000130548", "HD17-9-1939S-RU"
DRC26-60S06	"ZPF000000000131384", "DRC26-60S06-LD", "DRC26-60S06-LS", "DRC26-60S06-L"
DRC26-40SC-PL01	
DRC18-40SC-PP02	
DRC12-40PA	"ZPF000000000131272", "DRC12-40PA-LD", "DRC12-40PA-LS", "DRC12-40PA-MS", "DRC12-40PA-L", "DRC12-40PA-M"
DRC16-40S	"ZPF000000000131293", "DRC16-40S-LS", "ZPF000000000146159", "DRC16-40S-L"
HDP24-24-31PT	"ZPF000000000131140", "HDP24-24-31PT-LD", "HDP24-24-31PT-LS", "HDP24-24-31PT-MS", "HDP24-24-31PT-L", "HDP24-24-31PT-M"
DT16-6SA-KP01	
DRC12-40PAE	"ZPF000000000131273", "DRC12-40PAE-MS", "DRC12-40PAE-M"
DRC18-40SC	"ZPF000000000131305", "DRC18-40SC-RU"
HD36-18-14SN-C012	
HD36-18-14SE-072	
DRC22-40PB	"DRC22-40PB-RU"
DRC18-40SB-PP02	
DRC26-50S10-C026	
HD34-18-14PT	"ZPF000000000130768"
HD36-24-31SE-072	"ZPF000000000131181", "3-1899806-1"
HDP26-18-20PN	"ZPF000000000130905"
DRC26-40SA-PL01	
DRC26-50S07	"ZPF000000000131369", "DRC26-50S07-LD", "DRC26-50S07-LS", "DRC26-50S07-L"

Product Affected	Alias Part Number
HD14-9-1939P	"ZPF000000000130537"
YHDP26-24-31SEL024	"HDP26-24-31SE-L024"
DRC26-50S08	"ZPF000000000131370", "DRC26-50S08-LD", "DRC26-50S08-LS", "DRC26-50S08-L"
HDP24-18-14SN	"ZPF000000000130754", "HDP24-18-14SN-LS", "HDP24-18-14SN-L"
DT16-18SC-EK02	
DRC26-50S09-C026	
DRC26-40SD-PL01	
HD16-9-96SE	"ZPF000000000130547"
DRC26-50S05-C027	
HD34-24-23SN-L005	
DRC22-40PD	
YHDP26-18-14SECL20	"HDP26-18-14SE-CL20"
HDP24-18-14SE	"ZPF000000000130752", "HDP24-18-14SE-LS", "HDP24-18-14SE-L"
HD36-24-31PT	"ZPF000000000131176", "HD36-24-31PT-MS"
DRC26-50S08-C026	
HDP24-24-23SN-L015	"ZPF000000000131021"
DRC18-40SD-P013	
DRC12-40PCE	"ZPF000000000131277", "DRC12-40PCE-RU"
YHD10-9-96PE-BE090	"HD10-9-96PE-BE09"
DRC26-50S05	"ZPF000000000131367", "DRC26-50S05-AS"
HDP26-24-23SE	"ZPF000000000131035", "HDP26-24-23SE-MS", "HDP26-24-23SE-SC", "HDP26-24-23SE-M", "HDP26-24-23SE-S"
DRC26-40SC-L011	
HD36-18-14PE-059	"ZPF000000000130778", "HD36-18-14PE-059-RU"
DRC26-40SA-L011	"ZPF000000000131317", "\$\$DRC26-40SA-L011"
HDP26-18-14PN	"ZPF000000000130757"
HD34-24-31SE	"ZPF000000000131167", "\$\$HD34-24-31SE"
HD34-18-14PE-072	
HD16-9-1939S	"ZPF000000000130543"
HDP24-18-14PE	"ZPF000000000130750", "HDP24-18-14PE-MS", "HDP24-18-14PE-M"
HD34-24-31PE-L005	
HD36-18-14SE-059	"ZPF000000000130784"

Product Affected	Alias Part Number
HD36-18-14PN	"ZPF000000000130780"
HDP26-24-23ST	"ZPF000000000131041", "HDP26-24-23ST-MS", "HDP26-24-23ST-M"
HD34-18-14PN-072	"ZPF000000000130766"
DRC26-60S02	"ZPF000000000131380"
HDP26-18-14PE- L015	
HD34-24-23PE-L005	
HD36-18-14PN-L005	
HD16-9-96S-C016	"ZPF000000000130546", "HD16-9-96S-C016-RU"
HD10-9-1939P-P080	"HD10-9-1939P-P080-RU"
HD36-18-14SN-H001	"ZPF000000000130789", "HD36-18-14SN-H001- RU"
HDP26-18-20SE	"HDP26-18-20SE-RU"
HD10-9-1939PE- BP03	
HDP24-24-23PT-L017	"ZPF000000000131016"
HD36-18-14PN-L006	
HDP26-18-14PE	"ZPF000000000130755"
2294482-1	"HDP26-24-31PT-L024"
HDP24-24-31PT-L015	"ZPF000000000131141"
HDP26-18-14PN- L017	
DRC26-50S05-C026	
DRC18-40SAE	"ZPF000000000131298"
HD10-9-96P-BE09	"HD10-9-96P-BE09-MS", "HD10-9-96P-BE09-M"
DRC18-40SBE	"ZPF000000000131303"
HDP26-24-23ST-L017	"ZPF000000000131043"
DRC26-50S06	"ZPF000000000131368", "DRC26-50S06-RU"
DRC26-40SB-P017	
HDB36-24-31SE-059	"ZPF000000000131134", "6-1899773-1"
HD36-24-31SE	"ZPF000000000131179", "HD36-24-31SE-AS", "\$ \$HD36-24-31SE"
YHDP24-18- 14PEL024	"HDP24-18-14PE-L024", "1899825-6"
HD36-18-20SN	"ZPF000000000130916"
DRC26-40SB	"ZPF000000000131320"
HD10-9-96P-B009	"ZPF000000000130532", "HD10-9-96P-B009-LD", "HD10-9-96P-B009-LS", "HD10-9-96P-B009-MS", "HD10-9-96P-B009-L", "HD10-9-96P-B009-M"
HD36-18-20SN-059	"ZPF000000000130917"

Product Affected	Alias Part Number
DRC14-40PDE	
HD34-24-31SE-L005	
HDP26-18-14SE-L017	"ZPF000000000130759", "3-1899772-9"
HD34-18-14SE-072	
HDP26-18-14SN	"ZPF000000000130760"
HD36-18-14PE-072	
HDP24-24-23PE	"ZPF000000000131008", "HDP24-24-23PE-LD", "HDP24-24-23PE-LS", "HDP24-24-23PE-MS", "HDP24-24-23PE-L", "HDP24-24-23PE-M"
HDB36-24-23PT	"ZPF000000000131000"
HD16-9-96S	"ZPF000000000130545"
DRC18-40SBE-P013	"ZPF000000000131304", "DRC18-40SBE-P013-RU"
HDP26-18-14PE-L017	"ZPF000000000130756", "9-1899773-5"
HDP26-24-23PE	"ZPF000000000131026", "\$HDP26-24-23PE"
HDP24-24-31ST-L017	"ZPF000000000131148", "7-1899820-8"
DRC26-50S08-C027	
HD34-24-31PT-072	
HDP24-24-23PN	"ZPF000000000131011"
HDP24-24-31ST	"ZPF000000000131146", "HDP24-24-31ST-LD", "HDP24-24-31ST-LS", "HDP24-24-31ST-L"
HDP26-24-23PT-L017	"ZPF000000000131034"
DRC26-50S01-C027	
HDP26-24-31PE-L017	"ZPF000000000131151", "8-1899770-1", "BE.082.00"
DRC14-40PBE	"ZPF000000000131290"
HDB36-24-23PE	"ZPF000000000130996"
HD36-24-23PN-L005	
DRC26-50S02-C026	
HD34-24-31PT-BL07	
DT16-18SB-EK02	
HDP24-24-31PE-L015	"ZPF000000000131138", "HDP24-24-31PE-L015LS", "5-1899768-6", "HDP24-24-31PE-L015-EZ", "HDP24-24-31PE-L015-L"
HD36-24-31PE-059	"ZPF000000000131174"
DRC16-40SE	"ZPF000000000131295"
DRC26-40SD	"ZPF000000000131323"
DRC26-60S10	"ZPF000000000131388"
DRC26-60S03	"ZPF000000000131381"
HD36-24-23SN-059	"ZPF000000000131076", "7-1899816-1"

Product Affected	Alias Part Number
HD34-18-14PN-H001	"ZPF000000000130767", "HD34-18-14PN-H001-RU"
DRC26-50S06-C026	
DRC18-40SD	"ZPF000000000131309"
HD36-24-31ST-B019	"ZPF000000000131185", "8-1899770-2"
DRC16-40S-P013	"ZPF000000000131294", "DRC16-40S-P013-LS", "DRC16-40S-P013-MS", "DRC16-40S-P013-M", "DRC16-40S-P013-L"
HDB36-24-31ST	"ZPF000000000131135"
HDB36-24-23SN-059	"ZPF000000000131005"
HDB36-24-23SN	"ZPF000000000131004", "HDB36-24-23SN-RU"
DRC18-40SA-PP02	
HDP24-18-14PE-L015	
HD36-24-31PE-L005	
HD36-24-23PE	"ZPF000000000131063", "\$\$HD36-24-23PE"
HD36-18-14PT	
DRC26-40SD-P017	
HDP26-24-31PT	"ZPF000000000131152", "HDP26-24-31PT-LD", "HDP26-24-31PT-MS", "HDP26-24-31PT-L", "HDP26-24-31PT-M"
DRC26-50S01	"ZPF000000000131362", "DRC26-50S01-AS", "DRC26-50S01-LS", "DRC26-50S01-E", "DRC26-50S01-L"
DRC18-40SD-PP02	
HD17-9-1939SE-P080	
HDP24-24-23SE	"ZPF000000000131017"
HDB36-24-23PN	"ZPF000000000130998", "HDB36-24-23PN-RU"
HD36-24-23SE-L005	
DRC14-40PA	"ZPF000000000131287"
HD17-9-1939S-P080	
HDP24-24-23SN	"ZPF000000000131020"
DRC26-50S06-C027	
HDP26-24-31PE-L015	"ZPF000000000131150", "BE.122.00"
HDP24-18-14PN	"ZPF000000000130751", "HDP24-18-14PN-AS"
HD36-24-23PN-059	"ZPF000000000131067", "9-1899831-9"
HD34-24-31ST	"ZPF000000000131170", "HD34-24-31ST-MS"
HD36-24-23PE-059	"ZPF000000000131064", "HD36-24-23PE-059-RU"
DRC18-40SB	"ZPF000000000131301"
HD36-18-14PE	"ZPF000000000130777", "HD36-18-14PE-RU"

Product Affected	Alias Part Number
YHDP24-18-20PEL024	"HDP24-18-20PE-L024"
HD10-9-96PE	"ZPF000000000130535"
HDP26-24-23PN-L015	"ZPF000000000131030"
DRC26-50S05-C031	
HD36-24-31ST	"ZPF000000000131182", "HD36-24-31ST-AS", "\$HD36-24-31ST"
HD14-9-1939PE-P080	
HD36-18-14PN-C012	"ZPF000000000130743"
HD36-18-14SN-C013	
HDP26-24-23PT	"ZPF000000000131032"
HD16-9-1939SE	"ZPF000000000130544"
HD36-18-14ST	"ZPF000000000130790"
HDP24-24-23ST-L015	"ZPF000000000131024"
HDB36-24-23PN-059	"ZPF000000000130999"
DRC26-40SB-PL01	
HD36-24-31PE-072	
HD34-18-20PN-059	"ZPF000000000130908", "HD34-18-20PN-059-RU"
HD34-24-31PE-059	"ZPF000000000131162", "HD34-24-31PE-059-RU", "6-1899790-5"
HD36-18-20PN	"ZPF000000000130913"
HD34-24-31PT-B019	"ZPF000000000131166", "6-1899766-2"
HD36-18-14PE-C028	
HDP24-24-23PN-L017	"ZPF000000000131013"
HD10-9-1939PE	"ZPF000000000130530", "HD10-9-1939PE-LD", "HD10-9-1939PE-LS", "\$HD10-9-1939PE", "HD10-9-1939PE-L"
HDP24-24-23PT-L015	"ZPF000000000131015"
HDB36-24-31SE	"ZPF000000000131133"
HD34-18-20SN	"ZPF000000000130910"
YHDP26-18-20SNL024	"HDP26-18-20SN-L024"
HD36-18-14SN-059	"ZPF000000000130787", "7-1899770-9", "HD36-18-14SN-059-RU"
HDP24-18-20PN-L017	
HD34-24-31PT	"ZPF000000000131164", "\$HD34-24-31PT"
HDP26-24-23PE-L017	"ZPF000000000131028", "6-1899773-5"

Product Affected	Alias Part Number
HD34-24-23PN-M003	
HD36-18-14PE-C029	
HD34-24-23PE-R010	
HD34-18-14SN-072	"ZPF000000000130776"
DRC26-50S06-C031	
DRC26-40SB-L011	"ZPF000000000131321", "\$\$DRC26-40SB-L011"
HDB36-18-14SN-059	"ZPF000000000130749"
HDB36-24-23SN-072	
HD36-24-23SN	"ZPF000000000131075"
HD14-9-1939P-P080	"HD14-9-1939P-P080-RU"
HD36-18-20SE	
DRC26-40SD-P019	
DRC26-40SA-P017	"ZPF000000000131318"
YHDP24-18-20PNL024	"HDP24-18-20PN-L024"
HD10-9-1939PE-P080	
HDP24-24-31PE	"ZPF000000000131137", "HDP24-24-31PE-AS", "HDP24-24-31PE-LD", "HDP24-24-31PE-LS", "HDP24-24-31PE-MS", "\$\$HDP24-24-31PE", "HDP24-24-31PE-E", "HDP24-24-31PE-L", "HDP24-24-31PE-M"
HD34-24-23PT	"ZPF000000000131050", "HD34-24-23PT-RU"
HD36-24-31SE-059	"ZPF000000000131180", "HD36-24-31SE-059-LS", "5-1899768-7", "HD36-24-31SE-059-L"
HDP26-18-20SN	"ZPF000000000130906", "ZPF000000000146155"
HD34-18-14PE	"ZPF000000000130761", "\$\$HD34-18-14PE"
DRC18-40SC-P013	"ZPF000000000131306", "DRC18-40SC-P013-MS", "DRC18-40SC-P013-M"
HDP26-24-23PN	"ZPF000000000131029"
HD14-9-96P-C016	"ZPF000000000130540"
DRC18-40SCE	"ZPF000000000131307"
DRC18-40SCE-P013	"ZPF000000000131308"
DRC18-40SA-P013	"ZPF000000000131297", "DRC18-40SA-P013-MS", "DRC18-40SA-P013-M"
HDP24-18-14ST	
HDP26-18-14ST	
HD36-24-23PN	"ZPF000000000131066", "HD36-24-23PN-MS", "HD36-24-23PN-M"
HDP24-24-23PE-L015	"ZPF000000000131009", "3-1899772-8"
DRC26-60S01	"ZPF000000000131379"

Product Affected	Alias Part Number
HDB36-24-23ST	
HDP24-24-23PN-L015	"ZPF000000000131012"
DRC26-50S07-C031	
DT16-6S-KP01	
HD10-9-96P	"ZPF000000000130531"
HD36-24-23PN-072	"ZPF000000000131068"
HD34-24-23SN-059	"ZPF000000000131057"
DRC18-40SA	"ZPF000000000131296"
HDP26-18-14PT	
HDB36-18-14PN	"ZPF000000000130746", "HDB36-18-14PN-RU"
HD36-24-23SN-J001	"ZPF000000000131078"
HDP26-24-31PT-L015	"ZPF000000000131153"
HD10-9-1939P-B022	"8-1899770-9", "HD10-9-1939P-B022-E"
HD36-24-31ST-059	"ZPF000000000131183", "8-1899770-4"
DRC22-40PC	
HD34-24-31PE	"ZPF000000000131161", "HD34-24-31PE-LD", "HD34-24-31PE-LS", "\$HD34-24-31PE", "HD34-24-31PE-L"
HD36-24-23SN-L005	
HDP26-24-31ST	"ZPF000000000131158", "HDP26-24-31ST-LD", "HDP26-24-31ST-LS", "HDP26-24-31ST-MS", "HDP26-24-31ST-L", "HDP26-24-31ST-M"
HDP26-24-23SN	"ZPF000000000131038"
DRC18-40SAE-P013	"ZPF000000000131299", "DRC18-40SAE-P013-MS", "DRC18-40SAE-P013-M"
DRC26-50S04	"ZPF000000000131366", "DRC26-50S04-AS", "DRC26-50S04-LS", "DRC26-50S04-L"
HD34-18-14PN-059	"ZPF000000000130765", "HD34-18-14PN-059-MS", "8-1899770-6", "HD34-18-14PN-059-RU", "HD34-18-14PN-059-M"
DRC26-50S10-C027	
HD36-18-14ST-059	
HDP26-24-31ST-L015	"ZPF000000000131159", "1899825-9"
HDP24-24-23SE-L017	"ZPF000000000131019", "2-1899836-1"
HD34-24-23SE-059	"ZPF000000000131054"
HD16-9-1939S-P080	"HD16-9-1939S-P080-RU"
HDP24-24-23SN-L017	"ZPF000000000131022", "5-1899777-0"
HDB36-18-14SE-059	

Product Affected	Alias Part Number
HDP24-24-31SE-L017	"ZPF000000000131145", "8-1899773-8"
DRC26-50S04-C027	
HD36-18-14PN-059	"ZPF000000000130781", "HD36-18-14PN-059-RU"
HD36-24-31PE	"ZPF000000000131173", "\$\$HD36-24-31PE"
HDP26-24-23SE-L017	"ZPF000000000131037", "HDP26-24-23SE-L017AS", "8-1899773-6"
DRC26-50S03-C027	
DRC18-40SDE-P013	
HD36-24-23SE	"ZPF000000000131072", "\$\$HD36-24-23SE"
YHDP26-24-31STL024	"HDP26-24-31ST-L024"
HDP26-24-23PN-L017	"ZPF000000000131031", "4-1899777-9"
HD34-24-23PE-072	"ZPF000000000131046", "3-1899806-0"
DT16-18SC-K004	
DRC26-60S09	"ZPF000000000131387"
HD14-9-96P	"ZPF000000000130539", "HD14-9-96P-MS", "HD14-9-96P-M"
HDP24-18-20PE-L017	
HDP26-24-23SE-L015	"ZPF000000000131036", "5-1899768-5"
DRC26-40SC	"ZPF000000000131322"
HD34-24-23SE	"ZPF000000000131053"
HDP24-24-23ST	"ZPF000000000131023"
DT16-18SD-EK02	
DT16-18SE-K004	
DRC26-50S02-C031	
HDP26-18-14SN-L017	"ZPF000000000140419"
HD36-24-23ST-059	"ZPF000000000131080"
HDP26-24-23SN-L015	"ZPF000000000131039", "HDP26-24-23SN-L015MS", "4-1899772-0", "HDP26-24-23SN-L015-M"
HDP24-24-31SE	"ZPF000000000131143", "HDP24-24-31SE-LS", "\$\$HDP24-24-31SE", "HDP24-24-31SE-L"
HD34-24-23PE-059	"ZPF000000000131045"
HD36-24-31SE-L005	
HD36-18-14SN	"ZPF000000000130786", "\$\$HD36-18-14SN"
HDP26-18-14SE-L015	"1-1899839-0"

Product Affected	Alias Part Number
YHDP24-18-14PEC041	"HDP24-18-14PE-C041", "4-1899829-6"
DRC18-40SB-P013	"ZPF000000000131302", "DRC18-40SB-P013-MS", "DRC18-40SB-P013-M"
DRC26-50S10	"ZPF000000000131372"
HD34-18-14PN-L005	
HD34-24-23ST	"ZPF000000000131059"
HDP24-24-31PT-L017	"ZPF000000000131142", "3-1899785-6"
HD36-18-14SE	"ZPF000000000130783", "\$HD36-18-14SE"
HD36-18-14SN-L005	"HD36-18-14SN-L005-RU"
DRC26-40SC-P019	
YHDP26-18-20SEL024	"HDP26-18-20SE-L024"
YHDP24-24-23PEL024	"HDP24-24-23PE-L024"
HDP26-24-31ST-L017	"ZPF000000000131160", "4-1899772-2"
DRC26-50S07-C027	
HD34-24-23PN	"ZPF000000000131047"
DRC26-50S03-C026	
YHDP24-24-31PEL024	"HDP24-24-31PE-L024"
HDP24-24-23PE-L017	"ZPF000000000131010", "HDP24-24-23PE-L017AS", "8-1899773-5"
HD34-18-14SN	"ZPF000000000130774"
DRC12-40PBE	"ZPF000000000131275"
HDP24-24-31ST-L015	"ZPF000000000131147"
HDP24-24-31SE-L015	"ZPF000000000131144"
DRC26-50S02-C027	
HD34-24-31SE-059	"ZPF000000000131168", "HD34-24-31SE-059-RU"
HD36-24-31PT-072	"ZPF000000000131178"
HD34-24-23SN	"ZPF000000000131056"
DRC26-50S02	"ZPF000000000131364", "DRC26-50S02-LS", "DRC26-50S02-L"
HDB36-18-14PE-072	
HD14-9-1939PE	"ZPF000000000130538"
HDP26-18-20SE-L017	"ZPF000000000140687"
HDP24-18-14PT	
HDP26-24-31SE	"ZPF000000000131155", "HDP26-24-31SE-AS", "HDP26-24-31SE-LS", "HDP26-24-31SE-MS", "\$HDP26-24-31SE", "HDP26-24-31SE-L", "HDP26-24-31SE-M"

Product Affected	Alias Part Number
HDP26-24-23SN-L017	"ZPF000000000131040", "HDP26-24-23SN-L017MS", "HDP26-24-23SN-L017-M", "1899781-2"
HD34-24-23PN-059	"ZPF000000000131048"
HD10-9-1939P-BP03	
HD10-9-96PE-B025	"HD10-9-96PE-B025-MS", "9-1899773-3", "HD10-9-96PE-B025-RU", "HD10-9-96PE-B025-M"
HDP24-24-23SE-L015	"ZPF000000000131018"
HD36-24-23ST	"ZPF000000000131079", "HD36-24-23ST-AS"
DRC14-40PB	"ZPF000000000131289", "DRC14-40PB-RU"
HD36-24-31PT-059	"ZPF000000000131177", "HD36-24-31PT-059-RU"
2294433-1	"HDP24-24-31PT-L024"
HD36-24-23PT	"ZPF000000000131069", "HD36-24-23PT-RU"
HDP24-18-20PN	"ZPF000000000130904"
DT16-18SA-EK02	
DRC26-40SA	"ZPF000000000131316", "DRC26-40SA-LS", "DRC26-40SA-L"
HD34-24-31SE-072	
HDB36-18-14PE-059	
DRC18-40SDE	
HDP24-18-20PE	"ZPF000000000140686"
DRC26-60S07	"ZPF000000000131385", "DRC26-60S07-LD", "DRC26-60S07-LS", "DRC26-60S07-L"
DRC14-40PD	
HD14-9-96PE	"ZPF000000000130541"
HD10-9-96P-B025	"ZPF000000000130533", "HD10-9-96P-B025-LD", "HD10-9-96P-B025-L"
HD34-24-31PT-059	"ZPF000000000131165", "8-1899770-7"
DRC26-50S09-C027	
DRC26-50S09	"ZPF000000000131371"
DRC14-40PCE	"ZPF000000000131292"
HDP26-18-14SN-L015	
HD36-24-23PE-072	"ZPF000000000131065"
DRC26-50S01-C031	
HDP26-18-20SN-L017	"ZPF000000000138937"
HDB36-24-31ST-059	"ZPF000000000131136"
DRC26-50S03-C031	
HD36-24-31SE-B019	
DRC26-40SA-P019	"ZPF000000000131319"

Product Affected	Alias Part Number
DRC12-40PB	"ZPF000000000131274", "DRC12-40PB-MS", "DRC12-40PB-M"
DRC12-40PD	"ZPF000000000131278"
HD36-18-14ST-072	

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or

all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.