



Product Change Notification

Current Date: 08-Jul-2021

TE Connectivity

Product Change Notification: P-21-021164

PCN Date: 07-JUL-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Manufacturing Location Change - Bangalore, India / Guangdong, China

Description of Changes
Please be informed that effective September 1, 2021 the following products currently manufactured at the TE Bangalore, India facility may also be sourced from the TE Shunde/Guangdong, China facility. Please contact your TE Account Manager with questions.

Reason for Changes:
Continual footprint analysis and improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-SEP-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1705949-1	NO		TYC1-1705949-1				
1-1705950-1	NO		TYC1-1705950-1				
1-1705951-1	NO		TYC1-1705951-1				
1-338084-3	NO		TYC1-338084-3				
1-338084-6	NO		TYC1-338084-6				
1-338086-3	NO		TYC1-338086-3	"CA8252-000", "AMP-1-0338086-3"			
1-338086-4	NO		TYC1-338086-4				
1-338086-6	NO		TYC1-338086-6				
1-338088-3	NO		TYC1-338088-3	"1352733"			
1-338088-6	NO		TYC1-338088-6				
1-5555153-1	NO						
100616-1	NO		TYC100616-1				
100616-2	NO		TYC100616-2				
1705549-1	NO		TYC1705549-1				
171822-2	NO		TYC171822-2				
171822-3	NO		TYC171822-3	"0-0171822-3"			
171822-4	NO		TYC171822-4	"CZ0532-000", "AMP-1-171822-4"			
171822-6	NO		TYC171822-6				
171822-8	NO		TYC171822-8				
172211-2	NO		TYC172211-2				
172211-4	NO		TYC172211-4				
172213-3	NO		TYC172213-3				
215875-1	NO		TYC215875-1				
215876-1	NO		TYC215876-1				
215876-2	NO		TYC215876-2				
215877-1	NO		TYC215877-1	"AMP-0-0215877-1", "C22207-000"			
216000-2	NO		TYC216000-2				
216005-4	NO		TYC216005-4	"A17555-000", "AMP-0-0216005-4"			
216548-1	NO		TYC216548-1				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
216550-1	NO		TYC216550-1				
3-5338556-1	NO		TYC3-5338556-1				
5-520314-7	NO		TYC5-520314-7				
5-520315-5	NO		TYC5-520315-5				
5-520315-7	NO		TYC5-520315-7	"2-41098-0241"			
5406429-1	NO		TYC5406429-1				
5406514-2	NO		TYC5406514-2				
5406721-1	NO		TYC5406721-1				
5406721-2	NO		TYC5406721-2				
5520249-2	NO		TYC5520249-2	"2-42932-7181"			
5520250-3	NO		TYC5520250-3	"CF8925-000", "AMP-0-5520250-3"			
5520251-4	NO		TYC5520251-4	"CC3737-000", "AMP-0-5520251-4", "6056062"			
5520257-2	NO		TYC5520257-2				
5520258-3	NO		TYC5520258-3				
5520259-4	NO		TYC5520259-4				
5520260-4	NO		TYC5520260-4	"6422303100", "1370017", "6422 3 03100"			
5520425-3	NO		TYC5520425-3				
5520426-4	NO		TYC5520426-4	"CF8931-000", "AMP-0-5520426-4"			
5555140-1	NO		TYC5555140-1				
5555141-1	NO		TYC5555141-1				
5555153-1	NO		TYC5555153-1	"CF8928-000", "AMP-0-5555153-1"			
5555153-5	NO		TYC5555153-5				
5555154-1	NO		TYC5555154-1				
5555154-2	NO		TYC5555154-2				
5555162-1	NO		TYC5555162-1	"CJ8433-000", "AMP-0-5555162-1"			
5556416-1	NO		TYC5556416-1	"650-1277-01"			
5557484-1	NO		TYC5557484-1				
5557730-1	NO		TYC5557730-1	"2-42938-4548"			
5557969-1	NO		TYC5557969-1	"CK1349-000", "AMP-0-5557969-1"			
5558178-1	NO		TYC5558178-1				
5558872-1	NO		TYC5558872-1	"A08646-000", "AMP-0-5558872-1"			
6-520315-2	NO		TYC6-520315-2				
6-520315-5	NO		TYC6-520315-5				
6339191-1	NO		TYC6339191-1	"1112265"			
6339191-4	NO						
6339191-5	NO		TYC6339191-5				
6368115-1	NO		TYC6368115-1				



Product Change Notification

Current Date: 08-Jul-2021

TE Connectivity

Product Change Notification: P-21-021164

PCN Date: 07-JUL-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Manufacturing Location Change - Bangalore, India / Guangdong, China

Description of Changes
Please be informed that effective September 1, 2021 the following products currently manufactured at the TE Bangalore, India facility may also be sourced from the TE Shunde/Guangdong, China facility. Please contact your TE Account Manager with questions.

Reason for Changes:
Continual footprint analysis and improvement.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-SEP-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1705949-1	NO		TYC1-1705949-1				
1-1705950-1	NO		TYC1-1705950-1				
1-1705951-1	NO		TYC1-1705951-1				
1-338084-3	NO		TYC1-338084-3				
1-338084-6	NO		TYC1-338084-6				
1-338086-3	NO		TYC1-338086-3	"CA8252-000", "AMP-1-0338086-3"			
1-338086-4	NO		TYC1-338086-4				
1-338086-6	NO		TYC1-338086-6				
1-338088-3	NO		TYC1-338088-3	"1352733"			
1-338088-6	NO		TYC1-338088-6				
1-5555153-1	NO						
100616-1	NO		TYC100616-1				
100616-2	NO		TYC100616-2				
171822-2	NO		TYC171822-2				
171822-3	NO		TYC171822-3	"0-0171822-3"			
171822-4	NO		TYC171822-4	"CZ0532-000", "AMP-1-171822-4"			
171822-6	NO		TYC171822-6				
171822-8	NO		TYC171822-8				
172211-2	NO		TYC172211-2				
172211-4	NO		TYC172211-4				
172213-3	NO		TYC172213-3				
215875-1	NO		TYC215875-1				
215876-1	NO		TYC215876-1				
215876-2	NO		TYC215876-2				
215877-1	NO		TYC215877-1	"AMP-0-0215877-1", "C22207-000"			
216000-2	NO		TYC216000-2				
216005-4	NO		TYC216005-4	"A17555-000", "AMP-0-0216005-4"			
216548-1	NO		TYC216548-1				
216550-1	NO		TYC216550-1				

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3-5338556-1	NO		TYC3-5338556-1				
5-520314-7	NO		TYC5-520314-7				
5-520315-5	NO		TYC5-520315-5				
5-520315-7	NO		TYC5-520315-7	"2-41098-0241"			
5406429-1	NO		TYC5406429-1				
5406514-2	NO		TYC5406514-2				
5406721-1	NO		TYC5406721-1				
5406721-2	NO		TYC5406721-2				
5520249-2	NO		TYC5520249-2	"2-42932-7181"			
5520250-3	NO		TYC5520250-3	"CF8925-000", "AMP-0-5520250-3"			
5520251-4	NO		TYC5520251-4	"CC3737-000", "AMP-0-5520251-4", "6056062"			
5520257-2	NO		TYC5520257-2				
5520258-3	NO		TYC5520258-3				
5520259-4	NO		TYC5520259-4				
5520260-4	NO		TYC5520260-4	"6422303100", "1370017", "6422 3 03100"			
5520425-3	NO		TYC5520425-3				
5520426-4	NO		TYC5520426-4	"CF8931-000", "AMP-0-5520426-4"			
5555140-1	NO		TYC5555140-1				
5555141-1	NO		TYC5555141-1				
5555153-1	NO		TYC5555153-1	"CF8928-000", "AMP-0-5555153-1"			
5555153-5	NO		TYC5555153-5				
5555154-1	NO		TYC5555154-1				
5555154-2	NO		TYC5555154-2				
5555162-1	NO		TYC5555162-1	"CJ8433-000", "AMP-0-5555162-1"			
5556416-1	NO		TYC5556416-1	"650-1277-01"			
5557484-1	NO		TYC5557484-1				
5557730-1	NO		TYC5557730-1	"2-42938-4548"			
5558178-1	NO		TYC5558178-1				
5558872-1	NO		TYC5558872-1	"A08646-000", "AMP-0-5558872-1"			
6-520315-2	NO		TYC6-520315-2				
6-520315-5	NO		TYC6-520315-5				
6339191-4	NO						
6339191-5	NO		TYC6339191-5				
6368115-1	NO		TYC6368115-1				