



Product Change Notification

Current Date: 20-Jul-2021

TE Connectivity

Product Change Notification: PCN-21-107524

PCN Date: 16-JUL-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

TERMINAL BLOCK ASSEMBLY, PCB MOUNT, SIDE WIRE ENTRY 2.54 AND 5.08 MM PITCH

Description of Changes

Please be aware of an upcoming feature change to the listed part numbers. Before: The product was supported on the PCB by means of 4 standoffs at 4 corners. After: Standoffs are now integral part of 2 side walls. Further the inside walls that separate the individual poles now reach the PCB surface and are visible by looking at the product from front. The draft of some surfaces on the back of the terminal block has been slightly increased. No change in Overall dimensions. Reference performance test data: Refer to attachment for detailed changes on the form of the housing.

Before-1	After-1
Before-2	After-2
Before-3	After-3

Other attachments:
[PCN-282834,282835,1546215](#)
Reason for Changes:

Update made to facilitate the molding process in mold remaking and the feeding of components in the automated assembling line

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	12-JAN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282834-5	NO		TYC282834-5				

The documents listed below are being modified. Related parts that are not explicitly listed on this PCN are not being modified or discontinued as per the PCN. The Last Order Date, Last Ship Date, First Date to Ship Changed Parts and last date for Mixed Shipments apply only to parts explicitly listed on this PCN.

Customer Drawing(s) Being Modified:

Drawing Number	Related Part Number	Customer Part Number	Current Revision	New Revision
282834	282834-5	TYC282834-5	C1	



Product Change Notification

Current Date: 20-Jul-2021

TE Connectivity

Product Change Notification: PCN-21-107524

PCN Date: 16-JUL-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

TERMINAL BLOCK ASSEMBLY, PCB MOUNT, SIDE WIRE ENTRY 2.54 AND 5.08 MM PITCH

Description of Changes

Please be aware of an upcoming feature change to the listed part numbers. Before: The product was supported on the PCB by means of 4 standoffs at 4 corners. After: Standoffs are now integral part of 2 side walls. Further the inside walls that separate the individual poles now reach the PCB surface and are visible by looking at the product from front. The draft of some surfaces on the back of the terminal block has been slightly increased. No change in Overall dimensions. Reference performance test data: Refer to attachment for detailed changes on the form of the housing.

Before-1	After-1
Before-2	After-2
Before-3	After-3

Other attachments:
[PCN-282834,282835,1546215](#)
Reason for Changes:

Update made to facilitate the molding process in mold remaking and the feeding of components in the automated assembling line

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	12-JAN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
282834-5	NO		TYC282834-5				