



Product Change Notification

Current Date: 03-Aug-2021

TE Connectivity

Product Change Notification: P-21-021265

PCN Date: 02-AUG-21

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP2.8 Contact

Description of Changes

addendum to P-18-016323. Capacity tool duplication. Additional manufacturing location - TE Brazil will have ability to supply these parts. This is not a manufacturing location change. THERE IS NO PHYSICAL CHANGE TO ANY PART OR PART DRAWING.

Reason for Changes:

Added capacity / second sourcing of product to support N. America customer base.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

21-AUG-2021

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968855-1	NO		TYC1-968855-1	"8202612100"			
1-968855-2	NO		TYC1-968855-2				
1-968855-3	NO		TYC1-968855-3				
1-968857-1	NO		TYC1-968857-1				
1-968857-3	NO		TYC1-968857-3				



Product Change Notification

Current Date: 03-Aug-2021

TE Connectivity

Product Change Notification: P-21-021265

PCN Date: 02-AUG-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP2.8 Contact

Description of Changes

addendum to P-18-016323. Capacity tool duplication. Additional manufacturing location - TE Brazil will have ability to supply these parts. This is not a manufacturing location change. THERE IS NO PHYSICAL CHANGE TO ANY PART OR PART DRAWING.

Reason for Changes:

Added capacity / second sourcing of product to support N. America customer base.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	21-AUG-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968855-1	NO			"8202612100"			
1-968855-2	NO						
1-968855-3	NO						
1-968857-1	NO						
1-968857-3	NO						