



Product Change Notification

Current Date: 24-Sep-2021

TE Connectivity

Product Change Notification: PCN-21-111689

PCN Date: 23-SEP-21

Customer: TTI, Inc. (1305175)

Location: Maisach-gernlinden

Agreement: TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

XT relay + PT/RT DIN-rail sockets

Description of Changes

Please be aware of an upcoming cosmetic change to the listed part numbers (not affecting the function of the product). The product marking will be applied by laser technology.

Socket PT78742	
Oil print marking	
Laser marking	
Relay XT484R24	
Oil print marking	
Laser marking	

Reason for Changes:

Product marking process known as ink stamping is replaced by laser marking. Product cosmetic or appearance is updated.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-SEP-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1415526-1	NO			"D51265-000", "AMPS-1-1415526-1", "PT78742"			
1860200-1	NO			"RT7872P"			
1860306-1	NO			"RT78725"			
1887212-2	NO			"XT484L24"			



Product Change Notification

Current Date: 24-Sep-2021

TE Connectivity

Product Change Notification: PCN-21-111689

PCN Date: 23-SEP-21

Customer: TTI, Inc. (3057778)



Location: Maisach-gernlinden




Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
XT relay + PT/RT DIN-rail sockets

Description of Changes
Please be aware of an upcoming cosmetic change to the listed part numbers (not affecting the function of the product). The product marking will be applied by laser technology.

Socket PT78742	
Oil print marking	 
Laser marking	 

Relay XT484R24	
Oil print marking	 
Laser marking	 

Reason for Changes:	
Product marking process known as ink stamping is replaced by laser marking. Product cosmetic or appearance is updated.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	27-SEP-2021
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-DEC-2021

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1860306-1	NO		TYC1860306-1	"RT78725"			
1887212-2	NO		TYC1887212-2	"XT484L24"			