



Product Change Notification

Current Date: 06-Oct-2021

TE Connectivity

Product Change Notification: P-21-021547

PCN Date: 05-OCT-21

Customer: TTI Inc(0000139702)

Location: WORLDWIDE

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Manufacturing location change

Description of Changes
Manufacturing location change. Following Part Numbers will be transferred from TE Connectivity, Fremont, CA to TE Connectivity Corporation, Waynesboro, PA, US

Reason for Changes:
Dear Customer, we hereby inform you about a transfer of tools and/or processes. The transfer follows a strict procedure, which fully maintains quality, ability to supply and form-fit-function of the concerned products. The new manufacturing location operates under a certified quality management system in accordance with standard ISO9001 2015 requirements. A TE-internal release test based on the relevant part specifications will be executed before delivery.

Estimated Dates:	
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	03-JAN-2022
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	31-MAR-2022

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
007510-000	NO			"4-1198063-5", "IR-550-238-VIEWING-WINDOW"			
013750-000	NO			"9-1190107-1", "AA-400-128-MK3-EL-KIT-120"			
018579-000	NO			"2-1190145-2", "AD-1319-12-HOLDNG-FIXTURE"			
047011-000	NO			"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
118902-000	NO			"6-1197950-5", "IR-550-237-FLTR-DUAL-COAT"			
181779-000	NO			"8-1191320-0", "AD-1565-1-SLDTCT-HLDR-ASY"			
395241-000	NO			"1-1192965-6", "AT-1319-22-SLDRT-HLD-FIXT"			
413186-000	NO			"4-1193115-5", "AT-1319-78-SOLDTCT-ADAPT"			
508744-000	NO			"5-1193999-5"			
529600-000	NO			"8-1199183-1", "IR-550-240-REFURB-KIT"			
582602-000	NO			"2-1194615-4", "AA-400-32-MK3-SUPHTR-120V"			
612903-000	NO			"4-1194845-3", "AD-1298-1-TRIMR-TWISTD-PR"			
729711-000	NO			"9-1195700-0", "HT-900A-114-TC-RPLMT-KIT"			
959025-000	NO			"7-1197423-9"			
979649-000	NO			"7-1197567-4"			
979663-000	NO			"9-1197567-4", "AA-400-102-MINI-SOLD-TIP"			
991017-000	NO			"2-1197663-7", "TG-12/A-160-HG-RFL-SMALL"			
992008-000	NO			"3-1197673-0"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
992013-000	NO			"3-1197673-8", "AD-1386-CALIBRATION-GAUGE"			
992024-000	NO			"5-1197673-3"			
993020-000	NO			"7-1197680-9", "IR-1000-P-N-13-LAMP"			
993770-000	NO			"1197687-6"			
993850-000	NO			"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
993872-000	NO			"7-1197687-4", "AT-1319-12"			
993877-000	NO			"8-1197687-0", "AT-1319-14-16-748-ST-ADP"			
993878-000	NO			"8-1197687-6", "AT-1319-15-16-POW-CNT-AD"			
993938-000	NO			"2-1197688-6", "AT-1319-19-723-SLDT-ASSY"			
994003-000	NO			"6-1197688-2", "AD-1464-CONT-RMVL-TL-ASSY"			
994040-000	NO			"1197689-8", "AD-1480-748-SOLDTK-HOLDER"			
994123-000	NO			"8-1197689-1", "AD-1377-P-E118-TOR-SPRNG"			
994350-000	NO			"3-1197691-2", "IR-550-50-MARKII-HT-TOOL"			
994855-000	NO			"6-1197695-6", "AD-1377-103-CRIMP-LOCATOR"			

Customer: TTI, Inc. (1305175)

Location: Maisach-germlinden

Agreement Number: TTI001

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
047011-000	NO		RAY047011-000	"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
993850-000	NO		RAY993850-000	"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
994040-000	NO		RAY994040-000	"1197689-8", "AD-1480-748-SOLDTK-HOLDER"			

Customer: TTI Inc (3164508)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
047011-000	NO			"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
118902-000	NO			"6-1197950-5", "IR-550-237-FLTR-DUAL-COAT"			
508744-000	NO			"5-1193999-5"			
612903-000	NO			"4-1194845-3", "AD-1298-1-TRIMR-TWISTD-PR"			
729711-000	NO			"9-1195700-0", "HT-900A-114-TC-RPLMT-KIT"			
959025-000	NO			"7-1197423-9"			
992008-000	NO			"3-1197673-0"			
992013-000	NO			"3-1197673-8", "AD-1386-CALIBRATION-GAUGE"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
992024-000	NO			"5-1197673-3"			
993850-000	NO			"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
993877-000	NO			"8-1197687-0", "AT-1319-14-16-748-ST-ADP"			
993938-000	NO			"2-1197688-6", "AT-1319-19-723-SLDT-ASSY"			
994855-000	NO			"6-1197695-6", "AD-1377-103-CRIMP-LOCATOR"			

Customer: TTI, Inc. (3057778)

Location: Maisach-gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
047011-000	NO		RAY047011-000	"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
993850-000	NO		RAY993850-000	"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
994040-000	NO		RAY994040-000	"1197689-8", "AD-1480-748-SOLDTK-HOLDER"			

Customer: TTI Inc (168830)

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
047011-000	NO			"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
118902-000	NO			"6-1197950-5", "IR-550-237-FLTR-DUAL-COAT"			
508744-000	NO			"5-1193999-5"			
612903-000	NO			"4-1194845-3", "AD-1298-1-TRIMR-TWISTD-PR"			
729711-000	NO			"9-1195700-0", "HT-900A-114-TC-RPLMT-KIT"			
959025-000	NO			"7-1197423-9"			
992008-000	NO			"3-1197673-0"			
992013-000	NO			"3-1197673-8", "AD-1386-CALIBRATION-GAUGE"			
992024-000	NO			"5-1197673-3"			
993850-000	NO			"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
993877-000	NO			"8-1197687-0", "AT-1319-14-16-748-ST-ADP"			
993938-000	NO			"2-1197688-6", "AT-1319-19-723-SLDT-ASSY"			
994855-000	NO			"6-1197695-6", "AD-1377-103-CRIMP-LOCATOR"			

Customer: TTI Inc (1281288)

Location: Fort Worth

Agreement Number: TTI002

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
007510-000	NO			"4-1198063-5", "IR-550-238-VIEWING-WINDOW"			
013750-000	NO			"9-1190107-1", "AA-400-128-MK3-EL-KIT-120"			
018579-000	NO			"2-1190145-2", "AD-1319-12-HOLDNG-FIXTURE"			
047011-000	NO			"2-1190361-8", "AD-1522-1-CRIMPING-TOOL"			
118902-000	NO			"6-1197950-5", "IR-550-237-FLTR-DUAL-COAT"			
181779-000	NO			"8-1191320-0", "AD-1565-1-SLDTCT-HLDR-ASY"			
395241-000	NO			"1-1192965-6", "AT-1319-22-SLDRH-HLD-FIXT"			
413186-000	NO			"4-1193115-5", "AT-1319-78-SOLDTCT-ADAPT"			
529600-000	NO			"8-1199183-1", "IR-550-240-REFURB-KIT"			
582602-000	NO			"2-1194615-4", "AA-400-32-MK3-SUPHTR-120V"			
959025-000	NO			"7-1197423-9"			
979649-000	NO			"7-1197567-4"			
979663-000	NO			"9-1197567-4", "AA-400-102-MINI-SOLD-TIP"			
991017-000	NO			"2-1197663-7", "TG-12/A-160-HG-RFL-SMALL"			
992008-000	NO			"3-1197673-0"			
992013-000	NO			"3-1197673-8", "AD-1386-CALIBRATION-GAUGE"			
993020-000	NO			"7-1197680-9", "IR-1000-P-N-13-LAMP"			
993770-000	NO			"1197687-6"			
993850-000	NO			"5-1197687-0", "AD-1319-9-HOLD-FIX-PACKAG"			
993872-000	NO			"7-1197687-4", "AT-1319-12"			
993877-000	NO			"8-1197687-0", "AT-1319-14-16-748-ST-ADP"			
993878-000	NO			"8-1197687-6", "AT-1319-15-16-POW-CNT-AD"			
993938-000	NO			"2-1197688-6", "AT-1319-19-723-SLDT-ASSY"			
994003-000	NO			"6-1197688-2", "AD-1464-CONT-RMVL-TL-ASSY"			
994040-000	NO			"1197689-8", "AD-1480-748-SOLDTK-HOLDER"			
994123-000	NO			"8-1197689-1", "AD-1377-P-E118-TOR-SPRNG"			
994350-000	NO			"3-1197691-2", "IR-550-50-MARKII-HT-TOOL"			
994855-000	NO			"6-1197695-6", "AD-1377-103-CRIMP-LOCATOR"			

Customer: TTI Electronics Asia Pte Ltd. (2771300)

Location: Singapore

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
-------------	---------------------------	------------------	----------------------	----------------------	------------------------	---------------------------------	---------------------------

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
992008-000	NO			"3-1197673-0"			