



# Product Change Notification

Current Date: 14-Dec-2021

## TE Connectivity

**Product Change Notification:** P-21-021869

**PCN Date:** 13-DEC-21

**Customer:** TTI Inc(0000139702)

**Location:** WORLDWIDE

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

Covers, DT04-2P, -3P, -4P, -6P, -8P, -12P and DT06-2S, -3S, -4S, -6S, -8S, -12S

### Description of Changes

The Industrial and Commercial Transportation business unit of TE Connectivity is adding new capacity tooling for the Deutsch Cover products identified with TE Logo Trademarks for the part number(s) listed below. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. Product drawing(s) will be affected with TE Logo views.

DEUTSCH LOGO



TE LOGO



### Reason for Changes:

Product improvement. Dear Customer, we hereby inform you of this change. The new tooling is necessary to better address the localized demand in the Asia region and worldwide as needed. The added tooling does not impact connector performance and has passed validation testing. IMPORTANT: No fit, form or function change and these parts off the new tool are interchangeable with current production. Shipments from current and new tooling configurations may be mixed.

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	15-JAN-2022
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	15-DEC-2022

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO			"ZPF000000000131515", "8202608536"			
<a href="#">1011-228-0205</a>	NO			"ZPF000000000131516"			
<a href="#">1011-229-0205</a>	NO			"ZPF000000000131517"			
<a href="#">1011-231-0305</a>	NO			"ZPF000000000137959"			
<a href="#">1011-233-0305</a>	NO			"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO			"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO			"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO			"ZPF000000000131527"			
<a href="#">1011-240-0605</a>	NO			"ZPF000000000131528"			
<a href="#">1011-241-0605</a>	NO			"ZPF000000000131529"			
<a href="#">1011-243-0805</a>	NO			"ZPF000000000131531"			
<a href="#">1011-245-0805</a>	NO			"ZPF000000000131533"			
<a href="#">1011-247-1205</a>	NO			"ZPF000000000131535"			
<a href="#">1011-248-1205</a>	NO			"ZPF000000000131536"			
<a href="#">1011-249-1205</a>	NO			"ZPF000000000131537"			
<a href="#">1011-255-0205</a>	NO						
<a href="#">1011-256-0205</a>	NO			"ZPF000000000131539"			
<a href="#">1011-257-0205</a>	NO			"ZPF000000000131540"			
<a href="#">1011-259-0305</a>	NO			"ZPF000000000131542"			
<a href="#">1011-261-0305</a>	NO			"ZPF000000000131544", "73000930-F"			
<a href="#">1011-263-0405</a>	NO			"ZPF000000000131546"			
<a href="#">1011-264-0405</a>	NO			"ZPF000000000131547"			
<a href="#">1011-265-0405</a>	NO			"ZPF000000000131548"			
<a href="#">1011-267-0605</a>	NO			"ZPF000000000131550"			
<a href="#">1011-268-0605</a>	NO			"ZPF000000000131551"			
<a href="#">1011-269-0605</a>	NO			"ZPF000000000131552"			
<a href="#">1011-270-0605</a>	NO			"ZPF000000000131553"			

Customer: TTI, Inc. ( 1305175 )

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO			"ZPF000000000131515", "8202608536"			
<a href="#">1011-228-0205</a>	NO			"ZPF000000000131516"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-229-0205</a>	NO			"ZPF000000000131517"			
<a href="#">1011-231-0305</a>	NO			"ZPF000000000137959"			
<a href="#">1011-233-0305</a>	NO			"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO			"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO			"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO			"ZPF000000000131527"			
<a href="#">1011-240-0605</a>	NO			"ZPF000000000131528"			
<a href="#">1011-241-0605</a>	NO			"ZPF000000000131529"			
<a href="#">1011-243-0805</a>	NO			"ZPF000000000131531"			
<a href="#">1011-245-0805</a>	NO			"ZPF000000000131533"			
<a href="#">1011-247-1205</a>	NO			"ZPF000000000131535"			
<a href="#">1011-248-1205</a>	NO			"ZPF000000000131536"			
<a href="#">1011-249-1205</a>	NO			"ZPF000000000131537"			
<a href="#">1011-255-0205</a>	NO						
<a href="#">1011-256-0205</a>	NO			"ZPF000000000131539"			
<a href="#">1011-257-0205</a>	NO			"ZPF000000000131540"			
<a href="#">1011-259-0305</a>	NO			"ZPF000000000131542"			
<a href="#">1011-261-0305</a>	NO			"ZPF000000000131544", "73000930-F"			
<a href="#">1011-263-0405</a>	NO			"ZPF000000000131546"			
<a href="#">1011-265-0405</a>	NO			"ZPF000000000131548"			
<a href="#">1011-267-0605</a>	NO			"ZPF000000000131550"			
<a href="#">1011-268-0605</a>	NO			"ZPF000000000131551"			
<a href="#">1011-269-0605</a>	NO			"ZPF000000000131552"			
<a href="#">1011-270-0605</a>	NO			"ZPF000000000131553"			

Customer: TTI ( 556264 )

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO			"ZPF000000000131515", "8202608536"			
<a href="#">1011-233-0305</a>	NO			"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO			"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO			"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO			"ZPF000000000131527"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-243-0805</a>	NO			"ZPF000000000131531"			
<a href="#">1011-264-0405</a>	NO			"ZPF000000000131547"			

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-germlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO		DEU1011-227-0205	"ZPF000000000131515", "8202608536"			
<a href="#">1011-228-0205</a>	NO		DEU1011-228-0205	"ZPF000000000131516"			
<a href="#">1011-229-0205</a>	NO		DEU1011-229-0205	"ZPF000000000131517"			
<a href="#">1011-231-0305</a>	NO		DEU1011-231-0305	"ZPF000000000137959"			
<a href="#">1011-233-0305</a>	NO		DEU1011-233-0305	"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO		DEU1011-235-0405	"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO		DEU1011-237-0405	"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO		DEU1011-239-0605	"ZPF000000000131527"			
<a href="#">1011-240-0605</a>	NO		DEU1011-240-0605	"ZPF000000000131528"			
<a href="#">1011-241-0605</a>	NO		DEU1011-241-0605	"ZPF000000000131529"			
<a href="#">1011-243-0805</a>	NO		DEU1011-243-0805	"ZPF000000000131531"			
<a href="#">1011-245-0805</a>	NO		DEU1011-245-0805	"ZPF000000000131533"			
<a href="#">1011-247-1205</a>	NO		DEU1011-247-1205	"ZPF000000000131535"			
<a href="#">1011-248-1205</a>	NO		DEU1011-248-1205	"ZPF000000000131536"			
<a href="#">1011-249-1205</a>	NO		DEU1011-249-1205	"ZPF000000000131537"			
<a href="#">1011-255-0205</a>	NO		DEU1011-255-0205				
<a href="#">1011-256-0205</a>	NO			"ZPF000000000131539"			
<a href="#">1011-257-0205</a>	NO		DEU1011-257-0205	"ZPF000000000131540"			
<a href="#">1011-259-0305</a>	NO		DEU1011-259-0305	"ZPF000000000131542"			
<a href="#">1011-261-0305</a>	NO		DEU1011-261-0305	"ZPF000000000131544", "73000930-F"			
<a href="#">1011-263-0405</a>	NO		DEU1011-263-0405	"ZPF000000000131546"			
<a href="#">1011-265-0405</a>	NO		DEU1011-265-0405	"ZPF000000000131548"			
<a href="#">1011-267-0605</a>	NO		DEU1011-267-0605	"ZPF000000000131550"			
<a href="#">1011-268-0605</a>	NO			"ZPF000000000131551"			
<a href="#">1011-269-0605</a>	NO		DEU1011-269-0605	"ZPF000000000131552"			
<a href="#">1011-270-0605</a>	NO		DEU1011-270-0605	"ZPF000000000131553"			

Customer: Tti Inc ( 3065242 )

Location: Maisach-Gernlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-228-0205</a>	NO			"ZPF000000000131516"			

Customer: TTI Inc ( 168830 )

Location: Fort Worth

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO			"ZPF000000000131515", "8202608536"			
<a href="#">1011-228-0205</a>	NO			"ZPF000000000131516"			
<a href="#">1011-229-0205</a>	NO			"ZPF000000000131517"			
<a href="#">1011-231-0305</a>	NO			"ZPF000000000137959"			
<a href="#">1011-233-0305</a>	NO			"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO			"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO			"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO			"ZPF000000000131527"			
<a href="#">1011-240-0605</a>	NO			"ZPF000000000131528"			
<a href="#">1011-241-0605</a>	NO			"ZPF000000000131529"			
<a href="#">1011-243-0805</a>	NO			"ZPF000000000131531"			
<a href="#">1011-245-0805</a>	NO			"ZPF000000000131533"			
<a href="#">1011-247-1205</a>	NO			"ZPF000000000131535"			
<a href="#">1011-248-1205</a>	NO			"ZPF000000000131536"			
<a href="#">1011-255-0205</a>	NO						
<a href="#">1011-257-0205</a>	NO			"ZPF000000000131540"			
<a href="#">1011-259-0305</a>	NO			"ZPF000000000131542"			
<a href="#">1011-263-0405</a>	NO			"ZPF000000000131546"			
<a href="#">1011-265-0405</a>	NO			"ZPF000000000131548"			
<a href="#">1011-267-0605</a>	NO			"ZPF000000000131550"			
<a href="#">1011-269-0605</a>	NO			"ZPF000000000131552"			

Customer: TTI, Inc. ( 3057778 )

Location: Maisach-gerlinden

Agreement Number: Agreement Unknown

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1011-227-0205</a>	NO		DEU1011-227-0205	"ZPF000000000131515", "8202608536"			
<a href="#">1011-228-0205</a>	NO		DEU1011-228-0205	"ZPF000000000131516"			
<a href="#">1011-229-0205</a>	NO		DEU1011-229-0205	"ZPF000000000131517"			
<a href="#">1011-231-0305</a>	NO		DEU1011-231-0305	"ZPF000000000137959"			
<a href="#">1011-233-0305</a>	NO		DEU1011-233-0305	"ZPF000000000131521"			
<a href="#">1011-235-0405</a>	NO		DEU1011-235-0405	"ZPF000000000131523"			
<a href="#">1011-237-0405</a>	NO		DEU1011-237-0405	"ZPF000000000131525"			
<a href="#">1011-239-0605</a>	NO		DEU1011-239-0605	"ZPF000000000131527"			
<a href="#">1011-240-0605</a>	NO		DEU1011-240-0605	"ZPF000000000131528"			
<a href="#">1011-241-0605</a>	NO		DEU1011-241-0605	"ZPF000000000131529"			
<a href="#">1011-243-0805</a>	NO		DEU1011-243-0805	"ZPF000000000131531"			
<a href="#">1011-245-0805</a>	NO		DEU1011-245-0805	"ZPF000000000131533"			
<a href="#">1011-247-1205</a>	NO		DEU1011-247-1205	"ZPF000000000131535"			
<a href="#">1011-248-1205</a>	NO		DEU1011-248-1205	"ZPF000000000131536"			
<a href="#">1011-249-1205</a>	NO		DEU1011-249-1205	"ZPF000000000131537"			
<a href="#">1011-255-0205</a>	NO		DEU1011-255-0205				
<a href="#">1011-256-0205</a>	NO			"ZPF000000000131539"			
<a href="#">1011-257-0205</a>	NO		DEU1011-257-0205	"ZPF000000000131540"			
<a href="#">1011-259-0305</a>	NO		DEU1011-259-0305	"ZPF000000000131542"			
<a href="#">1011-261-0305</a>	NO		DEU1011-261-0305	"ZPF000000000131544", "73000930-F"			
<a href="#">1011-263-0405</a>	NO		DEU1011-263-0405	"ZPF000000000131546"			
<a href="#">1011-265-0405</a>	NO		DEU1011-265-0405	"ZPF000000000131548"			
<a href="#">1011-267-0605</a>	NO		DEU1011-267-0605	"ZPF000000000131550"			
<a href="#">1011-268-0605</a>	NO			"ZPF000000000131551"			
<a href="#">1011-269-0605</a>	NO		DEU1011-269-0605	"ZPF000000000131552"			
<a href="#">1011-270-0605</a>	NO		DEU1011-270-0605	"ZPF000000000131553"			