

19-Nov-2021

PCN #: PCN-21-121539

Subject : DEUTSCH Size 16 S&F pin terminal Gap Change.

Description of Change : DEUTSCH Size 16 S&F pin terminal Gap Change.

The Industrial and Commercial Transportation business unit of TE Connectivity is making a change to the gap between the locking shoulder and wire crimp barrel for the part number(s) listed below. NOTE: The distance from the locking shoulder to the wire crimp barrel has not changed nor the overall length of the terminal. These PNs are TE proprietary designs, therefore considered catalog/general market product. PPAP and/or sample requests must be submitted within 14 days of PCN submission via ict-ppap-request@te.com or ePPAP system. Submission will not occur without request. If PPAP requested, disposition response is required within 14 days of submit date or it will be considered approved. The change does not impact performance and crimp application tooling. Product drawing(s) are affected.

REASON FOR CHANGE: The change is necessary to align the design with other size 16 S&F pin terminals. IMPORTANT: The current and previous revisions of these parts can be used interchangeably in the field. The change(s) are being phased in gradually and previous revision can remain stocked until use. Shipments of both configurations may be mixed.

Reason:

Key Dates:

Contact By Date: 18-Feb-2022 Implementation Date: 18-Feb-2022

| Product Affected | Alias Part Number | Substitute Part Number | AliasSub Part Number |
|---------------------|----------------------|---------------------------|----------------------|
| 1060-16-1277 | "2113497-3" | | |
| 1060-16-0688 | | | |

| 1060-16-0122 | "ZPF0000000 00131901", "1060-16-012 2-AS", "1060-16-012 2-LD", "1060-16-012 2-SC", "1060-16-012 2-E", "1060-16-012 2-L", "1060-16-012 2-L", "1060-16-012 2-S" | |
|--------------|---|--|
| 1060-14-0177 | | |
| 1060-14-1088 | | |
| 1060-16-0144 | "ZPF0000000 00131903", "1060-16-014 4-LS", "1060-16-014 4-L" | |
| 1060-16-1222 | "ZPF0000000 00131912", "2113497-1", "61.309.00" | |
| 1060-16-1244 | "2113497-2" | |
| 1060-16-0177 | | |
| 1060-14-0122 | "ZPF0000000 00131897", "1060-14-012 2-LS", "1060-14-012 2-L" | |
| 2392252-1 | "1060-16-019 9" | |
| 1060-16-0722 | "ZPF0000000 00131909", "1060-16-072 2SAMPLE" | |

| 1060-16-0622 | "ZPF0000000 00131905", "1060-16-062 2-LD", "1060-16-062 2-LS", "1060-16-062 2-SC", "1060-16-062 2SAMPLE", "ZPF0000000 00141127", "1060-16-062 2-L", "1060-16-062 2-S", "61.310.00", "5000636" | |
|--------------|---|--|
| 2392251-1 | "1060-14-019 9" | |
| 1060-16-0677 | | |
| 2392253-1 | "1060-16-069 9" | |
| 1060-16-0988 | "ZPF0000000 00131910", "1060-16-098 8-LD", "1060-16-098 8-LS", "1060-16-098 8-MS", "1060-16-098 8-L", "1060-16-098 8-M" | |
| 1060-16-0644 | "ZPF0000000 00131907", "1060-16-064 4SAMPLE" | |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.