



09-Jun-2022

PCN #: P-22-022868

Subject : 040 MULTILOCK CONNECTOR

Description of Change : To add source of the connector housing resin, Not any changes, impacts on the products function and performance.

Reason : Product improvement.For Business Contingency Plan. An internal release based on our specifications will be executed before any parts will be delivered, which guarantees the performance. please contact your TE Account Manager for the concerned matter.

Key Dates :

Contact By Date:15-Aug-2022

Implementation Date:15-Aug-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
174056-2			
174057-2	"0-0174057-2"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.