



09-Jun-2022

PCN #: P-22-022867

Subject : 8POS,AMP MCP1.5K,REC. HSG,CODA

Description of Change : For the following parts we have built a duplication tool : 21-1963799

Reason : Customer Request. Customer Request, Dear customer, we hereby inform you about a tool Duplication of a molding tool for the mentioned Part-Numbers. As result of our continuous strive for quality improvements of our production, we hereby inform you upfront about a Duplication tool, which is under construction in order to meet all specification requirements.

Key Dates :

Contact By Date:24-Jun-2022

Implementation Date:24-Jun-2022

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
1-1418480-1			
3-1564542-1			
3-1418480-1			
4-1564542-1			
2-1418479-1			
1-1564542-1			
3-1418479-1			
4-1418480-1			
2-1564542-1			
1-1418479-1			
2-1418480-1			
4-1418479-1			

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.