



# Product Change Notification

Current Date: 19-Apr-2023

## TE Connectivity

**Product Change Notification:** P-23-024413

**PCN Date:** 18-APR-23

**Customer:** TTI, Inc. ( 1305175 )

**Location:** Maisach-gernlinden

**Agreement:** TTI001

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**  
RZ relay series

**Description of Changes**  
The following part numbers are being modified by changing the outside case color from orange to white. Performance, SSA Approvals as well as specified material parameters remain unchanged. Please get in touch with your local TE sales representative in case of open questions.

**Reason for Changes:**  
Product improvement. Dear Customer, you are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts are affected by the change mentioned above!

Estimated Dates:	
<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	16-OCT-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	18-OCT-2024

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1415899-0</a>	NO		TYC1-1415899-0	"RZ01-1C4-D012"			
<a href="#">1-1415899-1</a>	NO		TYC1-1415899-1	"RZ01-1C4-D024"			
<a href="#">1-1415899-3</a>	NO		TYC1-1415899-3	"RZ03-1A4-D005"			
<a href="#">1-1415899-6</a>	NO		TYC1-1415899-6	"RZ03-1A4-D012"			
<a href="#">1-1415899-7</a>	NO		TYC1-1415899-7	"RZ03-1A4-D024"			
<a href="#">1-1415899-9</a>	NO		TYC1-1415899-9	"RZ03-1C4-D005"			
<a href="#">1415899-5</a>	NO		TYC1415899-5	"RZ01-1A4-D024"			
<a href="#">1415899-7</a>	NO		TYC1415899-7	"RZ01-1C4-D005"			
<a href="#">1415899-9</a>	NO		TYC1415899-9	"RZ01-1C4-D009"			
<a href="#">2-1415899-2</a>	NO		TYC2-1415899-2	"RZ03-1C4-D012"			
<a href="#">2-1415899-3</a>	NO		TYC2-1415899-3	"RZ03-1C4-D024"			
<a href="#">2-1415899-4</a>	NO		TYC2-1415899-4	"RZ03-1C4-D048"			
<a href="#">2-1415899-5</a>	NO		TYC2-1415899-5	"RZH3-1C4-D012"			
<a href="#">2-1415899-6</a>	NO		TYC2-1415899-6	"RZH3-1C4-D024"			
<a href="#">2-2071452-4</a>	NO						
<a href="#">2-2158000-9</a>	NO						
<a href="#">3-1415899-5</a>	NO			"RZ02-1C4-D012"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">4-1415899-4</a>	NO		TYC4-1415899-4	"RZ01-1C3-D012"			
<a href="#">4-1415899-7</a>	NO		TYC4-1415899-7	"RZ03-1A3-D005"			
<a href="#">4-1415899-9</a>	NO		TYC4-1415899-9	"RZ03-1A3-D012"			
<a href="#">5-1415899-0</a>	NO		TYC5-1415899-0	"RZ03-1A3-D024"			
<a href="#">5-1415899-2</a>	NO		TYC5-1415899-2	"RZ03-1C3-D005"			
<a href="#">5-1415899-4</a>	NO		TYC5-1415899-4	"RZ03-1C3-D012"			
<a href="#">6-1415899-4</a>	NO			"RZHH-1A4-D005"			
<a href="#">6-1415899-6</a>	NO		TYC6-1415899-6	"RZHH-1A4-D012"			
<a href="#">6-1415899-7</a>	NO		TYC6-1415899-7	"RZHH-1A4-D024"			
<a href="#">7-1415899-7</a>	NO			"RZ03-1C4-D012-R"			
<a href="#">9-1415899-1</a>	NO		TYC9-1415899-1	"RZ03-1A4-D024-R"			
<a href="#">9-1415899-4</a>	NO			"RZ0H-1A4-D012"			



# Product Change Notification

Current Date: 19-Apr-2023

## TE Connectivity

**Product Change Notification:** P-23-024413

**PCN Date:** 18-APR-23

**Customer:** TTI, Inc. ( 3057778 )

**Location:** Maisach-gernlinden

**Agreement:** Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### General Product Description:

RZ relay series

### Description of Changes

The following part numbers are being modified by changing the outside case color from orange to white. Performance, SSA Approvals as well as specified material parameters remain unchanged. Please get in touch with your local TE sales representative in case of open questions.

### Reason for Changes:

Product improvement. Dear Customer, you are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts are affected by the change mentioned above!

### Estimated Dates:

<b>Last Order Date</b> (Obsolete Parts Only):	<b>First Date To Ship</b> (Changed Parts Only):
	16-OCT-2023
<b>Last Ship Date</b> (Obsolete Parts Only):	<b>Last Date for Mixed Shipments:</b> (Changed Parts Only):
	18-OCT-2024

### Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">1-1415899-0</a>	NO		TYC1-1415899-0	"RZ01-1C4-D012"			
<a href="#">1-1415899-1</a>	NO		TYC1-1415899-1	"RZ01-1C4-D024"			
<a href="#">1-1415899-3</a>	NO		TYC1-1415899-3	"RZ03-1A4-D005"			
<a href="#">1-1415899-6</a>	NO		TYC1-1415899-6	"RZ03-1A4-D012"			
<a href="#">1-1415899-7</a>	NO		TYC1-1415899-7	"RZ03-1A4-D024"			
<a href="#">1-1415899-9</a>	NO		TYC1-1415899-9	"RZ03-1C4-D005"			
<a href="#">1415899-5</a>	NO		TYC1415899-5	"RZ01-1A4-D024"			
<a href="#">1415899-7</a>	NO		TYC1415899-7	"RZ01-1C4-D005"			
<a href="#">1415899-9</a>	NO		TYC1415899-9	"RZ01-1C4-D009"			
<a href="#">2-1415899-2</a>	NO		TYC2-1415899-2	"RZ03-1C4-D012"			
<a href="#">2-1415899-3</a>	NO		TYC2-1415899-3	"RZ03-1C4-D024"			
<a href="#">2-1415899-6</a>	NO		TYC2-1415899-6	"RZH3-1C4-D024"			
<a href="#">2-2071452-4</a>	NO						
<a href="#">2-2158000-9</a>	NO						
<a href="#">3-1415899-5</a>	NO			"RZ02-1C4-D012"			
<a href="#">4-1415899-4</a>	NO		TYC4-1415899-4	"RZ01-1C3-D012"			
<a href="#">4-1415899-9</a>	NO		TYC4-1415899-9	"RZ03-1A3-D012"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5-1415899-0</a>	NO		TYC5-1415899-0	"RZ03-1A3-D024"			
<a href="#">5-1415899-2</a>	NO		TYC5-1415899-2	"RZ03-1C3-D005"			
<a href="#">5-1415899-4</a>	NO		TYC5-1415899-4	"RZ03-1C3-D012"			
<a href="#">6-1415899-6</a>	NO		TYC6-1415899-6	"RZHH-1A4-D012"			
<a href="#">6-1415899-7</a>	NO		TYC6-1415899-7	"RZHH-1A4-D024"			
<a href="#">7-1415899-7</a>	NO			"RZ03-1C4-D012-R"			
<a href="#">9-1415899-1</a>	NO		TYC9-1415899-1	"RZ03-1A4-D024-R"			
<a href="#">9-1415899-4</a>	NO			"RZ0H-1A4-D012"			