



04-May-2023

PCN #: P-23-024487

Subject : Controlled Electrical Cables as per attached parts list

Description of Change : Tyco Electronics UK Ltd (TE Connectivity) have made a change to the Chemically Foamed Polyethylene insulation material used in some of our controlled electrical cables. This is a supplier-initiated change, as a supplier will no longer be able to provide an old grade of material due to a chemical blowing / foaming agent, which has been identified as a Substance of Very High Concern (SVHC) as per EU REACH regulations. The new greener Chemically Foamed Polyethylene insulation material complies with EU REACH regulations. Validation testing based on our specifications has been completed, which shows no change in the performance of the concerned products. There is a minor visual change to the colour of the finished products. See pictures below for more details.

Reason : Product improvement.

Key Dates :

Contact By Date:04-May-2023

Implementation Date:04-May-2023

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CQ85873001	"EPD121857 BCK0193"		
CQ07273001	"EPD116370 A/1(M)"		
4400773001	"4-1193307- 7", "7524A1311- 0"		
CT70013001	"0022E0311- 0(2M)"		
6771553001	"5024A1P11- 9(CO)", "3- 1195324-5"		
CQ41903001	"EPD116255 A- OCK0547/2"		

CQ72753001	"EPD121328 A"		
6148333001	"1194860-2", "EPD63054C"		
5684253001	"7-1194513- 3", "EPD84052Q "		
2999853001	"6-1192270- 1", "EPD43063A "		
CQ67833001	"EPD120650 A/4(CO)"		
A778873001	"1-1201161- 3", "EPD93790A/ 1(CO)"		
CD38803001	"EPD66813R/ 1-1L(CO)", "5-1899272- 0"		
CQ82483001	"EPD121857 ACK0193"		
CD18353001	"EPD106112 BCK0162", "8-1899171- 5"		
2262433001	"0020D0P11- 9(CO)", "1- 1191666-0"		
F244303001	"EPD98487C CK0339", "8- 1200878-7"		
4280513001	"4-1193220- 5", "5020A1311- 0(CO)"		
C387673001	"3-1201713- 5", "EPD67422A CK0277"		
200121W002	"6-1191449- 2", "5019D3P18- 1L"		
A328983001	"5-1200812- 8", "EPD99292A/ 1-1L/9(CO)"		

420106-002	"1193165-4", "5020A3311-0"		
5920593001	"5012A3P11-9(CO)", "7-1194682-6"		
F066903001	"EPD99530A/1-9(CO)", "2-1200885-1"		
CT69753001	"EPD114765 A"		
0672243001	"7-1199555-4", "EPD95224Q(CO)"		
5487033001	"7-1194318-3", "EPD40295Q"		
CD71413001	"7526A1P18-9(CO)", "7-1899430-5"		
CT67183001	"EPD104317 C"		
E172733001	"7526A1P11-9(CO)", "3-1200600-3"		
CD48133001	"0024A0311-9(2M)", "1-1899323-3"		
CQ37893001	"EPD118396 A"		
CQ93043001	"EPD108750 ACK0308"		
CD50983001	"EPD107869 A/1(CO)", "8-1899336-0"		
2814313001	"1-1192085-9", "5012A3811-0(CO)"		
CD12423001	"7528A1P18-9(CO)", "7-1899146-2"		
CD31543001	"120-OHM-2SJR-22-1L(CO)", "1899237-6"		
CD53483001	"EPD107992 A", "1-1899349-0"		

4404993001	"5-1193311-5", "5030A1314-0"		
CQ21063001	"EPD117760A"		
815137-000	"7524A1811-0", "3-1196352-0"		
D815803001	"6-1200498-0", "EPD96117A"		
3248873001	"7-1192458-6", "EPD24187D/1-0(M)"		
CQ54533001	"EPD107550GCK0202/2"		
1013913001	"1-1190742-3", "EPD24135A"		
E153103001	"3-1201320-7", "EPD95289L/1-9(CO)"		
2002083001	"6-1191450-4", "7524A1P11-1L"		
9190933001	"5-1197132-1", "EPD70340L/1-9"		
C955393001	"6-1200919-1", "EPD99442B"		
CQ67803001	"EPD120650A/1-9(CO)"		
CT69713001	"EPD114765A/1-1L(CO)"		
D426553001	"7-1202050-6", "EPD101754B/2(CO)"		
EQ00263001	"EPD121839ACK0308"		
C525563001	"9-1200885-2", "EPD99529A/1-1L(CO)"		

A231303001	"3-1201416-5", "EPD97000A CK0900"		
CQ76103001	"EPD121495 A"		
A502873001	"4-1200884-7", "EPD60608C/ 1-9(CO)"		
5391813001	"1194231-8", "9524A1P11-1L(CO)"		
5788673001	"7-1197892-1", "EPD71607A/ 2(CO)"		
CQ91643001	"0024K1811-0(M4)(FS)"		
CQ05423001	"EPD117331 A"		
CT36443001	"EPD113282 A", "9-1899562-4"		
E823283001	"EPD104315 A/1-9(CO)"		
CQ41893001	"EPD116262 B-0CK0547/2"		
CT92783001	"EPD116377 A"		
7796773001	"3-1196067-2", "EPD78122A "		
CD46603001	"5026C3814-0", "6-1899315-7"		
CQ04193001	"EPD109318 Q/1-9(M2)"		
6551363001	"9-1198297-8", "EPD7032B/1-1L4(CO)"		
4400693001	"3-1193307-4", "5026A1317-0(500)"		

E010613001	"9-1201142-2", "EPD94822L/2(CO)"		
4387893001	"7-1193297-4", "5018D3P11-9(CO)"		
A457833001	"3-1201747-3", "EPD98865Q/1-1L(CO)"		
CQ67773001	"EPD120650A/1-3(CO)"		
1792913001	"3-1191303-9", "5020A1P11-9(FS)"		
D661573001	"8-1200760-0", "EPD94823L/2(CO)"		
CT82783001	"EPD115671A"		
F410203001	"2-1201263-5", "0024A0311-91(CO)"		
EQ07243001	"0024F0611-9(CO)"		
C995233001	"1201320-4", "EPD95289L/2(CO)"		
4406803001	"4-1193313-9", "7528A1314-9"		
C950363001	"1200886-7", "EPD99528A/2(CO)"		
6353413001	"8-1195023-1", "EPD6035A/1-1L(CO)"		
4200793001	"7-1193164-5", "5028A3318-9"		
EQ05153001	"EPD122871A/3-1/9(CO)"		
CQ83373001	"EPD121047A"		

1101353001	"4-1190804-5", "EPD78120A"		
E509923001	"2-1201498-8", "EPD98738L/2(CO)"		
D349043001	"9-1200858-0", "EPD96598A/3(CO)"		
4201243001	"3-1193165-5", "5012A3311-0"		
607305-000	"5-1194803-9", "EPD31322B"		
CD76933001	"EPD105601 A/1-6(CO)", "1899449-4"		
2246673001	"9-1191654-9", "EPD31475A-OBS"		
9275313001	"7-1197192-6", "EPD85875A/1-9(CO)"		
2009423001	"0024A0P11-1L", "8-1191456-2"		
1437783001	"5-1191039-6", "EPD29057A"		
CT73953001	"EPD114354 A/1-0(4M)"		
EQ10193001	"EPD35767Q CK0647"		
F266063001	"EPD25986A/1-9(CO)", "4-1201019-9"		
CD56713001	"0024K1811-0", "3-1899364-6"		
C576213001	"6-1200884-2", "EPD60603C/1-1L(CO)"		

C77266-000	"6-1202050-1", "EPD101747 B/2(CO)"		
CQ92593001	"EPD120794 ACK1100"		
3375233001	"1-1192548-3", "EPD76688Q "		
8965773001	"7-1196970-8", "EPD69569B/ 2(CO)"		
F271513001	"EPD96117A/ 1(CO)", "8- 1200501-6"		
7436423001	"8-1195801-0", "EPD28251A "		
3224453001	"1-1192441-1", "7522A1P11- 1L(CO)"		
CQ07483001	"EPD43063A/ 1(CO)"		
5877533001	"5020A1P11- 9(CO)", "4- 1194651-3"		
2475493001	"0022D0311- 9(CO)", "5- 1191815-7"		
9443513001	"1197310-4", "EPD35589A "		
CQ93543001	"EPD44091Q CK0202"		
CQ27943001	"EPD113842 Q/1- 1LCK0399/1"		
D541233001	"1200338-4", "EPD98008L/ 1-9(CO)"		
CQ83833001	"EPD118179 A/3(CO)"		
CQ95103001	"EPD122259 A"		
CQ67783001	"EPD120650 A/1-5(CO)"		

F045423001	"EPD99114A/ 1-1L/9(CO)", "9-1200811- 5"		
C929223001	"1-1200878- 3", "EPD98516B CK0339"		
8933433001	"0024A0311- 0(FS)", "5- 1196948-1"		
440680-000	"4-1193313- 8", "7528A1314- 9"		
EQ08403001	"XXX- 5024D3314- 0"		
4861673001	"2-1193638- 2", "5024A1311- 0(FS)"		
6430333001	"9-1195080- 8", "EPD67526M "		
440107-002	"1-1193308- 7", "5028A1314- 0"		
8103513001	"2-1196297- 6", "EPD32183C"		
CT65463001	"EPD114512 A"		
CD37073001	"5024C1P11- 9(CO)", "2- 1899261-5"		
CQ42083001	"EPD119031 A/2(CO)"		
CQ41983001	"EPD119030 A/4(CO)"		
1266373001	"5-1190920- 3", "EPD77622L/ 1-1L(CO)"		
CQ72513001	"EPD121304 A"		
2008513002	"0020D0P11- 9", "7- 1191455-3"		

CQ87583001	"EPD120794 ACK0193"		
C568353001	"4-1200755- 9", "EPD42233A/ 2-1L(CO)"		
CQ34083001	"EPD117756 ACK0298"		
CD29313001	"CLFH400/1(FS)", "9- 1899222-5"		
5942233001	"1194698-7", "EPD33307Q "		
CT94893001	"EPD116422 A/1-6(CO)"		
CT92533001	"EPD116101 A"		
1324513001	"6-1190962- 8", "EPD44031S/ 2-1L(CO)"		
CT94903001	"EPD116422 A/2(CO)"		
CQ40143001	"CLFH-400"		
EQ06033001	"EPD121860 B/2(CO)"		
CQ41953001	"EPD119030 A/5(CO)"		
CQ72873001	"EPD121340 A"		
CT98843001	"EPD115851 A"		
5989013002	"6-1201791- 4", "0024F0611- 9"		
CQ17973001	"EPD117888 A/1(CO)"		
EQ14063001	"EPD108173 ACK0308/3"		
2598313001	"8-1191900- 2", "7524A1311- 0(CO)"		
5582983001	"7-1198928- 8", "EPD78640L CK0121/4"		

4408083001	"5-1193314-6", "9530A1318-9"		
CT75893001	"EPD115268 A"		
CT74203001	"EPD114357 A/1-9(CO)"		
CT04913001	"EPD113319 A/1(CO)", "2-1899555-8"		
4145573001	"9-1193124-8", "EPD65700F/1(CO)"		
EQ02393001	"EPD122640 A/1-1L(CO)"		
A201023001	"5026A1811-0(8M)", "1-1200160-4"		
7636953001	"9-1195945-8", "EPD76441L/1(CO)"		
6073053001	"6-1194803-0", "EPD31322B"		
794567W002	"2-1196151-2", "EPD35077A"		
CQ07223001	"EPD117416 ACK0355"		
EQ02413001	"EPD122640 A/2(CO)"		
A121953001	"1-1201508-5", "EPD101626 A"		
4828353001	"8-1193613-2", "EPD60604B"		
CD84013001	"EPD109365 A/4(CO)", "1-1899478-0"		
CQ52733001	"EPD118745 ACK0202/3"		
CQ49573001	"EPD100582 BCK0355"		

420115-000	"2-1193165-4", "5026A3311-0"		
581269-000	"2020E0811-0", "8-1194605-1"		
3346573001	"1192528-3", "7524A1311-0(FS)"		
CD57673001	"0024K1811-0(4M)", "2-1899369-3"		
CQ21023001	"EPD117756 A"		
440808-000	"5-1193314-5", "9530A1318-9"		
5888793001	"9-1194659-3", "9526A1311-0"		
5354893001	"3-1194204-8", "EPD72947A/2(CO)"		
5141673001	"2-1194039-9", "EPD67526M/1"		
7227173001	"5-1195650-6", "EPD40890G"		
7995633001	"6-1196181-8", "EPD60480L/1(CO)"		
CD76893001	"EPD105601 A", "9-1899448-9"		
CQ95353001	"EPD121049 A"		
6658953001	"4-1195246-6", "EPD63054C/1-6"		
0551773001	"1-1190421-0", "EPD38335A"		

EQ05513001	"EPD122014 ACK0193/1"		
4576943001	"8-1199198- 2", "EPD95011L/ 1-0(7M)"		
CD16843001	"EPD104312 B/1-9(CO)", "8-1899162- 1"		
200943-000	"8-1191456- 6", "5012A3P11- 1L"		
CQ83683001	"EPD116265 A/1-6(CO)"		
0014393001	"6-1190010- 2", "EPD69568A/ 1-1L"		
CQ03023001	"EPD24357A CK0298/1"		
D023093001	"4-1201142- 9", "EPD94822M /1-9(CO)"		
CQ91673001	"0024K1811- 0(M3)"		
CD31333001	"CLFH179", "1899236-2"		
CQ60893001	"EPD116262 A/3(CO)"		
CQ48103001	"5012A3811- 0CK0016"		
CQ76613001	"EPD117755 ACK0298/1"		
CQ95403001	"EPD121056 A"		
E020763001	"9-1201142- 3", "EPD94821M /2(CO)"		
CT82773001	"EPD115671 A/2(CO)"		
F043923001	"9-1201288- 2", "EPD96642A "		

CD15653001	"EPD86888C/ 1-1L(CO)", "8-1899160- 9"		
3157093001	"9-1192388- 7", "EPD91802A "		
1371113001	"9-1190993- 8", "EPD40890H "		
5543973001	"4-1194376- 3", "EPD60326A/ 1-9(CO)"		
4400103002	"3-1193306- 9", "5024A1314- 0"		
4402513001	"6-1193309- 9", "5020A1111- 9"		
CQ86983001	"EPD120896 B/1-9(M)"		
9170713001	"5-1197118- 0", "EPD39096E"		
D325533001	"7-1202050- 3", "EPD101753 B/1-9(CO)"		
E126983001	"3-1201284- 5", "EPD99442B CK0400"		
4407883001	"4-1193314- 2", "5030A1318- 9"		
7746533001	"3-1196032- 9", "EPD38445Q "		
CT62673001	"EPD96873B"		
CQ67823001	"EPD120650 A/3(CO)"		
4405623001	"2-1193312- 2", "5018A1311- 0"		

0644013001	"6-1190486-1", "EPD76441L/ 2-9(CO)"		
E527573001	"EPD104310 A/1-9(CO)"		
3323353001	"1192511-5", "EPD44306A/ 1"		
CQ73423001	"EPD121379 A"		
CT75883001	"EPD115267 A"		
2009413001	"0024A0P11- 9", "7- 1191456-8"		
440672-000	"3-1193313- 0", "7520A1311- 0"		
E947903001	"6-1200929- 3", "EPD99111A CK0339"		
CQ98113001	"EPD115373 ACK1100"		
4451823005	"2524E0311- 9", "8- 1193345-1"		
CQ56163001	"EPD116267 A/1-3(CO)"		
EQ03443001	"EPD122537 ACK1100"		
CQ99473001	"CLFH179CK 1200"		
144278-000	"8-1191042- 8", "7820G0111- 9"		
440788W004	"4-1193314- 6", "5030A1318- 9"		
D935083001	"2-1200338- 6", "EPD93086R CK0226"		
EQ10143001	"EPD122871 ACK0654/1"		
CQ77113001	"EPD121138 ACK0547/2"		

4400603006	"1193307-1", "5024A1311-0"		
2958893001	"7-1192241-7", "5020A1P11-9"		
440060W012	"1193307-7", "5024A1311-0"		
798383-000	"2530A0614-9", "6-1196175-6"		
EQ01253001	"EPD122713 A"		
7418513001	"4-1195789-5", "9528A1P17-1L(CO)"		
7392613001	"5-1195770-2", "EPD60301B"		
CD17373001	"7528A1318-0(FS)", "1-1899165-3"		
CQ87513001	"EPD116265 A-0CK0547/2"		
604207-000	"1194781-6", "7520A1811-0"		
CT95703001	"EPD116490 A"		
CQ30063001	"7524A1311-0(M1)CK2240"		
6012523001	"2-1199954-6", "EPD2028E/1-1L0(CO)"		
0903973001	"1-1197921-3", "EPD91568Q/1-9(CO)"		
440101W003	"1-1193308-2", "9530A1318-0"		
CD62363001	"EPD108341 A/2(CO)", "7-1899385-6"		

D498853001	"2-1201800-8", "0024F0P11-9(CO)"		
0789433001	"1190587-3", "EPD73307R/1-6(CO)"		
F705083001	"5-1201791-3", "EPD101039L/1-1L(CO)"		
CT02393001	"CLFH-179-0(7M)", "1-1899549-2"		
CQ82603001	"EPD121661A/1-9(CO)"		
CQ56193001	"EPD116267A/2(CO)"		
3110073001	"1-1192354-0", "EPD44031S/2-9(CO)"		
CD84253001	"EPD107550A/2(CO)", "3-1899479-7"		
144278K002	"9-1191042-2", "7820G0111-9"		
CQ86403001	"EPD120887B"		
CQ91263001	"0020D0311-9(M)"		
E030303001	"3-1201320-1", "EPD95289L/1-1L(CO)"		
420106W003	"1193165-6", "5020A3311-0"		
CT82833001	"EPD96718CCK0254"		
CT99633001	"EPD109318QCK0456/3"		
CQ78723001	"EPD121586A"		
CD31503001	"EPD106743A/4(CO)", "7-1899236-5"		

4233653001	"2-1193188-4", "7528A1P14-9(CO)"		
1490333001	"6-1191077-0", "EPD46419Q/1-9(CO)"		
3H07103001	"1-1193004-5", "EPD20698A"		
CD40733001	"EPD107072A", "8-1899287-0"		
CD53543001	"EPD107883B/1(CO)", "2-1899350-6"		
C800783001	"7-1201321-8", "EPD100317ACK0900"		
4044043001	"6-1199211-6", "EPD95412Q/1-9(CO)"		
2289943001	"5-1201021-6", "EPD100319A/2(CO)"		
CD76883001	"EPD105568A", "9-1899448-8"		
CQ51963001	"EPD119924A/1-6(CO)"		
D534643001	"EPD104313A/1-9(CO)"		
EQ06263001	"EPD119554A"		
CD00993001	"EPD104861A/2(CO)", "3-1899094-8"		
CD37403001	"7-1899264-0", "EPD104100A/1(CO)"		
5155673001	"2-1194049-3", "EPD65782L"		

5614513001	"8-1194434-8", "EPD69569A/1-9"		
CQ06963001	"EPD116448A"		
CQ45853001	"EPD67422ACK0206/2"		
EQ02823001	"EPD121962ACK0624"		
CQ41823001	"EPD116262B/1-9(CO)"		
CD69983001	"5026C1314-06(CO)", "8-1899423-8"		
CD59683001	"EPD106482A/1-1L(CO)", "3-1899377-8"		
A914083001	"EPD104312A/1-1L(CO)"		
EQ05193001	"EPD122871A/3-2/5(CO)"		
7372113001	"5012A3311-0(M)", "9-1195755-2"		
CQ60593001	"0024B0P11-9(CO)"		
CQ31993001	"0024K1811-0(M)"		
CT69743001	"EPD114765A/3(CO)"		
C315313001	"7-1201929-7", "EPD74283ACK0365"		
CQ97323001	"EPD120656A/1-6(CO)"		
2000103002	"0022D0P11-1L", "5-1191448-0"		
CD85043001	"EPD31475QCK0206/1", "5-1899482-1"		
CQ96463001	"EPD122430A"		

2000743001	"1-1191449-9", "5024A1P12-1L"		
2809253001	"5-1192080-0", "5024A1P11-1L(CO)"		
440499-000	"5-1193311-4", "5030A1314-0"		
CQ70133001	"EPD118341 B/1-0(CO)"		
C060573001	"9-1201422-2", "EPD96295Q/1-9(CO)"		
CQ31953001	"EPD115269 A"		
CQ88253001	"7520A5611-9CK0635"		
8877113001	"6-1196906-0", "EPD69568A/2"		
5375753001	"9-1194218-9", "EPD31173A/1-9(CO)"		
A365153001	"8-1200826-5", "EPD98487C"		
0301643001	"3-1197946-1", "EPD90786Q/1-9(CO)"		
F040023001	"EPD99036A", "9-1200756-8"		
5219113001	"5026A1311-0-M", "6-1194101-9"		
6474633001	"1-1195112-1", "EPD25640A"		
CD17513001	"EPD105273 A", "9-1899165-4"		

CQ04113001	"EPD109318 Q/1- 9(M2)(FS)"		
CQ18873001	"EPD117888 A"		
CD54463001	"0024K1811- 0(2M)", "4- 1899355-8"		
C112163001	"3-1201192- 9", "EPD92473A "		
1372693001	"6-1190995- 2", "EPD90041A/ 1-9(CO)"		
1192453001	"5-1190867- 9", "5012A3P11- 1L(CO)"		
1069893001	"4-1190781- 3", "EPD83644L/ 2-1L/9(M)"		
CD51413001	"EPD107356 A/1-9(CO)", "4-1899338- 8"		
C949883001	"1201342-1", "EPD98739L/ 1-9(CO)"		
CD72913001	"EPD108704 ACK0210", "3-1899435- 6"		
CQ72733001	"EPD121326 A"		
6311793001	"6-1197825- 7", "7518A1P11- 9(CO)"		
CT69683001	"EPD114764 A/2(CO)"		
4201153001	"2-1193165- 5", "5026A3311- 0"		
CD93803001	"6-1899514- 5", "EPD111034 A/1-9(CO)"		

CQ83743001	"EPD118179 A/1-96(CO)"		
6735993001	"9-1195298- 4", "EPD67887L"		
CQ41813001	"EPD116262 B/1-6(CO)"		
EQ10213001	"EPD60947Q CK0647/1"		
2863093001	"8-1192168- 6", "EPD22634B"		
A813343001	"0022E0P11- 1L(CO)", "1- 1200481-9"		
CD58723001	"7530A1P18- 9(CO)", "9- 1899371-1"		
2904013001	"7-1192201- 1", "EPD37229A "		
CQ11893001	"EPD117498 A/1-1L(CO)"		
CQ17503001	"EPD117861 A"		
334657-000	"1197969-1", "7524A1311- 0(FS)"		
440026-000	"2-1198283- 2", "5020A1311- 9"		
0677213001	"3-1190510- 6", "EPD25986B/ 1-1L(CO)"		
CD43333001	"0028G1P14- 1L(CO)", "2- 1899300-4"		
1555713001	"1191124-4", "EPD67526M /1-0(M)"		
4418383001	"1193322-5", "5020A1311- 0(M)"		
CT67303001	"EPD4673H(S 82M)"		
CQ99573001	"EPD101753 BCK0446"		

1330133001	"1190966-4", "EPD64118L"		
CQ19293001	"EPD118014 A/1-9(CO)"		
CQ74593001	"EPD118341 C/1-4(CO)"		
3962683001	"2524E0P11- 9", "3- 1192972-3"		
A816013001	"6-1201726- 7", "7530A1814- 0"		
CQ72963001	"EPD121348 A"		
CQ22193001	"EPD106513 ACK0213/3"		
7023233001	"9-1195510- 7", "EPD66401A "		
2485113001	"6-1191822- 6", "7522A1811- 0"		
CQ83773001	"EPD118179 A/1-5(CO)"		
CQ31913001	"EPD117254 A"		
3529793001	"2530A1318- 9(CO)", "4- 1192651-6"		
7766533001	"4-1196046- 8", "EPD67888L"		
7462343001	"9-1197924- 4", "7530E1114- 0(CO)"		
CT01933001	"EPD113292 A/1(CO)", "8- 1899547-3"		
3711143001	"3-1198306- 5", "9530E1P14- 1L(CO)"		
4418063001	"8-1193321- 9", "5024A1311- 0(M)"		

C922243001	"8-1201321-1", "EPD98739L"		
CQ31983001	"EPD115512 A"		
CD58413001	"EPD108173 A/1(CO)", "6- 1899370-5"		
EQ07213001	"EPD123088 A"		
CQ45573001	"7528F5614- 9(M)"		
EQ05213001	"EPD122871 A/3-3/9(CO)"		
CQ83703001	"EPD116265 A/1-0(CO)"		
CT95963001	"EPD116546 A/1-9(CO)"		
1506313001	"9-1191088- 8", "EPD46419Q "		
CQ87023001	"EPD114955 A"		
D099293001	"1-1201345- 8", "EPD101254 A"		
F345173001	"1201167-5", "EPD100566 A/1-1L(CO)"		
CQ17493001	"EPD117860 A"		
C416523001	"2-1201142- 9", "EPD94822M /1-1L(CO)"		
E330723001	"8-1201461- 8", "EPD4045- C/4(CO)"		
2288493001	"4-1191683- 9", "EPD69569A/ 2"		
CD17673001	"0024A0311- 9(4M)", "1- 1899166-8"		
CQ95873001	"EPD122360 A"		

F933853001	"EPD98957B/ 2(CO)", "2- 1200773-0"		
F265233001	"3-1201426- 0", "EPD96685Q/ 1-9(CO)"		
CD51253001	"0024E0P11- 9(CO)", "8- 1899337-9"		
D551283001	"6-1201425- 2", "EPD96685Q/ 1-1L(CO)"		
440010W001	"4-1193306- 1", "5024A1314- 0"		
A102493001	"6-1201018- 5", "EPD60608D "		
A478223001	"2524E0P11- 1L(SFS)", "2- 1200676-7"		
CQ06993001	"EPD116370 A"		
9345953001	"6-1197241- 8", "EPD68346Q "		
D199013001	"1201727-4", "7530A1P14- 9(CO)"		
D349783001	"9-1201148- 5", "EPD95079A/ 1-9(M)"		
420115W003	"2-1193165- 7", "5026A3311- 0"		
4838333001	"1-1193621- 0", "EPD24357A "		
CQ86213001	"EPD84488A CK0558"		
CT89503001	"EPD116118 A/1-9(CO)"		

4408373001	"8-1193314-3", "7530A1318-9"		
E260793001	"9-1200884-5", "EPD99528A/1-1L(CO)"		
2948313001	"6-1192233-9", "EPD46612Q"		
0484633001	"3-1190372-3", "EPD4673G/2-1L"		
6120093001	"5020A3311-96(CO)", "1194839-9"		
419187-000	"2-1197969-1", "7524A1P11-9(FS)"		
CQ74893001	"EPD117248 ACK0298/1"		
CQ98703001	"EPD122536 A"		
F212383001	"2-1201424-0", "EPD96295Q/1-1L(CO)"		
8530253001	"6-1196649-6", "EPD25986C/1-1L(CO)"		
CQ83563001	"EPD121866 ACK0547/2"		
5517793001	"4-1194361-6", "7820G0P11-9(CO)"		
CQ31233001	"EPD118470 A"		
CT73963001	"EPD114354 A"		
CQ12803001	"EPD114879 A"		
CQ72503001	"EPD121303 A"		
EQ05063001	"EPD122871 ACK0654"		

9458733001	"2524E0P14-9(CO)", "2-1197320-4"		
CD29653001	"EPD106662 A", "5-1899224-7"		
CD48793001	"EPD107297 A", "1-1899326-5"		
EQ06043001	"EPD121860 B/3(CO)"		
CT95423001	"EPD115891 A"		
CQ13723001	"EPD117488 A"		
1147053001	"1190836-5", "EPD69713L"		
CT89483001	"EPD116119 A"		
4191873001	"2-1193158-0", "7524A1P11-9(FS)"		
440499W002	"5-1193311-6", "5030A1314-0"		
5848243001	"1199983-5", "EPD96879Q/1-N(CO)"		
CQ78733001	"EPD121587 A"		
CD16623001	"EPD105062 B", "3-1899162-8"		
CD14953001	"EPD105951 A/1-2(CO)", "2-1899157-9"		
0160993001	"1190126-1", "EPD65055A CK0078"		
5992353001	"3-1194737-9", "EPD62225Q/1-N(CO)"		
C608913001	"7524A1311-0(3M)"		
CQ70173001	"EPD118341 B/1-6(CO)"		

1364233001	"1190989-9", "5020A3811-0"		
2665283001	"5-1199910-0", "EPD66569Q/1-1L(CO)"		
0683833001	"2-1190515-1", "EPD87667A/4-0"		
CD45773001	"EPD107343A", "9-1899311-0"		
CT73173001	"EPD114823A"		
EQ05053001	"EPD122871A/4(CO)"		
CT72193001	"EPD115106QCK0456"		
CT94883001	"EPD116422A/1-9(CO)"		
CQ45153001	"CLFH-179-0(M)"		
7783873001	"6-1196058-5", "EPD29210A"		
2115953001	"8-1191532-6", "7518A1811-0(CO)"		
762893-000	"5-1195940-3", "EPD26995Q"		
CQ72333001	"EPD121286A"		
CT95993001	"EPD116546A/3(CO)"		
A706343001	"EPD104311A/1-1L(CO)"		
E426383001	"EPD104345A/1-1L(CO)"		
200010-000	"0022D0P11-1L", "4-1191448-9"		
CQ33343001	"EPD118336A"		

D335453001	"1200369-7", "EPD97000A "		
445182-000	"2524E0311- 9", "7- 1193345-9"		
420079W002	"7-1193164- 6", "5028A3318- 9"		
CT66913001	"5030A1318- 0(CO)"		
EQ01333001	"EPD117603 ACK0624"		
A215413001	"EPD104448 A/2(CO)", "5- 1899067-0"		
1054853001	"1190771-7", "EPD61457A "		
8991113001	"5-1196988- 4", "EPD20662B/ 2(CO)"		
1581553001	"6-1191142- 5", "EPD60844C"		
490097W005	"4-1193666- 5", "9530E1014- 0"		
CQ17363001	"2024A0111- 9(M)"		
CT89473001	"EPD116118 A"		
3292153001	"1192489-1", "EPD20499Q/ 1-9(CO)"		
CD43043001	"2024A0111- 9", "6- 1899298-3"		
1844293001	"1-1191339- 3", "9530E1014- 0(CO)"		
CQ74643001	"EPD118341 C"		
CQ80713001	"EPD91157L CK0624"		
CQ95323001	"EPD121045 A"		

9615153001	"8-1197438-1", "EPD20662B/4-2(CO)"		
E561433001	"6-1201741-0", "EPD98865Q"		
420030K003	"2-1193164-9", "5019D3318-0"		
CT75233001	"EPD114938A"		
5628253001	"8-1194446-8", "EPD63054C/2"		
CQ77123001	"EPD121137ACK0547/2"		
440838-000	"8-1193314-4", "5018D3311-0"		
1049743001	"5-1199206-4", "EPD37229ACK0030"		
CQ73543001	"EPD121394A"		
200165W002	"3-1191450-0", "5028A1P14-1L"		
CD93913001	"EPD111033A/1-1L(CO)", "7-1899514-8"		
CQ77983001	"0024A0311-1L/9-0(CO)"		
CT68823001	"7522D5311-0CK1150"		
CT69703001	"EPD114764A"		
1723693001	"8-1191253-3", "EPD32856A/2(M)"		
CQ34223001	"EPD118757A"		

CQ22603001	"EPD109382 ACK0298/2"		
CQ74613001	"EPD118342 C/1-2(CO)"		
CQ86263001	"EPD121857 BCK0193/1"		
3H00583001	"1-1193003- 4", "EPD4044"		
CQ73033001	"EPD121355 A"		
3289523001	"2-1200147- 4", "EPD93086R/ 1-1L(CO)"		
1305073001	"9-1190947- 2", "7518A1P11- 1L(CO)"		
CQ95273001	"2018A1811- 0"		
D537623001	"9-1201508- 1", "EPD101624 A"		
EQ00893001	"EPD67422A CK0503/2"		
9484583001	"6-1198918- 2", "EPD67526M /1-0(19M)"		
CQ82573001	"EPD121661 A"		
CQ70293001	"EPD120998 A"		
CD46983001	"5026C3P14- N(CO)", "6- 1899316-1"		
317185-000	"2-1192403- 2", "5012A3811- 0"		
5666293001	"5-1194474- 9", "CLFH179(S5 0)"		
CD93903001	"EPD111034 A/1-1L(CO)", "7-1899514- 7"		

4601893001	"7-1193451-8", "EPD77127L/1-9(CO)"		
CQ11933001	"EPD117497 A/2(CO)"		
3991533001	"5-1192994-7", "5022A1P11-9(CO)"		
CT69783001	"5020A1311-0(3M)"		
CQ36033001	"EPD105273 ACK0298/1"		
9488933001	"1197811-1", "EPD79182A/1-9(CO)"		
EQ06223001	"EPD44091Q CK0202/1"		
CQ61083001	"2530A0P14-1L(CO)"		
CQ27973001	"EPD113842 Q/1-9CK0399/4"		
A178843001	"2524E0311-0(6M)", "2-1200752-4"		
4689953001	"1193515-3", "EPD80972A"		
D737523001	"EPD104319 A/2(CO)"		
CQ07513001	"EPD64983B CK1030"		
739261-000	"5-1195770-1", "EPD60301B"		
F04392-000	"9-1201288-1", "EPD96642A"		
F484333001	"2-1201403-2", "EPD99112A CK0900"		
2699533001	"5-1191992-3", "EPD40487B"		
E960333001	"5020A1311-0(2M)", "6-1200431-2"		

CQ75573001	"EPD67422A CK0503/1"		
0745493001	"1-1197921- 9", "EPD91568Q/ 1-1L(CO)"		
EQ14373001	"EPD106672 ACK0193"		
D186573001	"6-1202050- 7", "EPD101744 B/1-1L(CO)"		
CT69773001	"EPD114767 A"		
CQ82623001	"EPD121661 A/2(CO)"		
9013253001	"7522A1311- 0(S)", "8- 1197005-3"		
8241703001	"8-1200285- 9", "EPD35077A CK0277"		
6330733001	"5020A3811- 0(CO)", "1- 1195008-9"		
8713013001	"1-1196781- 9", "EPD40218Q "		
5093703001	"4-1198950- 1", "EPD90687A "		
CQ86223001	"EPD98738L CK0558"		
4348813001	"2-1193270- 2", "EPD44774M /1-0"		
A736753001	"1201761-9", "EPD101186 A/1-9(CO)"		
440088-000	"7-1193307- 2", "7528A1318- 0"		
CQ17413001	"EPD117867 A/1(CO)"		

7928773001	"2524E0P11-1L(CO)", "5-1196139-7"		
CQ95393001	"EPD121055 A"		
9536653001	"4-1197384-6", "EPD60608B"		
179291-000	"4-1197969-4", "5020A1P11-9(FS)"		
3438753001	"2-1192590-6", "5020A1311-02(CO)"		
1269273001	"6-1190922-9", "EPD69568B/1-9(CO)"		
CT55943001	"EPD113887 A"		
2063573001	"1191496-7", "EPD60651B"		
CT88083001	"EPD115994 A/1(CO)"		
2005083001	"9-1191452-7", "5020A1P11-1L"		
CQ37763001	"EPD31475Q CK0206/4"		
F518743001	"2020E0811-0(CO)", "8-1200596-4"		
5331433001	"8-1194185-3", "EPD89109Q/1-9(CO)"		
CQ41763001	"EPD116262 B/2(CO)"		
EQ02923001	"EPD35077A CK0206/5"		
2005563001	"3-1191453-6", "7520A1P11-1L"		
5950633001	"1194706-9", "EPD4044/2-1L"		

CQ38193001	"0028A0P11-9(CO)"		
0444653001	"7-1190341-7", "EPD20499Q/1-1L(CO)"		
CQ72603001	"EPD121313A"		
A485693001	"8-1201347-8", "EPD98750A/1-1L(CO)"		
4450193001	"6-1193344-0", "CLFH178/1(CO)"		
CQ71693001	"EPD116816ACK0206/3"		
CQ19563001	"0024A0311-9/9-0(CO)"		
9412793001	"2-1197288-3", "EPD86166R/1-9(CO)"		
CQ68143001	"EPD109382ACK0298/4"		
5519213001	"4-1194362-0", "EPD72464A"		
9637263001	"5-1197946-9", "EPD93791A"		
9287123001	"6-1201141-0", "EPD94822L/1-9(CO)"		
CD75183001	"EPD104280A/2(CO)", "6-1899443-4"		
C642753001	"1-1200807-3", "EPD99113A"		
6619853001	"1195218-1", "EPD68931Q"		
EQ05203001	"EPD122871A/3-2/6(CO)"		

D409143001	"1-1200369-1", "EPD97018A"		
1904673001	"6-1191381-4", "EPD91387A/1-1L"		
4710453001	"6-1193529-0", "EPD36313D"		
CQ97213001	"EPD122335A"		
9560673001	"7518A1811-0", "1197402-8"		
7552683001	"6-1198297-7", "EPD7032B/1-1L2(CO)"		
3598473001	"2524E0P14-1L(CO)", "8-1192699-8"		
CQ64063001	"EPD111051ACK0298/2"		
CQ44483001	"EPD60947QCK0503"		
A965863001	"1200988-8", "EPD99292B"		
2485113002	"6-1191822-7", "7522A1811-0"		
4404733010	"3-1193311-7", "5024A1312-9"		
CQ61873001	"EPD120656A/2(CO)"		
CQ28223001	"EPD116816ACK0206/1"		
6779313001	"9-1195329-2", "EPD60326A/1-1L(CO)"		
CD15613001	"EPD86888C/2-1L/9(M)", "8-1899160-5"		

E849293001	"8-1201929-8", "0024A0311-9(M)"		
6225033001	"4-1194920-7", "EPD74283A/3-0(M)"		
EQ02993001	"EPD122537 A"		
F084573001	"5-1201509-2", "EPD101632 A"		
C572543001	"6-1202060-7", "9530A1114-9(3M)"		
CQ58443001	"EPD115373 A"		
EQ04173001	"EPD122605 A/1(CO)"		
8335203001	"9-1199205-3", "EPD95412Q"		
3157253001	"1192389-8", "EPD90041A/1-1L(CO)"		
CT64503001	"2020E0P11-1L(CO)"		
6573673001	"0024A0311-0(M)", "6-1195183-5"		
CQ61863001	"EPD120656 A"		
CD69793001	"CLFH-178-0(CO)", "2-1899423-3"		
D867393001	"9-1200760-4", "EPD94823L/1-1L(CO)"		
3316743001	"1-1199172-6", "EPD67422A/1-0(7M)"		
4401013001	"1-1193308-1", "9530A1318-0"		

CD14963001	"EPD105951 A/1-9(CO)", "3-1899157- 0"		
1490913001	"1-1191078- 3", "EPD60651B/ 1-1L(CO)"		
2670533001	"4-1191971- 1", "EPD8851F/3 -9(CO)"		
F953553001	"2-1201445- 3", "EPD99409A "		
CQ07133001	"EPD116448 A/1(M)"		
CT54343001	"EPD113433 A"		
A365403001	"7-1201018- 2", "EPD60608D/ 1-1L(CO)"		
C225323001	"2524E0311- 9(4M)", "2- 1200811-8"		
CD51393001	"EPD107356 A", "4- 1899338-6"		
F519973001	"EPD2029J/1- 9(CO)", "1- 1200773-1"		
CQ74493001	"EPD100126 ACK0298"		
CQ18903001	"120-OHM- 2SJFR-26- 6(CO)"		
4869293001	"9-1193643- 8", "EPD4044/1- 0"		
CQ73793001	"EPD121177 A/1-9"		
1231943001	"8-1198298- 7", "EPD7032B/1 -1L6(CO)"		
4458243001	"9-1193350- 7", "5012A3P11- 9"		

8887893001	"4-1196914-9", "EPD91801A"		
CD51403001	"EPD107356 A/1-1L(CO)", "4-1899338-7"		
CQ28073001	"EPD113842 Q/1-1L(M1)"		
CQ97683001	"0022E0811-0(M)"		
C597663001	"EPD104319 A/1-9(CO)"		
CQ17573001	"EPD117898 A/2(CO)"		
CD93483001	"120-OHM-2SJR-24-1L(CO)", "3-1899512-3"		
7235153001	"2-1195656-3", "7820G0P11-1L(CO)"		
CD04593001	"CLFH179CK 1001", "5-1899114-0"		
CQ90183001	"EPD77622M CK0213"		
CQ28033001	"EPD113842 Q/1-1L(M1)(FS)"		
CQ21013001	"EPD117755 A"		
A127213001	"1-1199548-6", "EPD36388Q(CO)"		
9212493001	"1197148-5", "EPD4673G"		
CQ77013001	"EPD117756 ACK0298/1"		
D700743001	"1201288-3", "EPD100153 A"		
CT94913001	"EPD107550 G/1-N(CO)"		
CQ33323001	"EPD62444Q CK0206/7"		

E977353001	"EPD104312 A/1-9(CO)"		
CQ17533001	"EPD117864 A"		
C857253001	"6-1201287- 2", "CLFH- 316CK0135"		
EQ05123001	"100-OHM- 2SJR-24- 3(CO)"		
E171533001	"EPD104317 A/1-1L(CO)"		
6622013001	"9-1195219- 1", "EPD72947A(S101)"		
7991153001	"7524A1P11- 9(CO)", "4- 1196178-9"		
CQ75313001	"EPD94392B CK0206/3"		
CD70953001	"7526A1318- 0CK0094", "2-1899429- 3"		
CQ11943001	"EPD117497 A/3(CO)"		
CQ11543001	"EPD117170 ACK0298/1"		
5435193001	"1194263-5", "EPD63892B"		
8439593001	"5019D3P18- 1L(CO)", "3- 1196584-7"		
3H07093001	"1-1193004- 4", "EPD20697A "		
2001483001	"1191450-4", "5026A1P11- 1L"		
A597283001	"EPD104316 A/1-1L(CO)"		
C757113001	"6-1201504- 0", "EPD98738L/ 1-9(CO)"		
4451563001	"2524E0314- 9", "5- 1193345-6"		

9214933001	"7-1197149-2", "EPD70875L"		
CD18343001	"EPD106111 BCK0162", "8-1899171-4"		
C741593001	"2-1201351-3", "5018D3P11- N(CO)"		
5995093001	"4-1194739-2", "EPD32396B"		
EQ05303001	"EPD122879 ACK0624"		
C951163001	"4-1201142-6", "EPD94821M /1-9(CO)"		
CD93833001	"6-1899514-8", "EPD111035 A/1-9(CO)"		
D535333001	"8-1200628-9", "EPD78249B"		
5105623001	"1199515-1", "9530A1P17-9(CO)"		
CQ88423001	"EPD122014 A"		
CQ68903001	"EPD108173 ACK0308/1"		
CQ64673001	"EPD120749 A"		
CT68173001	"EPD104297 B"		
CD48483001	"EPD100582 BCK0076", "5-1899324-5"		
CQ70163001	"EPD118341 B/1-5(CO)"		
A413943001	"5-1200885-6", "EPD99528A/ 3(CO)"		
CD96893001	"EPD111040 A", "4-1899525-5"		

7743333001	"5018A1P11-1L(CO)", "1196030-3"		
4435763001	"4-1201422-5", "EPD96295Q/2-1L/9(CO)"		
CQ77023001	"EPD117759 ACK0298"		
CQ40643001	"EPD118745 ACK0202"		
CQ51423001	"EPD113842 QCK0456/4"		
5309393001	"9-1194169-7", "CLFH178"		
9926933001	"6-1197678-1", "CLFH400(S50)"		
EQ06313001	"0024K1811-1(CO)"		
EQ06303001	"EPD123073 A"		
CQ72803001	"EPD121333 A"		
CQ76833001	"EPD118745 ACK0202/4"		
8646013001	"6-1196733-5", "EPD44343A "		
2949713001	"7-1192234-7", "5024A1811-0(CO)"		
C698673001	"9-1201341-1", "EPD98739L/2(CO)"		
CQ43813001	"EPD109382 ACK0298/3"		
4405693001	"3-1193312-2", "5026A1311-0"		
CQ51953001	"EPD119924 A/1-2(CO)"		
5268583001	"1194140-3", "EPD26875A "		

CQ77973001	"EPD121558 A"		
1830673001	"8-1191329- 8", "5028A1314- 0(M)"		
200508-000	"9-1191452- 6", "5020A1P11- 1L"		
CQ41863001	"EPD116255 A/1-6(CO)"		
8674693001	"8-1196753- 7", "EPD39105E"		
2389813001	"6-1191756- 4", "EPD37557D "		
C276663001	"5-1200879- 5", "EPD99036A CK0339"		
CQ93163001	"EPD116816 ACK0206/4"		
2519953001	"6-1191846- 2", "EPD2028E/1 -1L(CO)"		
6502253001	"9-1195134- 3", "9530A1317- 90(CO)"		
4201063001	"1193165-5", "5020A3311- 0"		
CQ48053001	"EPD67364Q CK0016"		
E444373001	"EPD104309 A/1-9(CO)"		
0585903001	"2-1198918- 7", "5026A3311- 0(16M)"		
5425973001	"1-1194254- 1", "EPD24187D/ 1(CO)"		
5629373001	"8-1194447- 2", "EPD30885B"		

7495013001	"4-1195845-6", "EPD67892L"		
4992713001	"5-1193732-1", "7518A1311-0(CO)"		
4363873001	"5-1193280-3", "EPD72123B"		
CQ91663001	"0024K1811-0(M2)"		
CQ45253001	"EPD111050 ACK0298/1"		
4185973001	"3-1193154-1", "EPD44031S/ 1(CO)"		
EQ05113001	"100-OHM-2SJR-24-2(CO)"		
0191273001	"4-1190149-5", "EPD8851F/3-91(CO)"		
CT72203001	"EPD115106 Q/1-1L(M)"		
CD75203001	"EPD104280 A/1-1L(CO)", "6-1899443-6"		
2141283001	"8-1199023-1", "7524A1311-0(2M)"		
A543163001	"6-1200885-0", "EPD99529A/ 4(CO)"		
CT98853001	"EPD115852 A"		
A885873001	"EPD104346 A/1-9(CO)"		
3966373001	"4-1192975-0", "EPD47366Q "		
6285913001	"5-1194976-5", "7528A1314-0(CO)"		

CQ60883001	"EPD116262 A/2(CO)"		
CT78693001	"EPD115223 A/1-9(CO)"		
440680W002	"5-1193313- 0", "7528A1314- 9"		
CQ51993001	"EPD119924 A/2(CO)"		
CD76943001	"EPD105568 A/1-2(CO)", "1899449-5"		
4843333001	"4-1193624- 5", "5018D3P11- 1L(CO)"		
6300693001	"9-1194986- 3", "EPD33017Q(CO)"		
4400863001	"6-1193307- 6", "5028A1318- 0(500)"		
CD74443001	"EPD108696 A/2(CO)", "5- 1899439-3"		
7763153001	"7522A1811- 0(M)", "2- 1196044-3"		
7628933001	"5-1195940- 4", "EPD26995Q "		
4900973001	"3-1193666- 9", "9530E1014- 0"		
CQ95363001	"EPD121050 A"		
4418253001	"3-1201344- 1", "0022D0311- 95(CO)"		
CQ98433001	"EPD116846 A"		
CQ42043001	"EPD119030 A/1-1L"		

440077W005	"5-1193307-5", "7524A1311-0"		
EQ00193001	"7528A1818-0(M)"		
CQ77573001	"EPD94392B CK0206/5"		
CT75423001	"EPD114761 B"		
CD85143001	"EPD109382 A", "6-1899482-5"		
5095313001	"7-1194005-5", "EPD22545D "		
D799103001	"EPD104345 A/1-9(CO)"		
C806053001	"2-1201423-8", "7520A1811-0(CO)"		
CD09063001	"EPD105592 A", "1899133-8"		
CQ99233001	"EPD122349 A"		
1416913001	"7-1191026-9", "EPD68148A "		
CD04043001	"EPD98865Q/ 1-6(CO)", "8-1899110-0"		
420124W002	"3-1193165-6", "5012A3311-0"		
200074W002	"2-1191449-0", "5024A1P12-1L"		
CT74183001	"EPD114357 A/2(CO)"		
0590423001	"2-1201141-2", "EPD94822L/ 1-1L(CO)"		

CD93063001	"EPD110996L", "1899511-4"		
A578233001	"3-1200752-0", "EPD98957B"		
4417333001	"3-1193321-7", "7526A1P17-1L(CO)"		
3713753001	"9-1192781-2", "EPD87108Q"		
EQ09843001	"EPD108852LCK0298/3"		
CQ83783001	"EPD118179A/1-95(CO)"		
CQ04163001	"EPD109318Q(FS)"		
CD14533001	"EPD86888C", "8-1899155-4"		
6647153001	"9-1195237-0", "7530E1114-9(CO)"		
CQ21053001	"EPD117759A"		
598901W001	"0024F0611-9", "1-1194735-1"		
480314-000	"6-1193595-6", "7530E1114-9"		
200557-000	"3-1191453-8", "7522A1P11-1L"		
E336753001	"1201791-3", "EPD101039L/1-9(M)"		
CT68403001	"EPD114276A"		
A952043001	"7-1201155-8", "EPD100628A/1-1L(CO)"		
CQ52003001	"EPD119924A"		

5089893001	"3-1194001-6", "7524A1811-0(M)"		
CT69693001	"EPD114764 A/3(CO)"		
CQ77673001	"CLFH316/1(FS)"		
CT72213001	"EPD115106 Q/1-9(M)"		
4860883001	"2-1198298-6", "EPD7032B/1-1L5(CO)"		
1482863001	"EPD104316 A/1-9(CO)"		
CD58403001	"EPD108173 A", "6-1899370-3"		
A728483001	"6-1200524-9", "EPD96002A/1-6(CO)"		
CQ70473001	"EPD72718A CK0206/5"		
CQ65763001	"EPD60947Q CK0647"		
C611643001	"5-1201504-4", "5018A1311-0(CO)"		
CQ44453001	"EPD35077A CK0503/1"		
EQ02403001	"EPD122640 A/1-9(CO)"		
CQ07233001	"EPD105670 ACK0440/1"		
5812693001	"2020E0811-0"		
4399053001	"6-1193305-3", "5026A1314-0(CO)"		
9521353001	"3-1197373-4", "EPD79935Q"		
0448763002	"7-1190344-6", "EPD22008F"		

EQ05253001	"100-OHM-2SJR-24-1L(CO)"		
4643373001	"8-1193481-3", "EPD40252B/1(CO)"		
CQ17583001	"EPD117898 A/3(CO)"		
CD99383001	"0024K1811-0(6M)", "9-1899535-6"		
CQ60853001	"EPD116262 A/1-6(CO)"		
CD89863001	"EPD110891 A", "2-1899499-7"		
9171573001	"2-1197119-0", "EPD73307R/1-0(CO)"		
CD93883001	"EPD111093 A/1-1L(CO)", "7-1899514-5"		
F229553001	"7-1201320-8", "7516A1P11-9(CO)"		
CT71493001	"EPD114556 A/1(CO)"		
CT98543001	"EPD116687 A"		
CT06353001	"EPD112378 Q/1-9(CO)", "7-1899559-7"		
CD56163001	"EPD108040 A/1-1L/9(CO)", "5-1899362-6"		
CQ66243001	"EPD116687 ACK0398"		
C179693001	"5-1202050-1", "EPD101755 B/1-1L(CO)"		
CQ17913001	"EPD117603 ACK0308"		

CQ91633001	"0024K1811-0(M3)(FS)"		
486167-000	"2-1193638-1", "5024A1311-0(FS)"		
CQ72093001	"EPD62444Q CK0621/1"		
CQ95583001	"EPD121087 A"		
CQ29923001	"5020A1311-0(M2)CK2240"		
CD48543001	"EPD106418 A", "7-1899324-1"		
CQ60843001	"EPD116262 A/1-0(CO)"		
6068833001	"6-1194800-9", "7520A1311-0(CO)"		
594223-000	"1194698-6", "EPD33307Q"		
CQ83603001	"EPD116265 A-0CK0547"		
4412333001	"8-1193317-9", "5028A1P17-9(CO)"		
CQ20533001	"EPD109318 Q/1-9(MARK2)"		
2008493001	"7-1191455-0", "7530E1P14-1L"		
1718593001	"1-1191250-2", "5020A3311-92(CO)"		
7945673001	"2-1196151-1", "EPD35077A"		
CQ72493001	"EPD121302 A"		
CQ76773001	"7528F5814-0CK0193"		

CD48083001	"EPD107588 A", "8- 1899322-9"		
CQ12553001	"EPD117622 A"		
CT00393001	"EPD112330L ", "4- 1899540-6"		
9059213001	"8-1197038- 7", "EPD77622L/ 2(CO)"		
6080873001	"9-1194809- 8", "EPD23197B/ 1-1L(CO)"		
EQ05093001	"100-OHM- 2SJR-24- 0(CO)"		
A948053001	"1-1201294- 7", "EPD95289L"		
CD15623001	"EPD86888C/ 3-1L/9(M)", "8-1899160- 6"		
530939-000	"9-1194169- 6", "CLFH178"		
440640W002	"1193313-5", "9530A1317- 9"		
8730553001	"6-1196793- 5", "EPD45759A "		
F932693001	"5026A1P14- 9(CO)", "6- 1199783-0"		
CQ12323001	"EPD45898Q CK0596"		
490097-000	"3-1193666- 8", "9530E1014- 0"		
4957973001	"1193708-6", "EPD62976A/ 2-9(M)"		
CQ58883001	"EPD105273 ACK0298/3"		

8902233001	"8-1196925-2", "EPD26169D"		
CQ72083001	"EPD62444Q CK0621"		
6205903001	"5030A3-317-0", "8-1194903-6"		
9528153001	"2524E0311-9(CO)", "2-1197378-6"		
CQ34113001	"EPD117603 ACK0298"		
956067-000	"7518A1811-0", "1199164-8"		
CD71463001	"EPD108750 ACK0519/1", "2-1899431-4"		
5189543001	"7-1194072-7", "EPD4673G/1 (CO)"		
CT75483001	"EPD115224 A/1-9(CO)"		
CD81953001	"EPD109698 A/1(CO)", "7-1899469-7"		
CD84243001	"EPD63976A/ 1-9(CO)", "3-1899479-5"		
6367983001	"5028A1314-9(S)", "7-1195034-2"		
CT60263001	"EPD114107 A", "8-1899591-2"		
CQ28043001	"EPD113842 Q/1-1L(M3)(FS)"		
D649603001	"7-1200884-5", "EPD60608C/ 1-1L(CO)"		
2005573001	"3-1191453-9", "7522A1P11-1L"		

6676093001	"9-1195257-9", "EPD76441L/2-1L(CO)"		
CT71263001	"EPD113842 QCK0456"		
CT74233001	"5020A1P12-N(CO)"		
CQ95313001	"EPD121042 A"		
E546883001	"9-1200754-2", "EPD42233A/2-9(CO)"		
CQ78273001	"EPD117603 ACK0298/2"		
CD76293001	"6-1899446-3", "EPD109318 Q/1-9(M)"		
CQ48733001	"EPD119159 A"		
3057083001	"9-1197945-4", "EPD93972A/1(CO)"		
3L08643001	"2-1193011-9", "EPD2029F"		
CT36383001	"EPD113286 A/1(CO)", "8-1899562-0"		
F714463001	"EPD99112A", "2-1200819-3"		
4400263001	"5-1193306-5", "5020A1311-9"		
CQ42073001	"EPD119031 A/3(CO)"		
4354333001	"1-1193274-4", "EPD70874L"		
CQ19303001	"EPD118014 A/2(CO)"		
CQ79403001	"2018A1P11-9(CO)"		

1182693001	"7-1190860-2", "5020A1P11-1L(CO)"		
2071713001	"8-1191501-1", "EPD20697A/1-9(CO)"		
CD00373001	"EPD104250A", "9-1899089-7"		
CT67203001	"EPD104317C/1-1L(CO)"		
9206533001	"7528A1P17-1L(CO)", "7-1197143-6"		
7733093001	"5-1196022-4", "EPD60603B"		
E279793001	"9-1202050-2", "EPD101747B/1-1L(CO)"		
CT69653001	"EPD114761A"		
EQ06343001	"0024K1811-6(CO)"		
A528763001	"9528A1P17-9(CO)", "1200600-4"		
1005653001	"4-1190736-1", "9526A1P11-1L"		
A565123001	"1200754-3", "EPD42233A/1-09(CO)"		
4425893001	"2524E0311-0(CO)", "2-1193327-4"		
C882553001	"5-1201459-2", "EPD98738L"		
7021133001	"3-1195509-1", "EPD69713L/1-0(M)"		
A099233001	"3-1202045-7", "EPD101753B"		

420124-000	"3-1193165-4", "5012A3311-0"		
1517773001	"1-1191097-2", "EPD32644A/3(CO)"		
1385423001	"7-1199572-3", "EPD95224Q/1-9(CO)"		
A459773001	"9-1202052-3", "EPD101729M/1-9(CO)"		
CQ58013001	"5018D3811-0CK0206"		
CT36403001	"120-OHM-2SJFR-24-2(CO)", "8-1899562-4"		
6042073001	"1194781-7", "7520A1811-0"		
CQ06613001	"EPD117381ACK0236"		
3808053001	"4-1192847-7", "EPD8851F/3-94(CO)"		
CD60493001	"EPD108181A", "8-1899379-0"		
CQ83823001	"EPD118179A/2(CO)"		
D226323001	"3-1201761-9", "EPD101186A/1-1L(CO)"		
6814113001	"1195358-2", "EPD71192Q"		
0119933001	"7-1190094-9", "5030A1P18-9(CO)"		
8621853001	"1-1196716-0", "EPD49551R/1-1L"		

CQ31603001	"EPD113283 A"		
E135733001	"5-1201496- 9", "EPD96420A/ 1(CO)"		
CQ60653001	"EPD120520 A"		
C241953001	"6-1202151- 5", "EPD77178R"		
E016023001	"5-1201904- 0", "7526A1311- 9(CO)"		
6445033001	"1-1195091- 2", "EPD40399Q "		
CQ73433001	"EPD121380 A"		
810351-000	"2-1196297- 5", "EPD32183C"		
CT67213001	"EPD104317 C/1-9(CO)"		
CQ83733001	"EPD118179 A/1-6(CO)"		
C312423001	"6-1201021- 2", "EPD100319 A/1-9(CO)"		
E029333001	"1-1202061- 0", "EPD103085 A/1(CO)"		
CT93363001	"EPD107550 GCK0202/1"		
2090413001	"8-1191514- 6", "EPD39105F"		
D256123001	"0024A0311- 0(3M)", "9- 1201023-9"		
CQ04123001	"EPD109318 Q/1- 1L(M1)(FS)"		
C546413001	"3-1201401- 2", "EPD99111A CK0900"		

CQ11903001	"EPD117498 A/1-9(CO)"		
A942693001	"0022E0311- 0(CO)"		
8866133001	"1-1196898- 5", "EPD69568B/ 1-1L(CO)"		
CD08983001	"9524A1311- 0(CO)", "9- 1899132-9"		
0404813001	"5-1190309- 5", "EPD26332A "		
CQ74603001	"EPD118342 C/1-0(CO)"		
C677853001	"4-1200754- 5", "EPD42233A/ 1-0(CO)"		
D574843001	"7526A1811- 0(3M)", "1200559-9"		
CQ04203001	"EPD109318 QCK5700"		
CQ71523001	"EPD35077A CK0647/1"		
2001443001	"9-1191449- 3", "5026A1P17- 1L"		
CT67153001	"EPD104313 B/1-1L(CO)"		
CT58143001	"EPD109318 QCK0456/1"		
EQ06253001	"EPD122605 BCK0427/1"		
CQ60643001	"EPD120521 A/1(CO)"		
CQ56173001	"EPD116267 A/1-6(CO)"		
5048283001	"5-1199508- 2", "EPD64983B"		
2904013002	"7-1192201- 2", "EPD37229A "		

EQ05183001	"EPD122871 A/3-2/3(CO)"		
CT36413001	"120-OHM- 2SJFR-24- 6(CO)", "8- 1899562-5"		
CQ34093001	"EPD117757 ACK0298"		
A901873001	"1199839-8", "EPD26168D/ 1-0(16M)"		
CT78703001	"EPD115223 A/2(CO)"		
4800793003	"1193594-7", "7530A1114- 9"		
2996603001	"4-1192268- 4", "7524A1311- 0-M"		
CQ55903001	"EPD77622M /1(CO)"		
D209823001	"7820G0111- 9(2M)", "1200717-1"		
EQ05843001	"EPD100584 B"		
7608873001	"0022D0P11- 9(CO)", "4- 1195926-8"		
C345453001	"EPD104312 A/2(M)"		
CQ21283001	"EPD35077A CK0206/3"		
CQ96333001	"EPD121857 CCK0193"		
6049923001	"3-1198232- 8", "EPD94452A "		
6832133001	"5-1195369- 7", "7522A1311- 0(M)"		
CQ29933001	"5020A1311- 0(M3)CK224 0"		
3356933001	"7-1192535- 0", "9530E1P14- 9(CO)"		

0364413001	"4-1190281-9", "EPD2028E-2(CO)"		
8845683001	"9-1197946-6", "EPD94100A"		
CD74033001	"EPD106972 A", "9-1899437-2"		
CD56153001	"EPD108038 A/1-1L/9(CO)", "5-1899362-5"		
CQ14333001	"EPD117622 A/6(CO)"		
2524833001	"2-1191848-8", "EPD44774M /1-0(M)"		
CQ38213001	"0028A1811-0(M)"		
CQ72103001	"EPD77804A CK0193"		
A661153001	"8-1201542-5", "EPD101389 A"		
A473193001	"1201262-6", "0024A0311-90(CO)"		
CT85583001	"EPD115579 A/1(CO)"		
7654613001	"5026A1P18-9(CO)", "1195959-6"		
7721303001	"5-1196014-0", "9530A1114-9(M)"		
CT67193001	"EPD104317 C/2(CO)"		
7215273001	"9-1195641-2", "EPD63774C"		
CQ14273001	"8-1899772-2", "EPD31475Q CK0206/3"		

440010-000	"3-1193306-8", "5024A1314-0"		
7785153001	"5026A1318-0(CO)", "4-1196059-7"		
D347483001	"1201342-8", "EPD98739L/1-1L(CO)"		
CQ41293001	"EPD114381A"		
1828093001	"1-1191328-9", "EPD36192A"		
CQ93173001	"EPD67422ACK0206/3"		
C152393001	"2-1201287-0", "CLFH316-0(CO)"		
D362073001	"3-1201348-7", "7524A1811-0(2M)"		
CQ77093001	"EPD121138A/1-6(CO)"		
D532133001	"7-1201499-9", "5020A3811-06(CO)"		
CD56463001	"120-OHM-2SJR-20-9(CO)", "1899363-1"		
CQ65773001	"EPD67422ACK0647"		
8688413001	"2524E0311-0(M)", "8-1196763-0"		
CQ74553001	"EPD118341C/1-0(CO)"		
CQ70143001	"EPD118341B/1-2(CO)"		
CQ78373001	"EPD102265ACK0298"		
0595263001	"8-1200068-5", "7524A1311-9(CO)"		

F490863001	"1-1202051-7", "EPD101754 B/1-9(CO)"		
D323943001	"1200775-1", "EPD98957B/1-1L(CO)"		
CQ19253001	"EPD109382 ACK0298/1"		
CQ12833001	"EPD117612 A"		
CT62683001	"EPD96718C"		
E940393001	"8-1201288-3", "CLFH-178CK0135"		
1338463001	"8-1190972-2", "EPD24920A"		
A728353001	"2-1200761-6", "EPD94823L/1-9(CO)"		
440563-000	"2-1193312-3", "7526A1317-0"		
CD40573001	"100-OHM-2SJFR-26-9(CO)", "2-1899281-8"		
9851513001	"5024A1311-9(CO)", "3-1197610-9"		
CQ72673001	"EPD121320 A"		
440562-000	"2-1193312-1", "5018A1311-0"		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.