



01-Aug-2023

PCN #: P-23-024891

Subject : Material Change in Foamed Polyethylene Controlled Electrical Cables

Description of Change : Source and material change of foamable polyethylene used in Controlled Electrical Cables (CEC).

Reason : Product improvement. TE Connectivity has been notified by its supplier of a foamable high-density polyethylene of a formulation change. The foamable high-density polyethylene is used in TE's Foamed Polyethylene Controlled Electrical Cables (coaxial, triaxial, twinaxial, J193 and high speed copper). As a result of this change, TE has identified and validated an alternative grade of foamable high-density polyethylene from a different vendor.

Key Dates :

Product Affected	Alias Part Number	Substitute Part Number	AliasSub Part Number
CR3843-000	5022A1311-0-L196		
CV5531-000	5028P3514-9CS1243		
CV5047-000	9532A3514-9CS1245		
440889-002	3-1193315-3, 7530A1314-0		
317185-000	2-1192403-2, 5012A3811-0		
759575W001	6-1195917-6		
CY7943-000			
CX1382-000			
440071-000	4-1193307-0, 5022A1311-0		
EM6760-000			
440788-000	4-1193314-1, 5030A1318-9		

CJ0917-000	7530A1317-0CS2979, 4-1899252-5		
509360-001	5021K1011-9, 5-1194004-3		
CP3521-000			
CB0920-000			
CV6024-000	5028A1314-0-L332		
CP9729-000			
CS5792-000			
884813-000	7528A1814-0, 7-1196885-1		
480138-000	5-1193594-5, 9532A5114-9		
440010-000	3-1193306-8, 5024A1314-0		
750391-000	2-1195852-3, 7528F5814-0		
062779-001	7-1190474-1, 5028D5312-9CS1173		
440751-000	1-1193314-1, 5028A1314-9		
EM7667-000	5026C1L14-9		
440582-006	4-1193312-9, 7528A1317-9		
604207-000	1194781-6, 7520A1811-0		
430058-000	9-1193234-4, 5028D5312-9		
617577K001	5-1194880-9		
EM7923-000	5012H3012-0-L016		
EM0495-000			
301429K001	4-1192283-4		
BM0394-000			
CA7842-000			
CV7415-000			
CF2197-000			
EJ3448-000			
440710-000	6-1193313-6, 7524A1311-9		

440101-002	1-1193308-0, 9530A1318-0		
CY7944-000			
CZ6912-000			
886501W001	3-1196897-6		
EM7108-000	5022D1312- 9CS991-L016		
123617-000	2-1190899-1, 7530A5314-9		
123562K001	5-1199124-6		
420030-000	2-1193164-7, 5019D3318-0		
EH9712-000	5024A1311- 0CS3440		
CX2090-000	5022E5111- 9CS3348		
544361-000	9-1194269-7, 9532A1114- 9CS1677		
440897-000	1-1200345-5, 7528A1314-0		
C11833W001	8-1202119-6		
441895-000	4-1193322-5, 5024A1314-9		
082799-000	7-1190612-8, 7528F8614-9		
EF7256-000	9524S1614-9		
440172-008	9-1193308-1, 9527A1318-9		
935715K001	1-1197250-5		
440094-000	9-1193307-3, 5026A1318-0		
EH5859-000			
CA7841-000			
D49240K001	1-1201566-5		
420109-001	1193165-8, 5028D5312-0		
440077-003	4-1193307-6, 7524A1311-0, 7524A1311-0		
620590-003	5030A3317-0, 8- 1194903-5		
480285-000	4-1193595-7, 9532A1314-0		

440356K001	5-1197961-5		
EM3478-000	7520C1311-0		
440206-000	2-1193309-2, 7530A1317-9		
EP1717-000	7524A1311- 9CS3510		
417923-000	5-1193149-9, 7528F5614- 9CS2205		
440516-000	9-1197869-5, 5024A1311-9		
440093-000	8-1193307-9, 9527A1318-0		
480123-000	4-1193594-2, 9532A1114-9		
E52774-000	9-1201365-9, 7520A1314-0		
CL6861-000			
958794-001	5012H3012-9, 1- 1197422-3		
EG7789-000	7528F5614-9- L016		
538445-000	7-1194225-8, 7524A1314-0		
CX4569-000			
CB4306-000	7528F5614-9-15, 3-1899168-0		
445818-000	8-1193350-8, 7522D5311-0		
430034-000	7-1193234-6, 5026D5314-0		
CN5824-000			
CS8370-000			
971843-000	5020A1611-9, 1- 1197512-4		
CJ1643-000			
582197-000	3-1194612-0, 7518A0811-0		
561198-000	1-1194433-4, 9532A1114- 9CS1102		
102833-000	5-1190752-8, 7524E5114-9		
CS5800-000			

A51721-000	5028A1314-0-L098, 1-1200862-1		
440591-000	6-1193312-2, 5028A1317-9		
440573-002	3-1193312-9, 9530A1314-0		
958703-000	5724D1311-0CS2283, 4-1197421-3		
992369K001	7-1197675-8		
440050-000	7-1193306-8, 7530A1317-0		
CY7946-000			
CV7796-000	7524A1311-0-2-L245		
A96951W001	4-1200440-4		
EG2836-000			
480045-000	4-1200910-3, 9530D1114-9		
469659-000	7-1193519-9, 5012M3612-0		
480322-000	7-1193595-9, 9032E1114-9		
EM7761-000	7526S1L14-9		
600957-000	5022A3312-0CS1865, 1-1194755-3		
440780-001	3-1193314-2, 5022D5311-0		
CS8375-000			
630519-000	1194990-8, EPD35767Q-US		
480381-000	2-1193596-1, 5024A1111-0		
440562-000	2-1193312-1, 5018A1311-0		
EF8518-000			
420106-002	1193165-4, 5020A3311-0		
EM7540-000	7530S161A-9		
480131-000	4-1193594-9, 9532A1314-9		
480314-000	6-1193595-6, 7530E1114-9		

CV7797-000	7524A1311-0-3-L245		
024401-000	5-1197924-4, 7514A1811-0-G019		
EF7410-000	EPD35767Q-US-L012		
420041-000	4-1193164-3, 7522D5311-9		
549947-000	7-1194326-7, 9528A1318-9CS1614		
110607K001	7-1190807-6		
EJ3011-000	9530D1114-9CS1677-1KF		
CB7534-000			
430061-000	9-1200968-6, 9530F5214-9		
C37073K001	9-1201567-9		
759337W001	9-1195915-3		
440564-000	2-1193312-5, 7522A1311-0		
490098-000	4-1193666-6, 5021K1011-0		
CY1457-000			
440786-000	3-1193314-7, 5030A1314-9		
440532-000	8-1193311-7, 7524A1318-0		
440107-002	1-1193308-7, 5028A1314-0		
CV7793-000	5020A1311-0-3-L245		
EL7175-000			
490096-000	3-1193666-6, 5012H3012-0		
440125-002	3-1193308-8, 5010D1312-0		
420124-000	3-1193165-4, 5012A3311-0		
776173-000	7518A3811-0, 2-1196043-7		
EM4419-000			
158937W001	5-1191148-4		

CN6837-000	7528A1817-0		
A68968W001	7-1202119-8		
430042-000	8-1193234-4, 7524D5111-9		
247135-000	7-1191812-0, 9527D1314- 0CS1238		
334741K001	6-1192528-2		
CL0863-000	7518A5611-9		
CZ3154-000			
EF4705-000	5010D3612-9		
CV7794-000	7524A1311-0-1- L245		
440499-000	5-1193311-4, 5030A1314-0		
A32759F002	9-1200230-7		
EG5139-000			
EG9451-000	7528G6314-9- E629		
EH7266-000			
EJ1420-000	7518A1811-0- L159		
440672-000	3-1193313-0, 7520A1311-0		
171879-000	2-1191250-8, 7524D5110-9		
638193-000	5020A1811-0, 7- 1195044-1		
490097-000	3-1193666-8, 9530E1014-0		
291478-000	7-1199146-2, 5020A5614-9- F871		
CB8382-000	7528A1P17-9- UNYIELDED, 3- 1899193-5		
592675-000	9-1194686-9, 9532A5114-0		
440680-000	4-1193313-8, 7528A1314-9		
440563-000	2-1193312-3, 7526A1317-0		
420111-000	1-1193165-5		

440061-000	1193307-8, 5028A1317-0		
EM6756-000			
CA8696-000			
CX0069-000			
440891-000	3-1193315-7, 9528A1317-9		
908774-001	1197059-4, 9530D1114- 9CS1677		
CW9186-000	7526A1318-0- L250		
EM5636-000	7518A1811-0- L397		
870951-000	5024D5614-9, 6- 1196778-1		
EM6368-000			
CU0897-000	5028A1314-0- L268		
663749-000	5024A3314-9, 4- 1197888-3		
440151-000	7-1193308-0, 5030A1317-0		
CP9577-000			
363271-000	1-1192724-3, 7528F8614- 9CS1653		
440069-000	3-1193307-3, 5026A1317-0		
EL7810-000			
EM3524-000			
853727-000	5024A3314-0, 6- 1196655-0		
694747K001	7-1195450-7		
175559-001	5-1191276-2, 5022D1312- 9CS991		
EL6723-000	7518A1811-0- L122		
628365K001	9-1194974-2		
244779-000	7-1191795-1, 7528F5614- 9CS2358		
368438-000	5-1198283-8, 5019D3618-0		

440060-011	9-1193306-5, 5024A1311-0		
666505-000	4-1195250-1, 7518A5811-0		
452137K001	1-1193395-1		
344039K001	4-1192591-0		
CF4757-000	5030A1317- 0CS2979, 1- 1899219-6		
CY2865-000			
145125-000	7-1191048-6, 5012E1112- 0CS2366		
300433-000	6-1192275-9, 7528A5314-9		
456470-000	1199978-3, 5026A1314- 9CS2979		
104946-000	4-1199146-0, 5020A1611-9- F871		
815137-000	7524A1811-0, 3- 1196352-0		
420051-000	4-1193164-9, 5019D3318-9		
158550K001	6-1198204-7		
CU8721-000			
A52042K001			
A80180K001	1-1200087-2		
905851K001	3-1197038-7		
CW7725-000			
EF4799-000	7524A1311-9- F891		
440737-002	9-1193313-1, 5026A1314-9		
A59673-000	6-1201388-1, 7528G6314-9		
F50780K001	2-1201236-2		
D65685-000	7-1201142-4, 5028C2214- 9CS2247		
931408K001	4-1198896-8		
CV7417-000			

440079-000	5-1193307-6, 9524A1311-0		
271643K001	7-1192012-5		
E90533-000	7528F5814- 0CS2979, 3- 1199873-2		
E93405W001	7-1201140-0		
C86830W001	5-1200440-8		
CX1718-000			
CZ2010-000	7522D5311-0- L027		
547699K001	5-1194311-6		
819799K001	5-1196388-7		
956067-000	7518A1811-0, 1199164-8		
EG8280-000	5020A1611-4		
C40039K001	1201568-1		
854926-000	7530A1314-9, 8- 1196663-2		
116476-000	5-1199162-1, 5028A1314-0- L025		
CP9728-000			
EM3518-000			
EG0010-000	7528A5814-0		
CF2203-000	5028A1317- 0CS2979, 3- 1899203-5		
CB8829-000	5020J1311-0		
837603K002	4-1196537-9		
440241-000	5-1193309-4, 5026A1314-0		
548490W001	2-1201138-9		
EG0539-000			
CW7545-000			
766613-000	5019D3618-9, 7- 1195974-2		
EM5688-000	7518A3811-0- L397		
497233-000	5026A1817-0		
440225-000	3-1193309-5, 5020A1311-0		

CS2607-000			
CW0099-000	7528F5814-0-L077		
CV7792-000	5020A1311-0-2-L245		
CA7843-000			
243721-000	1-1191788-6, 7528F5614-9		
EM7466-000	5026S5L14-9		
CU9565-000	7528F5614-9-15-L193		
EM6364-000			
988831-000	5026D5314-9, 2-1197641-4		
440569-000	3-1193312-1, 5026A1311-0		
440640-000	1193313-3, 9530A1317-9		
420079-000	7-1193164-4, 5028A3318-9		
430028-000	6-1193234-7, 5022E5111-9		
430021-001	5-1193234-7, 9530D5114-9		
CV7791-000	5020A1311-0-1-L245		
289995K002	6-1192198-8		
480312-000	6-1193595-1, 9528D5114-9		
440838-000	8-1193314-4, 5018D3311-0		

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.

