



30-Mar-2012

PCN #:P-12-007854

Subject:Qucik Connect products

Description of Change: Reel type change from 3 piece plastic reel to single piece plastic reel The key differences are, Central hole diameter : Current 21mm - Proposed 22mm Reel drive hole diameter :Current 11mm - Proposed 13mm Reel drive hole distance from centre :Current 29mm Proposed 29mm

Reason: New specification.Current three piece reel being discontinued

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-May-2012

Implementation Date:01-May-2012

Product Affected

160917-1

160914-4

160534-2

160917-4

345397-1

5-160555-7

150566-1

140544

160859-6

345397-2

5-160446-8

160922-2

154740-1

160684-3

Product Affected

154713-3

160666-4

100645-3

929901-1

160808-2

342018-2

927969-1

152404-3

160869-2

100651-2

42594-1

160786-2

160597-1

344469-2

160684-4

280755-4

150631-2

140731-2

160597-4

151614-2

5-160558-1

(Alias Part Numbers:

"CU3090-000"

"AMPS-5-0160558-1")

150530-1

928793-2

5-160558-9

180464-5

42778-1

150520-2

280223-2

(Alias Part Numbers:

"0-0280223-2")

160772-3

1-151939-0

160844-2

160913-3

160645-1

1-151939-1

160928-4

Product Affected

160887-1

42098-1

5-160430-7

5-160558-2

160655-1

140837-2

6-160526-1

342781-2

41771-1

160862-4

140808-2

140525

160533-9

1-280002-1

160765-1

6-160430-6

(Alias Part Numbers:

"CU3091-000"

"AMPS-6-0160430-6")

160914-1

42594-2

346101-2

962825-3

928793-1

926933-4

280005-2

160913-2

160484-1

6-160448-6

160859-1

160917-3

160666-3

151382-3

140808-1

1-160655-1

150681-3

280004-2

150571-2

160859-4

737190-2

Product Affected

280002-2

42098-2

(Alias Part Numbers:

"CF5844-000"

"AMPS-0-0042098-2")

160718-9

160684-2

346100-2

150557

160743-2

345153-1

160457-1

925856-2

280004-1

344536-2

338011-1

6-160432-3

6-160448-2

140780-2

152404-2

160655-3

160859-2

150618-1

150519

150530

160927-2

160864-4

160861-8

160743-1

5-160526-6

280050-7

140723-1

150500-1

160844-1

150500-2

962825-2

925856-1

(Alias Part Numbers:

"CM1530-000"

"AMPS-0-0925856-1")

Product Affected

928890-2

160786-4

5-160446-2

160409-2

969184-1

160862-7

160655-2

(Alias Part Numbers:

"F49671-000"

"AMPS-0-0160655-2")

152313-1

6-160526-2

6-160303-4

160645-2

280755-2

160484-4

152301-2

160457-2

160861-7

180397-5

5-160555-1

5-160303-6

925667-2

5-160433-6

5-160433-1

1-180464-2

5-160303-2

160922-4

346697-3

926933-2

5-160713-2

5-160446-4

968021-2

160864-2

150681-1

160927-1

2-180464-1

281091-2

5-160558-3

962825-1

Product Affected

160666-5

160864-5

150204

160927-4

280756-2

140760-2

160887-4

5-160555-2

(Alias Part Numbers:

"5-0160555-2")

160366-1

160860-3

925667-1

100645-2

280428-4

160914-3

160869-5

160807-2

964156-1

341343-1

926935-2

293042-1

100097-2

1-151939-3

151667

926935-1

160808-1

926933-3

1814988-1

160870-1

180388-2

(Alias Part Numbers:

"C38663-000"

"AMPS-0-0180388-2")

160533-1

6-160448-1

152404-1

151667-2

342018-1

160913-4

Product Affected

160173-7

338052-4

140760-1

100494-2

929901-2

160208-1

160173-1

6-160558-0

160927-3

160208-6

160415-1

150570-2

346697-2

160860-2

1955414-1

150204-2

160861-6

142685-3

150635-1

5-160446-1

1-160534-0

1-160534-1

2-180464-4

737306-2

928764-2

160691-2

(Alias Part Numbers:

"CU3065-000"

"AMPS-0-0160691-2")

5-160526-9

160928-1

346100-3

6-160448-5

160743-4

735097-2

150635-4

140569

926933-1

(Alias Part Numbers:

"CB1666-000"

Product Affected

"AMPS-0-0926933-1")

5-160526-7

160859-3

160450-2

160729-8

346697-1

5-160526-8

280003-1

140635

5-160446-6

6-160448-3

5-160429-2

150681-2

345153-2

280002-1

346103-2

151667-4

160918-4

140791-2

140778-1

150542-2

282184-1

160655-9

160772-1

160173-2

282181-1

5-160431-2

(Alias Part Numbers:

"5-0160431-2")

180464-1

160691-4

160450-1

5-160429-1

(Alias Part Numbers:

"CU3089-000"

"AMPS-5-0160429-1")

341299-1

280756-4

150681-4

736233-2

Product Affected

160860-1
160780-2
928890-1
160922-3
160388-2
160534-9
151359-2
160743-3
160741-2
5-160446-5
150503-4
160860-4
154672-2
160534-4
160913-1
180397-2
160870-4
160533-2
153292-1
736233-1
150545-1
5-160303-1
344538-2
160862-6
160655-4
1-100645-3
969039-1
150545-2
6-160448-0
150572-2
160780-4
4-160256-2
151614-1
160862-8
160917-2
280005-1
140568
160655-6
42594-3
160914-2

Product Affected

160762-2

(Alias Part Numbers:

"0-0160762-2")

160928-2

5-160316-2

160765-3

150519-2

280004-5

342368-2

5-160316-1

160533-5

180416-2

160691-1

150635-2

160928-3

160762-1

180353-1

160811-5

180398-2

160870-3

280003-2

100644-4

346102-2

160366-2

151382-2

180388-5

1-151302-2

341299-2

180464-2

5-160430-6

160415-2

342368-1

(Alias Part Numbers:

"CU3083-000"

"AMPS-0-0342368-1")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.