



03-Jul-2012

**PCN #:**E-12-011560

**Subject:**Type III+ Socket Contacts

**Description of Change:** Change the plating in the wire crimp area of these contacts from gold flash over nickel to matte tin over nickel. The plating located on the mating end of these contacts will not change.. The plating in the center of the contact between the mating end and the crimp end will change from gold flash over nickel to nickel only. Following the change the contacts will continue to comply with TE product specification 108-10042.

**Reason:** PCN-P-12-007828 was distributed in March 2012 providing customers with this same notification with a first ship date of 18Jun2012. This is a duplicate notification.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**28-Jun-2012

**Implementation Date:**28-Jun-2012

**Product Affected**

1-66358-3

1-66399-1

1-66105-8

3-66104-0

1-66109-8

66101-4

2-66358-1

1-66360-6

66399-3

66358-1

788088-1

## **Product Affected**

66331-8

(Alias Part Numbers:

"1099392"

"1098628")

66108-5

66563-5

66331-2

66399-2

66563-1

66565-1

1-66360-4

66109-1

66598-2

(Alias Part Numbers:

"A17719-000"

"AMP-0-0066598-2")

66105-4

2-66105-0

1-66101-7

2-66100-0

1-66105-9

66101-1

66358-5

(Alias Part Numbers:

"295444-000"

"AMPS-0-0066358-5")

66104-1

66428-3

66108-3

66394-5

2-66104-9

66424-8

66101-3

(Alias Part Numbers:

"C41086-000"

"AMPS-0-0066101-3")

1-66331-4

66394-8

2-66104-3

1-66101-5

## **Product Affected**

66358-9

1-66598-1

66109-3

66598-9

66331-7

66100-1

66424-7

66104-6

1-66601-3

66565-4

66108-7

66601-9

1-66358-6

66424-1

66601-2

2-66101-0

1-66360-2

1-66100-9

66394-1

66331-4

66563-4

66601-8

1-66598-0

66108-4

66360-8

66565-7

1-66358-0

1-66563-1

1-66101-8

1-66360-3

66104-8

66358-4

1-66601-0

1-66360-1

1-66109-6

66360-1

1-66109-7

1-66399-0

66105-3

(Alias Part Numbers:

**Product Affected**

"8M1762-000")

3-66104-2

1-66598-2

66563-8

66100-9

(Alias Part Numbers:

"D84265-000"

"AMPS-0-0066100-9")

66108-1

66108-8

(Alias Part Numbers:

"401188883")

1-66358-7

66399-9

66104-9

(Alias Part Numbers:

"402840912"

"0-0066104-9"

"C79825-000"

"AMP-0-0066104-9"

"2011813")

66109-4

1-66358-9

1-66601-2

66100-8

66360-4

66565-3

1-66101-9

(Alias Part Numbers:

"C35858-000"

"AMPS-1-0066101-9")

66360-3

1-66358-8

66104-4

1-66108-5

66100-3

66105-1

1-66105-5

66424-3

1-66424-1

## **Product Affected**

66100-4

66399-4

66428-4

66100-6

66601-1

66565-2

66399-1

66360-2

66109-2

66105-2

66101-2

(Alias Part Numbers:

"244580-000"

"LTRW-AMP-66101-2")

66598-7

66598-1

(Alias Part Numbers:

"1139882")

66563-6

66424-6

1-66358-2

66358-6

66358-2

66331-5

(Alias Part Numbers:

"405756909")

66331-1

66108-6

(Alias Part Numbers:

"6055300")

2-66104-5

66104-7

(Alias Part Numbers:

"AMPS-0-0066104-7"

"E43178-000")

66104-2

66100-7

(Alias Part Numbers:

"0-0066100-7")

66100-2

**Product Affected**

66601-7

66399-6

1-66360-0

1-66109-5

1-66105-6

1-66101-6

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.