



19-Sep-2012  
PCN #:E-12-016129

**Subject:**MTA-156 header

**Description of Change:** Changing pin length back to 0.650" and changing the housing height back to 0.425".

**Reason:** Customer Request. Several customers have rejected the change in design due to issues with their specific application. TE has decided not to support 2 different P/Ns and is therefore reverting to the previous design.

**Impact of Change:**form - fit - function

**Key Dates:**

**Contact By Date:**17-Sep-2012

**Implementation Date:**17-Sep-2012

**Product Affected**

1-640388-8  
644752-4  
640389-9  
2-640445-1  
1-640445-1  
1-640387-6  
1-640445-4  
2-640389-0  
644753-5  
1-640387-2  
1-640445-8  
1-644752-1  
1-640445-0

(Alias Part Numbers:

**Product Affected**

"2-42932-9327")

640388-4

644753-9

1-640388-2

640388-7

1-644752-2

(Alias Part Numbers:

"2-42932-9326")

640387-5

1-644752-0

640387-9

640445-2

(Alias Part Numbers:

"651-1088-01"

"2-42934-1423")

640445-3

(Alias Part Numbers:

"651-1102-01")

1-644752-7

1-640445-5

2-640389-4

2-640445-4

640445-9

(Alias Part Numbers:

"402947741")

1-644752-6

640387-6

640389-4

(Alias Part Numbers:

"403405863"

"868728-000"

"AMPS-0-0640389-4")

1-640387-7

640389-6

1-640388-4

1-640388-5

640389-8

1-640445-2

644752-3

1-644753-2

## **Product Affected**

640388-8

640389-3

(Alias Part Numbers:

"2-42935-3121")

1-640389-5

1-640389-8

640388-2

644753-2

2-640388-4

1744017-2

2-640388-0

640389-5

(Alias Part Numbers:

"2-42935-3123")

640388-5

1-640388-0

1-640389-3

640445-4

(Alias Part Numbers:

"651-1086-01"

"LDC01142"

"28-91107-04")

1-640389-2

1-644752-8

1-640445-9

1-640445-7

644753-3

1-640387-4

2-644752-0

2-640445-0

1-640389-4

1-640387-5

640388-3

1-640388-7

644752-9

1-644752-5

644752-7

640387-8

3-640445-8

1-644753-5

## **Product Affected**

644753-6

1-640388-6

640389-2

(Alias Part Numbers:

"1060936")

1-640388-3

640387-4

1-640387-3

1-644753-0

2-640445-2

1-640389-7

1-640389-1

640445-6

(Alias Part Numbers:

"651-1075-01"

"1136837")

1-640389-6

1-640389-0

1-640387-0

1-640388-1

640445-5

(Alias Part Numbers:

"651-1050-01"

"2-42934-1424")

640445-8

(Alias Part Numbers:

"2-42934-1425"

"CU3106-000"

"PER-640445-8")

640388-6

1-640445-6

644752-8

644752-6

1-640445-3

(Alias Part Numbers:

"2-42934-1422")

1-640387-1

1-644752-3

640387-7

644752-5

**Product Affected**

640388-9

644752-2

644753-4

644753-8

1-644753-6

644753-7

(Alias Part Numbers:

"1300907")

640387-3

640389-7

2-640445-3

640445-7

640387-2

1-644752-4

1-640387-8

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

Tyco Electronic's corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the Tyco Electronics Product Information Center at 800-522-6752 or your Tyco Electronics Sales Representative.