



20-Nov-2012

PCN #:P-12-008571

Subject:Amplimite, HD-20, Plug Assembly, Right-Angle, PCB Mount

Description of Change: On solder-tail exit side of connector housing (opposite side of connector from mating face), add full length alignment rib between circuits for solder-tails on upper row of contacts. Current parts only have partial alignment ribs located on the upper end and low end of the solder-tails.

Reason: Product improvement. The full length ribs between circuits will provide additional alignment support for the solder-tails when bent during the assembly process. This will prevent stubbing of the solder-tails on the lower alignment ribs during the bending operation.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:02-Jan-2013

Implementation Date:02-Jan-2013

Product Affected

7-747840-0

5745990-6

5747250-2

5747840-4

5747236-6

5747835-6

5747250-3

5747832-4

5788792-1

5747840-6

5747842-5

Product Affected

5747840-3

5788794-2

5788795-1

5747840-5

5747842-6

5747843-3

5747833-6

5747842-3

5747841-4

5747840-2

5747832-6

5745990-4

5747250-4

6-747840-9

5747236-4

5747827-6

5788794-1

5747841-3

5747843-2

5747834-6

6-747843-7

5747238-3

5747238-6

6-747841-8

6-747841-7

5747833-4

5745994-4

7-747840-1

6-747832-7

5747829-4

747840-6

(Alias Part Numbers:

"1033351")

5747841-6

5747843-6

5747835-4

6-747842-8

5747843-4

(Alias Part Numbers:

"CC2972-000"

Product Affected

"AMP-0-5747843-4")

5788793-2

5747834-4

5747827-4

5747842-4

5747841-2

5747250-6

5747238-4

5745990-3

5747252-4

5747842-2

5747238-2

5788793-1

5747236-2

5788792-2

788793-1

788792-1

747834-6

(Alias Part Numbers:

"2-42937-7005")

747832-6

(Alias Part Numbers:

"2-42937-6981")

747843-6

(Alias Part Numbers:

"1324819")

747843-4

747842-6

747842-4

747841-6

(Alias Part Numbers:

"27-01518-00")

747841-4

(Alias Part Numbers:

"27-01518-01")

747840-5

747840-4

(Alias Part Numbers:

"405928391")

747840-3

Product Affected

747252-4

747250-6

747250-4

(Alias Part Numbers:

"A61411-000"

"AMP-0-0747250-4")

747238-6

747238-4

determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.