



30-Jan-2013

PCN #:P-13-008824

Subject:MTA-100 Connectors

Description of Change: Change housing from solid color to white with color stripe.

Reason: Product improvement. Through our continuous improvement process, we plan on providing better customer service via reduce lead-times. Implementing this housing striping color change will significantly reduce the work in process and deliver an end product that helps meet our customers requested dates. (Remark: This PCN is just supplementary declaration of PCNs E-12-005579, this PCN only redefine new date: Estimated First Ship Date and Estimated Last Date for Mixed Shipments).

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-Mar-2013

Implementation Date:01-Mar-2013

Product Affected

4-647000-4

4-643815-6

3-643816-7

3-640468-4

4-640442-4

3-643816-5

4-643816-0

3-640440-6

(Alias Part Numbers:

"1419493")

3-640440-4

Product Affected

3-640440-2
3-640440-8
3-641534-3
4-640442-6
4-644511-2
4-643816-1
3-640442-3
3-644511-5
3-640443-8
4-640442-1
4-640443-1
4-644511-6
3-640443-5
3-647002-2
3-647002-5
4-640443-6
4-643815-2
4-643813-2
4-643813-6
4-640440-9
3-647000-7
3-640442-7
5-643815-0
3-640442-4
4-643816-6
3-640443-4
4-640443-0
3-640470-4
3-640442-9
4-640442-2
4-644511-4
3-647002-6
3-643813-9
4-643813-5
3-647002-7
3-643816-4
3-647002-4
5-643813-3
3-643816-9
3-640440-5

Product Affected

4-640442-3
4-643813-8
4-643816-2
3-643815-5
4-644511-5
4-640440-2
4-640440-5
3-640440-7
3-640442-5
4-640440-8
3-643815-2
3-640442-2
4-640442-7
3-641536-2
4-640443-4
3-647000-3
3-640442-6
4-643815-4
3-643816-3
3-640468-3
3-640443-9
4-643813-3
4-640443-8
4-643816-5
4-640440-1
3-647002-3
4-640443-3
3-643813-4
4-643813-0
3-640443-2
3-647000-2
3-640443-3
3-643815-4
4-640442-0
4-640440-7
5-644511-2
4-647000-0
4-640440-6
4-644511-3
3-647000-4

Product Affected

3-641536-3
3-643815-6
4-647002-0
3-647002-8
5-643813-2
4-643813-4
3-640468-2
5-640440-4
3-643816-2
4-647000-2
3-641537-2
4-643813-1
3-643815-3
4-640440-3
4-640442-5
3-643815-9
4-644511-7
3-647000-8
3-643815-7
3-647000-6
4-640440-4
5-643813-4
5-640440-0
3-647000-5
4-644511-8
3-643813-2
3-643813-5
3-640442-8
4-643815-5
4-640443-2
3-643815-8
3-643813-6
4-640440-0
4-647002-2
4-640443-5
3-643816-6
3-640440-3
3-641534-2
4-643816-3
3-643813-8

Product Affected

3-647000-9

4-643816-4

3-640443-6

3-640440-9

3-643816-8

3-640443-7

4-643815-1

3-643813-3

(Alias Part Numbers:

"1422592")

3-641537-3

5-643816-5

4-643815-0

5-640440-3

3-643813-7

3-641534-8

5-643813-0

647000-9

647000-6

647000-5

647000-4

647000-3

647000-2

644511-3

644511-2

643816-7

643816-6

643816-5

643816-4

643816-3

643816-2

643815-9

643815-8

643815-7

643815-5

643815-4

643815-3

643815-2

643813-9

643813-8

Product Affected

643813-7

643813-6

643813-5

(Alias Part Numbers:
"5021908")

643813-4

643813-3

(Alias Part Numbers:
"1166369")

643813-2

641537-2

641536-2

641534-8

641534-2

640471-2

640470-4

640470-2

640468-3

640443-9

640443-8

640443-7

640443-6

640443-5

640443-4

640443-3

640443-2

640442-9

640442-8

640442-7

640442-6

640442-5

(Alias Part Numbers:
"0-0640442-5")

640442-4

(Alias Part Numbers:
"0-0640442-4")

640442-3

(Alias Part Numbers:
"403444862")

640442-2

Product Affected

640440-9

640440-8

640440-7

640440-6

(Alias Part Numbers:

"405040510"

"2-42933-9052")

640440-5

640440-4

640440-3

(Alias Part Numbers:

"403712094")

640440-2

(Alias Part Numbers:

"403712102"

"2-42933-9053")

2-643813-0

2-640440-6

2-640440-4

2-640440-0

1-647000-4

1-647000-2

1-643816-5

1-643816-0

1-643815-4

1-643815-1

1-643813-8

1-643813-7

1-643813-6

1-643813-5

1-643813-4

1-643813-3

1-643813-2

1-643813-1

1-643813-0

1-640443-8

1-640443-6

1-640443-4

1-640443-0

1-640442-6

Product Affected

1-640442-5

1-640442-4

1-640442-3

1-640442-2

1-640442-0

1-640440-8

1-640440-7

1-640440-6

1-640440-5

1-640440-4

1-640440-3

1-640440-2

(Alias Part Numbers:

"2-42933-9058")

1-640440-1

1-640440-0

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.