



21-May-2013

PCN #:E-13-005785

Subject:Universal MATE-N-LOK Gold-Plated Contacts

Description of Change: No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

Reason: Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

Impact of Change:form - fit - function

Key Dates:

Contact By Date:25-May-2013

Implementation Date:25-May-2013

Product Affected

350218-3

(Alias Part Numbers:
"403431893")

350537-6

350218-1

350218-6

(Alias Part Numbers:
"900476441")

350570-3

(Alias Part Numbers:
"403761786")

Product Affected

350570-7

350536-2

350699-3

350925-2

350922-6

(Alias Part Numbers:

"403927767")

350699-7

350923-6

350851-2

350570-6

350654-7

350536-7

350561-1

(Alias Part Numbers:

"0-0350561-1"

"CU3085-000"

"AMPS-0-0350561-1")

350851-1

(Alias Part Numbers:

"0-0350851-1"

"2021755"

"CU3086-000"

"AMPS-0-0350851-1")

350561-8

350561-2

350570-1

350537-3

350654-1

350561-3

(Alias Part Numbers:

"405331331")

350536-6

(Alias Part Numbers:

"402245922")

350561-5

350537-7

350218-9

350923-4

350923-3

Product Affected

(Alias Part Numbers:

"403980899")

350561-7

350687-4

350851-7

(Alias Part Numbers:

"2021748")

350687-7

350699-8

1-350218-0

350700-3

350218-7

350570-2

(Alias Part Numbers:

"AMPS-0-0350570-2"

"F35891-000")

350924-6

350536-1

(Alias Part Numbers:

"403429822")

350925-1

350922-3

1-350218-1

350537-2

350687-8

350687-2

350687-1

350700-1

350537-1

(Alias Part Numbers:

"AMPS-0-0350537-1"

"D60465-000")

350924-1

(Alias Part Numbers:

"CA7011-000"

"AMPS-0-0350924-1")

350925-6

350699-1

350699-5

350700-8

Product Affected

350922-1

350218-2

350699-2

350700-7

350536-3

(Alias Part Numbers:

"403311541")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary

from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.