



19-Jun-2013

PCN #:E-13-008537

Subject:MTA-100 and MTA-156 HDR and Connector

Description of Change: Plating change from bright tin-lead to matte tin

Reason: Product improvement.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Oct-2013

Implementation Date:31-Oct-2013

Product Affected

3-644812-3

3-644807-9

3-644807-2

3-644812-9

3-644807-3

1-647016-2

647016-4

643787-3

2-641216-2

1-641216-5

1-641216-4

1-641216-0

641216-8

641216-7

641216-6

641216-5

641216-4

Product Affected

641216-3

641216-2

2-641215-4

2-641215-0

1-641215-8

1-641215-6

(Alias Part Numbers:

"407225713")

1-641215-4

1-641215-2

1-641215-1

1-641215-0

641215-9

641215-8

641215-7

641215-6

(Alias Part Numbers:

"651-1079-01")

641215-5

641215-4

641215-3

(Alias Part Numbers:

"406005140"

"651-1078-01")

641215-2

(Alias Part Numbers:

"405384330")

1-641213-0

641213-8

641213-7

641213-5

641213-4

641213-3

641213-2

641212-5

641211-4

641211-3

641211-2

641127-5

641127-4

Product Affected

641127-3

641127-2

1-641126-4

(Alias Part Numbers:
"403662901")

1-641126-2

1-641126-1

(Alias Part Numbers:
"403590136")

1-641126-0

641126-9

641126-8

641126-7

641126-6

(Alias Part Numbers:
"403850423")

641126-5

641126-4

641126-3

(Alias Part Numbers:
"1166372")

641126-2

(Alias Part Numbers:
"651-1247-01")

2-641125-4

1-644043-4

1-644043-3

644043-8

1-644042-0

644042-9

644042-8

644042-5

644042-4

644042-3

644042-2

1-644040-1

644038-6

1-644020-2

1-644020-0

644020-7

Product Affected

644020-6

644020-5

644020-4

644020-3

(Alias Part Numbers:

"655-1018-01")

641241-8

641239-7

641239-5

641239-4

641239-3

641239-2

1-641238-1

1-641238-0

641238-9

641238-8

641238-7

641238-6

641238-5

641238-4

641238-3

641238-2

1-641237-2

1-641237-1

1-641237-0

641237-9

641237-8

641237-7

641237-6

641237-5

641237-4

641237-3

641237-2

641199-5

1-641193-2

1-641193-0

641193-2

641192-5

641192-3

641192-2

Product Affected

1-641191-0

641191-8

641191-4

641191-3

641191-2

1-641190-8

1-641190-4

1-641190-2

1-641190-0

641190-9

641190-8

641190-7

641190-6

641190-5

641190-4

641190-3

(Alias Part Numbers:

"403894546")

647479-3

1-644663-0

644663-8

644663-4

644662-9

644662-4

644662-2

1-644460-8

1-644460-2

1-644460-0

644460-9

644460-8

644460-6

644460-4

644460-2

644284-6

641219-3

641219-2

641218-3

1-641217-4

1-641217-2

641217-8

Product Affected

641217-7

641217-6

641217-2

641150-5

641150-4

641150-3

641150-2

(Alias Part Numbers:

"403631286")

1-641148-2

641148-8

641148-4

(Alias Part Numbers:

"403631237")

641148-3

641148-2

644489-5

644489-2

1-644487-0

644487-8

644487-6

644487-5

647481-6

647481-3

647476-4

647476-3

644812-2

644807-6

644807-3

643995-6

643995-3

643995-2

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.