



22-Aug-2013

PCN #:P-13-009417

Subject:040 & 070 Series Receptacle Contacts, Multilock

Description of Change: TE Connectivity, Global Automotive Division, will be adding an additional existing material vendor to meet our raw material supply demands in an effort to raise our customer service and improve delivery of quality product to the customer-requested dates. These facilities are TS16949 and ISO 9000/1 certified. A PPAP will be requested on your behalf for customers who have purchased affected part nos. in the past 24 months. PPAP will include: PSW, Material certification, affected dimensional data from customer drawing. information.

Reason: Product improvement. These efforts will position us to serve your future needs. Dual sourcing will ensure uninterrupted material supply while minimizing the impact of raw material cost escalations. Please contact your TE Connectivity Sales Engineering representative with any questions regarding this correspondence.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:23-Jan-2014

Implementation Date:23-Jan-2014

Product Affected

776181-1

776129-2

175265-1

173681-1

175180-1

1456598-1

776129-6

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.