



23-Jan-2014

PCN #:P-14-009864

Subject:TE's program "smart design on Silver use" for MSR Relay

Description of Change: In addition to the currently used contacts, TE is planning to use plated contacts for the MSR series with AgCdO, AgCdO gold plated and AgNi_{0,15} contact material. Numerous tests have been completed and TE confirms the same performance for the plated contacts. Start for implementation into the series production is planned for CW9/2014.

Reason: Product improvement.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:01-Mar-2014

Implementation Date:01-Mar-2014

Product Affected

4-1393222-8

(Alias Part Numbers:

"T75S1D112-24"

"V23061A1007X 7")

4-1393223-9

(Alias Part Numbers:

"V23061B1014A501")

1-1416200-1

(Alias Part Numbers:

"V23061D1002A402")

1393223-3

(Alias Part Numbers:

"T75S5D112-12"

Product Affected

"V23061B1005X 6")

5-1393222-1

(Alias Part Numbers:

"V23061A1007X 84")

5-1393222-9

(Alias Part Numbers:

"V23061A1009X 9")

7-1393222-4

(Alias Part Numbers:

"V23061B1002A501")

1416200-8

(Alias Part Numbers:

"V23061A1005X099")

2-1393223-1

(Alias Part Numbers:

"V23061B1007A401")

3-1393222-6

(Alias Part Numbers:

"V23061A1006A502")

3-1393223-4

(Alias Part Numbers:

"V23061B1007X 96")

5-1393222-8

(Alias Part Numbers:

"V23061A1009A602")

6-1393222-4

(Alias Part Numbers:

"V23061A1010X 10")

1393223-1

(Alias Part Numbers:

"V23061B1005A601 *X060")

3-1393223-5

(Alias Part Numbers:

"V23061B1008A401")

2-1393222-9

(Alias Part Numbers:

"T75S1D112-12"

"V23061A1005X 5")

4-1393223-5

(Alias Part Numbers:

Product Affected

"V23061B1010X 11")

1-1393223-2

(Alias Part Numbers:

"V23061B1006A401")

2-1393223-6

(Alias Part Numbers:

"V23061B1007A601")

7-1393222-5

(Alias Part Numbers:

"V23061B1002A601")

5-1393223-0

(Alias Part Numbers:

"V23061B2007A401")

4-1393223-8

(Alias Part Numbers:

"V23061B1013A401")

3-1393222-1

(Alias Part Numbers:

"V23061A1005X 63")

1-1416200-7

(Alias Part Numbers:

"V23061C2005A402")

4-1416200-5

(Alias Part Numbers:

"V23061B1003A401*X60")

1-1393222-7

(Alias Part Numbers:

"V23061A1004A502")

2-1393223-4

(Alias Part Numbers:

"V23061B1007A401 *X097")

2-1416200-1

(Alias Part Numbers:

"V23061A2005A402")

7-1393222-9

(Alias Part Numbers:

"V23061B1003A401")

5-1393222-6

(Alias Part Numbers:

"V23061A1009A402")

Product Affected

7-1393222-0

(Alias Part Numbers:
"V23061B1001X 2")

3-1393223-8

(Alias Part Numbers:
"V23061B1009A401")

1-1393222-6

(Alias Part Numbers:
"V23061A1004A402")

9-1393222-7

(Alias Part Numbers:
"V23061B1005A501")

8-1393222-1

(Alias Part Numbers:
"V23061B1003A501")

2-1393222-5

(Alias Part Numbers:
"V23061A1005A402 *Z180")

1-1393222-8

(Alias Part Numbers:
"V23061A1004A602")

4-1393222-7

(Alias Part Numbers:
"V23061A1007A602")

1-1393223-4

(Alias Part Numbers:
"V23061B1006A501")

8-1393222-7

(Alias Part Numbers:
"V23061B1004A401 *X060")

6-1419136-9

(Alias Part Numbers:
"T 75S 5D 1212"
"T75S5D1212")

8-1393222-2

(Alias Part Numbers:
"V23061B1003A601")

1393223-7

(Alias Part Numbers:
"V23061B1005X 85")

Product Affected

4-1393223-0

(Alias Part Numbers:
"V23061B1009A601")

1423089-1

(Alias Part Numbers:
"T75S5D112-60")

2-1393222-4

(Alias Part Numbers:
"V23061A1005A402 *X060")

3-1393223-9

(Alias Part Numbers:
"V23061B1009A501")

4-1393223-7

(Alias Part Numbers:
"V23061B1011A401")

2-1393223-2

(Alias Part Numbers:
"V23061B1007A401 *X060")

3-1393223-6

(Alias Part Numbers:
"V23061B1008A501")

6-1393222-9

(Alias Part Numbers:
"V23061B1001A401")

1393223-4

(Alias Part Numbers:
"V23061B1005X 51")

7-1393222-8

(Alias Part Numbers:
"V23061B1002X 80")

2-1393222-3

(Alias Part Numbers:
"V23061A1005A402"
"CA1475-000"
"AMPS-2-1393222-3")

8-1393222-3

(Alias Part Numbers:
"V23061B1003X 4")

5-1393222-5

(Alias Part Numbers:

Product Affected

"V23061A1008A402")

6-1393223-1

(Alias Part Numbers:

"V23061B1006X010")

4-1393222-2

(Alias Part Numbers:

"V23061A1007A402")

2-1393223-7

(Alias Part Numbers:

"V23061B1007A601 *X060")

4-1393222-5

(Alias Part Numbers:

"V23061A1007A402 *Z180")

8-1393222-8

(Alias Part Numbers:

"V23061B1004A501")

5-1393222-0

(Alias Part Numbers:

"V23061A1007X 83")

2-1393222-6

(Alias Part Numbers:

"V23061A1005A402 *Z187")

3-1393222-5

(Alias Part Numbers:

"V23061A1006A402")

6-1393222-5

(Alias Part Numbers:

"V23061A1013A402")

5-1416200-2

1393222-7

(Alias Part Numbers:

"T75S1D112-05"

"V23061A1002X 2")

9-1393222-8

(Alias Part Numbers:

"V23061B1005A501 *X060")

5-1393223-2

(Alias Part Numbers:

"T75S1D112-06")

7-1393222-6

Product Affected

(Alias Part Numbers:

"T75S5D112-05"

"V23061B1002X 3")

4-1393223-1

(Alias Part Numbers:

"T75S5D112-48"

"V23061B1009X 10"

"V23061B1009X010")

3-1393222-0

(Alias Part Numbers:

"V23061A1005X 51")

3-1393222-7

(Alias Part Numbers:

"V23061A1006A602")

6-1393222-1

(Alias Part Numbers:

"V23061A1010A402")

2-1393223-5

(Alias Part Numbers:

"V23061B1007A501")

9-1393222-4

(Alias Part Numbers:

"V23061B1005A401")

8-1419146-6

(Alias Part Numbers:

"T75S5D1125")

7-1393222-3

(Alias Part Numbers:

"V23061B1002A401")

6-1393222-8

(Alias Part Numbers:

"V23061A2002A402")

2-1393222-7

(Alias Part Numbers:

"V23061A1005A502")

8-1393222-9

(Alias Part Numbers:

"V23061B1004A601")

1-1393223-3

(Alias Part Numbers:

Product Affected

"V23061B1006A401 *X060")

1393223-6

(Alias Part Numbers:

"V23061B1005X 81")

9-1393222-5

(Alias Part Numbers:

"V23061B1005A401 *X060")

8-1393222-0

(Alias Part Numbers:

"V23061B1003A401 *X060")

1-1393223-5

(Alias Part Numbers:

"V23061B1006A601")

1-1393222-9

(Alias Part Numbers:

"V23061A1004X 4")

1-1393222-3

(Alias Part Numbers:

"V23061A1003A502")

1-1393223-6

(Alias Part Numbers:

"T75S5D112-18"

"V23061B1006X 7")

1-1393223-0

(Alias Part Numbers:

"V23061B1005X 95")

8-1393222-6

(Alias Part Numbers:

"V23061B1004A401")

4-1393222-6

(Alias Part Numbers:

"V23061A1007A502")

7-1419136-0

(Alias Part Numbers:

"T 75S 5D112 5"

"T75S5D1125")

1-1393222-2

(Alias Part Numbers:

"V23061A1003A402")

2-1393223-8

Product Affected

(Alias Part Numbers:

"T75S5D112-24"

"V23061B1007X 8")

5-1393222-7

(Alias Part Numbers:

"V23061A1009A502")

4-1393222-3

(Alias Part Numbers:

"V23061A1007A402 *X060")

3-1416200-7

(Alias Part Numbers:

"V23061C2007A402")

1393222-5

(Alias Part Numbers:

"V23061A1002A402")

4-1393223-2

(Alias Part Numbers:

"V23061B1010A401")

2-1393222-8

(Alias Part Numbers:

"V23061A1005A602")

3-1416200-1

(Alias Part Numbers:

"V23061B2005A401")

4-1393223-4

(Alias Part Numbers:

"V23061B1010A601")

6-1393222-2

(Alias Part Numbers:

"V23061A1010A502")

1393223-9

(Alias Part Numbers:

"V23061B1005X 92")

3-1393222-8

(Alias Part Numbers:

"V23061A1006X 6")

3-1393223-1

(Alias Part Numbers:

"V23061B1007X 82")

1393222-6

Product Affected

(Alias Part Numbers:
"V23061A1002A502")
1393223-8

(Alias Part Numbers:
"V23061B1005X 91")
9-1393222-6

(Alias Part Numbers:
"V23061B1005A401 *Z180")
3-1393223-2

(Alias Part Numbers:
"V23061B1007X 86")
9-1393222-9

(Alias Part Numbers:
"V23061B1005A601")
3-1393223-3

(Alias Part Numbers:
"V23061B1007X 93")
9-1393222-0

(Alias Part Numbers:
"T75S5D112-09"
"V23061B1004X 5")
5-1393222-3

(Alias Part Numbers:
"V23061A1007X 94")
8-1419146-7

(Alias Part Numbers:
"T75S5D1212")
6-1393222-3

(Alias Part Numbers:
"V23061A1010A602")
2-1393223-3

(Alias Part Numbers:
"V23061B1007A401 *X068")
4-1393222-4

(Alias Part Numbers:
"V23061A1007A402 *X068")
4-1393223-3

(Alias Part Numbers:
"V23061B1010A501")
7-1419136-2

Product Affected

(Alias Part Numbers:

"T75S5D112-48")

6-1393223-0

(Alias Part Numbers:

"V23061/T75")

5-1393223-9

(Alias Part Numbers:

"V23061/T75")

5-1393223-8

(Alias Part Numbers:

"V23061/T75")

5-1393223-7

(Alias Part Numbers:

"T 75S 5D11212"

"T75S5-D11212")

5-1393223-6

(Alias Part Numbers:

"V23061/T75")

5-1393223-5

(Alias Part Numbers:

"V23061/T75")

5-1393223-4

(Alias Part Numbers:

"V23061/T75")

5-1393223-3

(Alias Part Numbers:

"V23061/T75")

5-1393223-1

(Alias Part Numbers:

"V23061/T75")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.