



20-May-2014

PCN #:P-14-010171

Subject:TE's program "smart design on Silver use" for MSR Relay

Description of Change: In addition to the currently used massiv contacts, TE is planning to use plated contacts for the MSR series with AgSnO, AgSnO gold plated contact material. Numerous tests have been completed and TE confirms the same performance for the plated contacts. Start for implementation into the series production is planned for CW45/2014.

Reason: Product improvement.

Impact of Change:form - fit - function

Key Dates:

Contact By Date:03-Nov-2014

Implementation Date:03-Nov-2014

Product Affected

1-1393222-5

(Alias Part Numbers:
"V23061A1004A302")

1-1416200-6

(Alias Part Numbers:
"V23061C2005X109")

1393222-3

(Alias Part Numbers:
"V23061A1002A202")

1-1416200-0

(Alias Part Numbers:
"V23061A1009A302")

4-1393222-0

Product Affected

(Alias Part Numbers:

"V23061A1007A302 *X022")

3-1416200-8

(Alias Part Numbers:

"V23061B1003A301")

1393222-1

(Alias Part Numbers:

"V23061A1001A202")

5-1393222-2

(Alias Part Numbers:

"V23061A1007X 89")

4-1416200-1

(Alias Part Numbers:

"V23061A1005X112")

3-1393222-9

(Alias Part Numbers:

"V23061A1007A302")

1-1393223-9

(Alias Part Numbers:

"V23061B1007A301 *X022")

1393222-9

(Alias Part Numbers:

"V23061A1003A302")

2-1393222-2

(Alias Part Numbers:

"V23061A1005A302 *X089")

7-1416200-1

1393222-4

(Alias Part Numbers:

"V23061A1002A302")

1-1393222-1

(Alias Part Numbers:

"V23061A1003A302 *X089")

1-1416200-4

(Alias Part Numbers:

"V23061A1006X108")

4-1416200-3

(Alias Part Numbers:

"V23061A1004X114")

2-1416000-0

Product Affected

(Alias Part Numbers:
"V23061A1016A302")

6-1393222-7

(Alias Part Numbers:
"V23061A1015A302")

4-1416200-6

(Alias Part Numbers:
"V23061D1007A301")

3-1393222-4

(Alias Part Numbers:
"V23061A1006A302")

4-1416200-8

(Alias Part Numbers:
"V23061B1004A301")

4-1416200-4

(Alias Part Numbers:
"V23061A1006X115")

7-1416200-4

9-1393222-2

(Alias Part Numbers:
"V23061B1005A301 *X022")

1-1393222-0

(Alias Part Numbers:
"V23061A1003A302 *X022")

7-1393222-2

(Alias Part Numbers:
"V23061B1002A301")

7-1416200-3

7-1416200-7

1-1393223-7

(Alias Part Numbers:
"V23061B1007A301")

4-1416200-9

(Alias Part Numbers:
"V23061D2005A301")

1416200-9

(Alias Part Numbers:
"V23061B1010A301")

5-1416200-1

(Alias Part Numbers:

Product Affected

"V23061A1005A202")

1-1416200-5

(Alias Part Numbers:

"V23061C2005A302")

3-1393223-7

(Alias Part Numbers:

"V23061B1009A301")

7-1416200-5

1-1393223-1

(Alias Part Numbers:

"V23061B1006A301")

2-1393223-0

(Alias Part Numbers:

"V23061B1007A301 *X089")

9-1393222-3

(Alias Part Numbers:

"V23061B1005A301 *X089")

7-1393222-1

(Alias Part Numbers:

"V23061B1002A201")

4-1416200-2

(Alias Part Numbers:

"V23061A1007X113")

5-1393222-4

(Alias Part Numbers:

"V23061A1008A302")

1-1393223-8

(Alias Part Numbers:

"V23061B1007A301 *X017")

7-1416200-6

4-1393222-1

(Alias Part Numbers:

"V23061A1007A302 *X089")

6-1393222-6

(Alias Part Numbers:

"V23061A1014A302")

4-1416200-0

(Alias Part Numbers:

"V23061A1007X111")

1393222-2

Product Affected

(Alias Part Numbers:
"V23061A1001A302")
3-1393222-3

(Alias Part Numbers:
"V23061A1005X 88")
7-1416200-2

1-1416200-2

(Alias Part Numbers:
"V23061B1002X107")
3-1416200-9

(Alias Part Numbers:
"V23061A1004X110")
4-1419137-6

(Alias Part Numbers:
"V23061A1007A301")
1956240-3

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.