



23-Jun-2014

PCN #:E-14-009319

Subject:Appliances electrical connector

Description of Change: Bring Part revision in-line with drawing revision

Reason: Document Clarification. Part and Drawing revision mismatch

Impact of Change:form - fit - function

Key Dates:

Contact By Date:31-Jul-2014

Implementation Date:31-Jul-2014

Product Affected

1-725996-2

1-160655-1

770642-1

154719-2

42400-1

152301-2

60487-1

42563-9

160928-4

928962-7

160625-2

63609-2

280080-4

154717-4

170002-5

341001-6

150500-2

Product Affected

170002-7

160655-4

154717-1

150530

160887-4

280755-4

1217061-1

154719-5

63757-2

42241-1

62050-2

160786-2

521583-2

160691-5

926539-5

160759-1

(Alias Part Numbers:

"F66259-000"

"AMPS-0-0160759-1")

5-160558-9

160173-7

5-160446-2

160666-4

170030-4

280756-4

160859-6

60573-2

154718-7

5-160667-2

42452-1

(Alias Part Numbers:

"0-0042452-1")

61687-2

6-160526-2

6-160526-1

42802-1

160645-1

346697-3

180398-1

160450-3

Product Affected

42594-1

1217062-1

280543-5

61400-1

964046-2

6-160449-5

170324-5

280311

150545-2

925387-2

170030-1

(Alias Part Numbers:

"0-0170030-1")

1-160305-9

160913-4

2-160759-9

160450-1

6-160448-2

520987-1

142681-1

175179-1

41531-1

60932-2

280080-2

160655-6

154719-1

(Alias Part Numbers:

"0-0154719-1")

2-520335-2

62057-1

63609-1

926523-1

342368-2

63854-1

160859-5

180906-5

(Alias Part Numbers:

"A51796-000"

"AMPS-0-0180906-5")

42563-8

Product Affected

170048-4

160811-7

926539-6

(Alias Part Numbers:

"0-0926539-6")

160860-4

154719-4

341002-6

5-160558-3

42098-1

170002-4

180906

(Alias Part Numbers:

"AMPS-0-0180906-0"

"F33331-000"

"0-0180906-0")

41480

160917-3

151667-2

63097-2

140791-2

160916-6

42475-2

(Alias Part Numbers:

"0-0042475-2")

160927-4

63196-4

160655-2

(Alias Part Numbers:

"F49671-000"

"AMPS-0-0160655-2")

170324-1

(Alias Part Numbers:

"0-0170324-1")

925387-1

521317-1

5-160526-9

60080-2

42486-3

42563-2

Product Affected

4-154719-0

151321-1

140723-2

63951-4

925552-2

160457-3

175019-5

1-160305-8

341002-1

61945-2

63951-1

170038-4

63933-1

154719

(Alias Part Numbers:

"154719-0")

61492-3

182490-2

160759-2

342452-2

170324-2

1-160759-2

154717-7

926728-1

(Alias Part Numbers:

"C69179-000"

"AMPS-0-0926728-1")

62056-7

175179-2

175019-6

42437-5

63306-2

6-160448-6

925856-1

(Alias Part Numbers:

"CM1530-000"

"AMPS-0-0925856-1")

63306-1

160859-4

41450-1

Product Affected

7-154719-0

1-154719-0

170030-5

342368-1

(Alias Part Numbers:

"CU3083-000"

"AMPS-0-0342368-1")

170328-1

965972-1

41772-1

170002-2

170030-2

60465-3

640249-1

determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.