



TE CONNECTIVITY CORPORATION

PRODUCT CHANGE NOTIFICATION

PCN DATE: 06-FEB-2009

PRODUCT CHANGE NOTIFICATION NO: P-09-001849

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

IMPACT:

PCN

GENERAL PRODUCT DESCRIPTION:

see below

DESCRIPTION OF CHANGE:

Tyco Electronics (TE) is moving the following Products to a new location: Closed-End Splices BOMBTAIL (LP & Taped) Closed-End Splices Nylon (LP & Taped) DIAMOND-GRIP STRATO-THERM HR Terminals & Splices (LP) DIAMOND-GRIP STRATO-THERM HT Terminals & Splices (LP) DIAMOND-GRIP Terminals (LP) FASTON Splices (LP) PIDG FASTON Flags (LP) PIDG FASTON Terminals (LP, Metal Strip, & Taped) PIDG Terminals & Splice (LP & Taped) SOLISTRAND Splice (LP) TERMINYL Terminals & Splice (LP) Please contact your TE Sales Engineer with questions. The specific part numbers & drawings are detailed below.

REASON FOR CHANGE:

After an extensive analysis of our Communications & Industrial Solutions (CIS) business unit operations, we are announcing a plan to simplify our manufacturing footprint. As a result of this plan, product produced at our Rte 230 facility in Mount Joy, PA will be relocated to our Lickdale Facility in Jonestown, PA (United States of America) by the end of September 2009.

ESTIMATE DATE:

RECEIVED DATE : 06-FEB-2009

LAST ORDER DATE:
(OBSOLETE PARTS ONLY)

FIRST DATE TO SHIP CHANGED PARTS: 15-FEB-2009
(CHANGED PARTS ONLY)

LAST SHIP DATE:
(OBSOLETE PARTS ONLY)

LAST DATE FOR MIXED SHIPMENTS: 03-OCT-2009
(CHANGED PARTS ONLY)



TE CONNECTIVITY
CORPORATION

PRODUCT CHANGE
NOTIFICATION

Following list contains all the unique parts and drawings /documents listed on each of the individual PCN Forms affecting this worldwide customer account.

| PART NUMBER | ALIAS PART NUMBER | SUBSTITUTE PART NUMBER | SUBSTITUTE ALIAS PART NUMBER | New Rev Code | Old Rev Code |
|-------------|----------------------------------|------------------------|------------------------------|--------------|--------------|
| 1-321235-0 | | | | | |
| 1-321235-1 | | | | | |
| 1-321897-0 | | | | | |
| 1-322325-0 | | | | | |
| 1-322325-1 | | | | | |
| 1-331456-0 | | | | | |
| 1-35115-0 | | | | | |
| 156666-1 | "749020-000", "AMPS-0-0156666-1" | | | | |
| 2-328375-3 | | | | | |
| 2-329251-1 | | | | | |
| 30996 | | | | | |
| 31771 | | | | | |
| 321519 | "CP7361-000", "AMPS-0-321519-0" | | | | |
| 321893 | | | | | |
| 321897 | | | | | |
| 321898 | | | | | |
| 322320 | | | | | |
| 322332 | | | | | |
| 322337 | | | | | |
| 322338 | | | | | |
| 322363 | | | | | |



TE CONNECTIVITY CORPORATION

PRODUCT CHANGE NOTIFICATION

Following list contains all the unique parts and drawings /documents listed on each of the individual PCN Forms affecting this worldwide customer account.

| PART NUMBER | ALIAS PART NUMBER | SUBSTITUTE PART NUMBER | SUBSTITUTE ALIAS PART NUMBER | New Rev Code | Old Rev Code |
|-------------|---------------------------------|------------------------|------------------------------|--------------|--------------|
| 322366 | | | | | |
| 322367 | | | | | |
| 322373 | | | | | |
| 322375 | | | | | |
| 323199 | | | | | |
| 323750 | | | | | |
| 323757 | | | | | |
| 324043 | | | | | |
| 324044 | | | | | |
| 324045 | | | | | |
| 324046 | | | | | |
| 324047 | "A42815-000", "AMP-0-0324047-0" | | | | |
| 324048 | "AMP-0-0324048-0", "E42038-000" | | | | |
| 324049 | | | | | |
| 324050 | | | | | |
| 324051 | | | | | |
| 324052 | | | | | |
| 324053 | | | | | |
| 324054 | | | | | |
| 324056 | | | | | |
| 324057 | | | | | |



TE CONNECTIVITY CORPORATION

PRODUCT CHANGE NOTIFICATION

Following list contains all the unique parts and drawings /documents listed on each of the individual PCN Forms affecting this worldwide customer account.

| PART NUMBER | ALIAS PART NUMBER | SUBSTITUTE PART NUMBER | SUBSTITUTE ALIAS PART NUMBER | New Rev Code | Old Rev Code |
|-------------|---|------------------------|------------------------------|--------------|--------------|
| 324058 | | | | | |
| 324082 | | | | | |
| 324083 | | | | | |
| 324084 | | | | | |
| 324111 | | | | | |
| 324112 | | | | | |
| 324484 | | | | | |
| 324485 | | | | | |
| 324486 | | | | | |
| 324625 | | | | | |
| 324658 | | | | | |
| 325154 | | | | | |
| 328307 | | | | | |
| 328655 | | | | | |
| 328730 | "182300-000", "AMPS-0-0328730-0", "1307511" | | | | |
| 328890 | | | | | |
| 329251 | | | | | |
| 331456 | | | | | |
| 35115 | "4-27203-1236" | | | | |
| 35653 | | | | | |
| 36964 | | | | | |



TE CONNECTIVITY
CORPORATION

PRODUCT CHANGE
NOTIFICATION

Following list contains all the unique parts and drawings /documents listed on each of the individual PCN Forms affecting this worldwide customer account.

| PART NUMBER | ALIAS PART NUMBER | SUBSTITUTE PART NUMBER | SUBSTITUTE ALIAS PART NUMBER | New Rev Code | Old Rev Code |
|-------------|--|------------------------|------------------------------|--------------|--------------|
| 36965 | "AMPS-0-0036965-0", "D03003-000" | | | | |
| 42844-1 | "AMP-0-0042844-1", "D70990-000" | | | | |
| 53041 | "1364430" | | | | |
| 53119-1 | "1108139" | | | | |
| 53234-1 | | | | | |
| 55929-1 | | | | | |
| 60894-1 | "010-1113-00" | | | | |
| 61048-1 | | | | | |
| 61060-1 | | | | | |
| 640902-1 | | | | | |
| 640903-1 | "AMP-0-0640903-1", "E23464-000" | | | | |
| 640903-2 | | | | | |
| 640905-1 | "402647564", "AMP-0- 0640905-1", "F94052- 000" | | | | |
| 640905-2 | "402989057" | | | | |
| 640907-1 | "AMPS-0-0640907-1", "D54822-000", "010- 5590-00", "4-16211-4031" | | | | |
| 640907-2 | "402989065", "1140289", "1139488" | | | | |
| 640909-1 | "579266-000", "AMPS-0- 0640909-1" | | | | |
| 640913-1 | "AMPS-0-0640913-1", "E76002-000" | | | | |
| 640917-1 | "AMPS-0-0640917-1", "F55918-000" | | | | |
| 640917-2 | "405769969" | | | | |



TE CONNECTIVITY
CORPORATION

PRODUCT CHANGE
NOTIFICATION

Following list contains all the unique parts and drawings /documents listed on each of the individual PCN Forms affecting this worldwide customer account.

| PART NUMBER | ALIAS PART NUMBER | SUBSTITUTE PART NUMBER | SUBSTITUTE ALIAS PART NUMBER | New Rev Code | Old Rev Code |
|-------------|-------------------------------------|------------------------|------------------------------|--------------|--------------|
| 640919-1 | "AMPS-0-0640919-1", "F11402-000" | | | | |
| 640923-1 | "AMPS-0-0640923-1", "F61867-000" | | | | |
| 640923-2 | "1181513" | | | | |
| 640925-1 | "AMPS-0-0640925-1", "F77142-000" | | | | |
| 640925-2 | | | | | |
| 640929-1 | | | | | |
| 640929-2 | | | | | |
| 640931-1 | "A86505-000", "AMPS-0-0640931-1" | | | | |
| 696357-1 | | | | | |
| 8-32151-1 | "A07969-000", "AMPS-8-0032151-1" | | | | |
| 8-640903-1 | "AMPS-8-0640903-1", "E71594-000" | | | | |