



15-Mar-2018

PCN #:P-18-015607

Subject:Manufacturing Location Change of Menlo Park Appliances Tubing ES1000 Products and UOM change for ES1000 coiled parts

Description of Change: Manufacturing location change. Following Part Numbers will be transferred from Menlo Park USA, to Trutnov, CZ.

Reason: Dear Customer, as part of the production move, we will start to ship ES1000 products after 12th June 2018 from the Trutnov facility. After this date TE reserves the right to provide qualified products from either the Menlo Park or Trutnov manufacturing locations during this transfer until the final closure date of Menlo Park location by the end of 2019. As not all part numbers will transfer at the same time, customers may still receive Products from the Menlo Park location after this transfer date due to inventory we will carry to allow this transfer to happen and to minimize impact to our tubing customers. Where necessary TE will continue with internal qualification and testing of products after they are received at the new locations.

Impact of Change:Manufacturing location change

Key Dates:

Contact By Date:01-Jun-2018

Implementation Date:01-Jun-2018

Product Affected

CW5088-000

CY1947-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-55MM"

"3-1899736-1")

193197P022

(Alias Part Numbers:

Product Affected

"6-1191401-5"

"ES1000-NO.1-C1-X-45MM")

CM5359-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-30MM")

035377P003

(Alias Part Numbers:

"4-1190273-7"

"ES1000-NO.3-B8-X-75MM")

193197P008

(Alias Part Numbers:

"5-1191401-1"

"ES1000-NO.1-C1-X-50MM")

193197P002

(Alias Part Numbers:

"4-1191401-5"

"ES1000-NO.1-C1-X-55MM")

CX7482-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-21MM"

"5-1899719-7")

E84631-000

(Alias Part Numbers:

"7-1200978-7"

"ES1000-NO.4B7X130MMCS7721")

035377P016

(Alias Part Numbers:

"6-1190273-0"

"ES1000-NO.3-B8-X-120MM")

193197P011

(Alias Part Numbers:

"5-1191401-4"

"ES1000-NO.1-C1-X-30MM")

F18778-000

(Alias Part Numbers:

"6-1201322-2"

"ES1000-NO.3-B8-X-80MM")

609564-000

(Alias Part Numbers:

"5-1201145-1"

Product Affected

"ES1000-NO.1-C1-X-150MM")

CR2067-000

C20744-000

(Alias Part Numbers:

"5-1201707-8"

"ES1000-NO.2-B9-X-45MM")

CP4997-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-38MM")

A04375-000

(Alias Part Numbers:

"2-1201147-4"

"ES1000-KIT3-REFILL")

576105P006

(Alias Part Numbers:

"8-1194570-1"

"ES1000-NO.2-A1-X-STK")

576105P009

(Alias Part Numbers:

"8-1194570-4"

"ES1000-NO.2-B9-X-50MM")

555081-000

(Alias Part Numbers:

"2-1197894-9"

"ES1000-NO.1-C1-X-COIL")

085193P005

(Alias Part Numbers:

"9-1190628-7"

"ES1000-NO.4-F3-X-75MM")

193197P021

(Alias Part Numbers:

"6-1191401-4"

"ES1000-NO.1-C1-X-100MM")

CX7481-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-32MM"

"5-1899719-4")

CR7066-000

(Alias Part Numbers:

"ES1000-NO.3-B8-X-30MM"

Product Affected

"7-1899719-9")

035377P006

(Alias Part Numbers:

"5-1190273-0"

"ES1000-NO.3-B8-X-50MM")

085193P006

(Alias Part Numbers:

"9-1190628-8"

"ES1000-NO.4-B7-X-50MM")

576105P002

(Alias Part Numbers:

"7-1194570-7"

"ES1000-NO.2-B9-X-55MM")

193197P003

(Alias Part Numbers:

"4-1191401-6"

"ES1000-NO.1-C1-X-65MM")

085193P004

(Alias Part Numbers:

"9-1190628-6"

"ES1000-NO.4-B7-X-90MM")

CR2066-000

193197P010

(Alias Part Numbers:

"5-1191401-3"

"ES1000-NO.1-C1-X-25MM")

D72328-000

(Alias Part Numbers:

"4-1201146-9"

"ES1000-NO.4-B7-X-150MM")

CM3556-000

(Alias Part Numbers:

"ES1000-NO.4-Z3-X-27MM"

"5-1899413-1")

193197P005

(Alias Part Numbers:

"4-1191401-8"

"ES1000-NO.1-A1-X-STK")

709246-000

(Alias Part Numbers:

Product Affected

"5-1201145-5"

"ES1000-NO.3-B8-X-150MM")

CW3316-000

(Alias Part Numbers:

"2-1899776-3"

"ES1000-NO.3-B8-X-48MM")

EG0206-000

(Alias Part Numbers:

"ES1000-NO.4-F3-X-60MM")

CZ9852-000

(Alias Part Numbers:

"6-1899770-2")

CX7430-000

(Alias Part Numbers:

"ES1000-NO.1-C1-X-19MM"

"5-1899719-5")

C22995-000

(Alias Part Numbers:

"9-1199704-5"

"ES1000-NO.3-B8-X-25MM")

CX7480-000

(Alias Part Numbers:

"ES1000-NO.2-B9-X-19MM"

"5-1899719-6")

CR2069-000

085193P014

(Alias Part Numbers:

"1190629-6"

"ES1000-NO.4-F3-X-50MM")

035377P004

(Alias Part Numbers:

"4-1190273-8"

"ES1000-NO.3-B8-X-STK")

D70463-000

(Alias Part Numbers:

"2-1199839-0"

"ES1000-NO.2B9X125MMCS7721")

A85870-000

(Alias Part Numbers:

"3-1201461-2"

Product Affected

"ES1000-NO.4-F3-X-30MM")

035377P008

(Alias Part Numbers:

"5-1190273-2"

"ES1000-NO.3-A1-X-STK")

364171-000

(Alias Part Numbers:

"5-1192730-5"

"ES1000-NO.2-B9-X-100MM")

CR2068-000

CU4597-000

(Alias Part Numbers:

"ES1000-NO.4-B7-X-70MM"

"9-1899652-2")

193197P023

(Alias Part Numbers:

"6-1191401-6"

"ES1000-NO.1-C1-X-35MM")

CL6607-000

(Alias Part Numbers:

"ES1000-NO.3-B8-X-115MM")

E20530-000

(Alias Part Numbers:

"1200424-6"

"ES1000-NO.2-B9-X-40MM")

E65254-000

(Alias Part Numbers:

"5-1201669-1"

"ES1000-NO.4-B7-X-130MM")

A52804-000

(Alias Part Numbers:

"2-1200965-3"

"ES1000-HW-NO.2-O3-X-35MM")

C63832-000

(Alias Part Numbers:

"1-1201146-9"

"ES1000-NO.2-B9-X-150MM")

193197P007

(Alias Part Numbers:

"5-1191401-0"

Product Affected

"ES1000-NO.1-C1-X-20MM")

576105P003

(Alias Part Numbers:

"7-1194570-8"

"ES1000-NO.2-B9-X-65MM")

576105P004

(Alias Part Numbers:

"7-1194570-9"

"ES1000-NO.2-B9-X-STK")

C34252-000

(Alias Part Numbers:

"1200827-7"

"ES1000-NO.3-B8-X-55MM")

CW3317-000

(Alias Part Numbers:

"2-1899776-2"

"ES1000-NO.2-B9-X-48MM")

020920-000

(Alias Part Numbers:

"4-1199943-0"

"ES1000-NO.4-B7-X-100MM")

576105P005

(Alias Part Numbers:

"8-1194570-0"

"ES1000-NO.2-B9-X-75MM")

193197P024

(Alias Part Numbers:

"6-1191401-7"

"ES1000-NO.1-C1-X-40MM")

576105P008

(Alias Part Numbers:

"8-1194570-3"

"ES1000-NO.2-B9-X-25MM")

CX7479-000

(Alias Part Numbers:

"ES1000-NO.1-C1-X-28MM"

"5-1899719-3")

CM3555-000

(Alias Part Numbers:

"ES1000-NO.4-Z3-X-75MM"

Product Affected

"5-1899413-0")

866121-000

(Alias Part Numbers:

"3-1196744-0"

"ES1000-NO.1-C1-X-80MM")

085193P002

(Alias Part Numbers:

"9-1190628-4"

"ES1000-NO.4-B7-X-75MM")

085193P003

(Alias Part Numbers:

"9-1190628-5"

"ES1000-NO.4-B7-X-STK")

D27408-000

(Alias Part Numbers:

"9-1200979-5"

"ES1000-HW-NO.3-M8-X-45MM")

683027-000

(Alias Part Numbers:

"5-1197886-2"

"ES1000-NO.2-B9-X-COIL")

193197P004

(Alias Part Numbers:

"4-1191401-7"

"ES1000-NO.1-C1-X-STK")

A87489-000

(Alias Part Numbers:

"3-1201461-3"

"ES1000-NO.4-F3-X-40MM")

035377P002

(Alias Part Numbers:

"4-1190273-6"

"ES1000-NO.3-B8-X-65MM")

189022-000

(Alias Part Numbers:

"5-1199705-1"

"ES1000-NO.1-C1-X-60MM")

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.