

## Technical change to HDC ModuPlug metal frame

Dear Madam or Sir,

the below listed articles will be supplied in a modified revision. Please pass this product information on to your employees and, if needed, to your customers. All modifications are performed for reasons of product improvements.

### 1. Initial situation

The labeling of the slots, the order number, and the manufacturer's lettering were previously applied by the die casting tool.

### 2. Technical change

The labeling of the slots, the order number, and the manufacturer's lettering are now applied with a laser.



### 3. Reason for change

The growing number of variants makes this change necessary. In addition, the readability of the individual slots has significantly increased.

### 4. Availability

As of now.

### 5. Affected parts

1429010000 HDC MF 16B AD  
1429030000 HDC MF 16B DA

### 6. Data

PCN-number:	PCN-PB72-20201215-00-A
Date of publishing:	2020, December 15
Duration of validity:	Until further notice
Revision number:	00-A

We are very sorry for all the inconveniences caused and doing everything to adjust this product change as smooth as possible without big influence on delivery times and general functions.

For further questions please contact your sales office directly. All contacts for sales representatives are available here: [www.weidmueller.com/contact](http://www.weidmueller.com/contact)

Best regards

Product Management

Weidmüller Interface GmbH & Co. KG  
Klingenbergstraße 16, 32758 Detmold, Germany

**Weidmüller** – Your partner in Industrial Connectivity  
We look forward to sharing ideas with you – **Let's connect.**